

**K.KIM HIN AUTO PTE LTD**  
**160 Sin Ming Drive**  
**#02-20 Sin Ming AutoCity**  
**Singapore 575722**

**Claim Reference:**  
**Assessment Number: KKHA0071**  
**Version: K.KIMHIN/1**  
**Date Calculated: 24/12/2018 06:51**

**Full Report - V1**  
**Registration: SJU8184X**  
**Printed: 24/12/2018 14:51**

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	Estimated Repair Time:
Policy Number:	Quote Due Date:
Other Reference:	Actual Repair Days:
Third Party:	Parts Ordered Date:
Insured Amount:	Hire Car Start:
Under Warranty:	Hire Car End:
Warranty Expired:	Vehicle Collected:

#### Vehicle Details

##### Vehicle

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS
Model Sheet Number:	YCM 13
Registration:	SJU8184X
Registration Month:	December
Registration Year:	2009
VIN Number:	MR053ZEE106161118
Manufacture Year:	2009
Odometer:	Not Known
Colour:	
Engine Number:	3ZZ4950915
Fuel Level:	%

##### Model Specs

PREPARE OFF VEHICLE	TWO COAT PEARL/MICA
---------------------	---------------------

*Authorised*  
*Resurvey B & paint*  
*EX NIL*  
*3 days*

#### Vehicle Condition



##### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	24/12/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

# K.KIM HIN AUTO PTE LTD

Claim Reference:  
Assessment Number: KKHA0071  
Version: K.KIMHIN/1  
Date Calculated: 24/12/2018 06:51

Full Report - V1  
Registration: SJU8184X  
Printed: 24/12/2018 14:51



## Addresses

## Cost Summary

Total Labour	\$562.50
Total Paint/Material	\$192.57
Total Parts	\$443.30
Excess:	TBA
Grand Total Exc GST:	\$1,198.37
7 % GST:	\$83.89
Grand Total Inc GST:	\$1,282.26

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$0.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
B410	R + R REAR BUMPER	4.0	18.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.50
NO NUMBER	R + R REAR BUMPER SUPPORT	1.0	4.50
B407	R + R LEFT REAR TAILLAMP	1.0	4.50
3481	REPAIR L/R SIDE PANEL	20 30.0*	135.00

### LABOUR COST

Total Work Units	37.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	3.7HRS	\$166.50
Paint Labour	8.8HRS	\$396.00
Total Labour	12.5HRS	\$562.50

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

### Guide Number Description

		WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
2581	REAR BUMPER NEW PART PAINT K1R	15.0	
3481	L/R SIDE PANEL REPAIR PAINTING >50%	22.0	
1781	L/R DOOR SURFACE PAINT	7.0	
2711	REAR CLOSING PANEL SURFACE PAINT	5.0	
2931	BOOTLID SURFACE PAINT	9.0	

### LABOUR COST - PAINT

TIME(PAINT)	58.0	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	88.0	

**K.KIM HIN AUTO PTE LTD****Claim Reference:****Assessment Number: KKHA0071****Version: K.KIMHIN/1****Date Calculated: 24/12/2018 06:51****Full Report - V1****Registration: SJU8184X****Printed: 24/12/2018 14:51**

<b>Total Paintwork Labour</b>	<b>8.8HRS</b>	<b>\$396.00</b>
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
<b>New Part Painting - Plastic K1R</b>		<b>\$75.77</b>
<b>Material-Constant Main Work Metal</b>		<b>\$28.60</b>
<b>Surface-/Blend Paint</b>		<b>\$51.55</b>
<b>Repair Painting</b>		<b>\$27.65</b>
<b>Material-Const Main Work Plastic</b>		<b>\$9.00</b>
<b>Total Excluding Pearlescent Uplift</b>		<b>\$192.57</b>
<b>Pearlescent Uplift @ 0.0%</b>		<b>\$0.00</b>
<b>Total Paint Material Cost</b>		<b>\$192.57</b>

**PARTS**

Guide No. Qty		Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
2581	1	REAR BUMPER	52159 02540	<i>Bud Nd</i>	0%		210.00* ✓
2621	1	L/R BUMPER RR BRKT	52156 02110		0%		38.00* X
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0%		10.00* ✓
3291	1	L/R OUTER LAMP CPL	81560 02470		0%		145.00* ✓
f: OEM Parts			Sub Total				\$403.00
g: Original			Mark Up From Cost	(10 %)			\$40.30
h: Secondhand			Sundry Parts	(Fixed)			\$0.00
p: Parallel			<b>Total Parts</b>				<b>\$443.30</b>
x: Exchange							

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Total Extras****\$0.00****Final Calculation**

<b>Total Parts</b>	<b>\$443.30</b>
<b>Labour</b>	
Total Panel/Mechanical	\$166.50
Total Paintwork	\$396.00
<b>Total Labour</b>	<b>\$562.50</b>
<b>Total Paint/Material Costs</b>	<b>\$192.57</b>
<b>Grand Total Excludes GST</b>	<b>\$1,198.37</b>
GST @ 7 %	<b>\$83.89</b>
<b>Grand Total Includes GST</b>	<b>\$1,282.26</b>

**Assessment Notes**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: