

ASS. REC. BY:

REF: CS/SM018023106/Atd3n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Menmen

Chen shu hui agnes

of

SMO

Date/Time:

28/12/18 2:27pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 3581P

Insured:

9M 5303G

at Workshop m/s

FI Autoclinic

Tel:

92712214

of

25 Keki Bukit Rd 4 #05-26 synergy

Policy No:

D18MTPV01006903

Claim No:

CMTD1805572

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/12/18

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

3:36pm 26/12/18

Person Contacted:

Chns

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBF 3581 P-X
	9M 5303G-X
28/12@15:40 pm-	Email to Agnes pending estimate.
	lump sum \$4200+ cred: 6406.85 (60%)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF3581P Yr Regn: 2006 Sept.
 Type: M.Car / M.Cycle / Bus (Van) / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C. 2494
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 340332 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFJS02PX05004169Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim orTyre Size: F: 195R15CR: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CST.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mm

D.O.A.

D.O.I. 27/12/18Survey held at F1 Auto ClinicDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampo.

COE Expiry: 12/09/21

MV: 21K
 PV: 132K
 Net: 7.8K

RECEIVED 20 FEB 2019

Date/Time, File Pass to?

2018 Typist
 Date/Time, File Return to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS, \$)

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$) 4200/-

350

10

360

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018		26 Dec 2018 14:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RENUKA VENKATARAMANI, ID: S8385024H		
Main Claimant:	LOW KAH WAI, ID: S9518866D		
Vehicle Reg. No.:	GBF3581P	Date of Loss:	14/12/2018 00:00 - :59
Claim Type:	TP / CMTD1805572	Policy/Cover Note No.:	D18MTPV01006903 (Comprehensive)
Vehicle Reg. No. (Insured):	SJM5303G	Policy No. (Claimant):	
		Excess:	
Repairer:	F1 Autoclinic Pte Ltd (HQ) Blk 25 Kaki Bukit Road 4 #05-26 Synergy @ Kaki Bukit, 417800 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/01/2019]		
Driver/Custodian (Insured):	SRINIVASAN MANIKANDAN (), NRIC: S8185572B, Tel: +6590621634		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Report Remarks Entry - CS/SMO18023106/Atd3n2

Remarks

Remarks

Add

	Remarks 1	By	On
<input type="checkbox"/>	GBF 3581P / SJM 5303G ; SUR : ADRIAN ; WKSP : F-1 AUTOCLINIC ; TP ; WP	NVT	26/12/2018 4:21:04 PM
<input type="checkbox"/>	28/12/2018 15:40 PM. - SEND TO AGNES PENDING ESTIMATE	TKC1	28/12/2018 3:42:55 PM
<input type="checkbox"/>	LUMP SUM \$4200/- 6DAYS	TKC1	20/2/2019 3:37:16 PM
<input type="checkbox"/>	20/2 - FILE PASS TO TYPIST	TKC1	20/2/2019 3:37:26 PM
<input type="checkbox"/>	CHECK WITH AGNES, SHE UNABLE TO CONFIRM THE ACCIDENT IF IT'S 13 OR 14. CHECK WITH HER CAN MAINTAIN AS 14 AND SUBMIT AS 14/12/2018 SHE SAY OK.	TKC1	28/2/2019 9:07:14 AM

View Sent Message

This mail is associated with :

***GBF3581P (CMTD1805572)
[SJM5303G]**

TP
LOW KAH WAI
Dec 14 2018 12:00AM
[RENUKA VENKATARAMANI]
F1 Autoclinic Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 28/12/2018 15:40 PM.
To agnes.chan@sompo.com.sg
Subject GBF3581P (CMTD1805572) [SJM5303G]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBF 3581P on 27/12/2018
We are pending estimate from repairer.

Regards,
Denise
LKKAuto

DOCUMENTS SUMMARY

There are no documents.

Henry, Irene James

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Wednesday, 26 December, 2018 12:53 PM
To: Henry, Irene James
Cc: Chan, Shu Hui Agnes; Ye, Yong Kang Melvin
Subject: Re: SOMPO REF: CMTD1805572/RE: GBF3581P & SJM530G doa 13/12/18

Dear Sir / Mdm ,

LKK Auto Consultant Pte Ltd. Thanks

Get [Outlook for iOS](#)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Wednesday, December 26, 2018 12:33:25 PM
To: chan pick yuen
Cc: Chan, Shu Hui Agnes; Ye, Yong Kang Melvin
Subject: SOMPO REF: CMTD1805572/RE: GBF3581P & SJM530G doa 13/12/18

Our Reference : CMTD1805572

Your Reference: GBF 3581P

Date: 26th December 2018

Without Prejudice
EMAIL ONLY

Attention:

M/S F-ONE AUTOCLINIC PTE LTD

ACCIDENT INVOLVING SJM 5303G & GBF 3581P ON 13.12.2018

Dear Sir/ Madam,

We refer to your Notice of Accident dated 26/12/2018 .

Please be informed that Agnes Chan is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	

		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: chan pick yuen <chris_chanbebe@hotmail.com>

Sent: Wednesday, 26 December, 2018 10:15 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: GBF3581P & SJM530G doa 13/12/18

Dear Sir / Mdm ,

Enclosed is our clients GIA report .

Please let us have your 10 name list of surveyor to survey our clients vehicle:GBF3581P . Thanks

Best Regards

Chris Chan

F-1 Autoclinic Pte Ltd

Hp:92712214

Get [Outlook for iOS](#)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2011 Volkswagen Scirocco 1.4A TSI Sunroof



Low Interest Rate @2.78%!
Very Well Maintained & Low
Mileage!
StarAd



ABWIN

ONE-STOP



VIEW OUR PRICES

Browse by Category

Save Search

Print

« Back (1 2) Next »

Sort by Date Posted

20 results/page

34 vehicles

Search

Hiace

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Hiace

Any

Any

> 10 year(s)
old

Any

Any

Any

Available



☐ Toyota Hiace (COE till
09/2020)

\$9,800

\$5,570 /yr

06-Oct-2000

2,986 cc

-

Van

Available

Fuel Type: Diesel

100% Loan View At Phoenix Motor Trading Enterprise.

Posted: 03-Dec-2018 Tags: 2000 Toyota Hiace, 2000 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, Hiace, Used Toyota



☐ Toyota Hiace

\$58,900

N.A

15-Apr-2003

2,985 cc

-

Bus

Available

Fuel Type: Diesel

Toyota Hiace Has Always Been A Reliable Vehicle, Selling Due To Loss Of Contract Jobs. My Loss Is Your Gain. COE Till 2023.

Posted: 27-Dec-2018 Tags: 2003 Toyota Hiace, 2003 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, Hiace, Used Toyota

DIRECT OWNER



☐ Toyota Hiace (COE till
02/2022)

\$25,000

\$7,880 /yr

14-Oct-2004

2,986 cc

-

Van

Available

Fuel Type: Diesel

COE. Left 4 Years.

Posted: 28-Oct-2018 Tags: 2004 Toyota Hiace, 2004 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, Hiace, Used Toyota

DIRECT OWNER



☐ Toyota Hiace (COE till
03/2020)

\$16,800

\$13,360 /yr

04-Apr-2005

2,494 cc

-

Van

Available

Fuel Type: Diesel

In-House Loan Available. Many Parts Changed Already. New Clutch And Mountings.

Posted: 03-Dec-2018 Tags: 2005 Toyota Hiace, 2005 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, Hiace, Used Toyota

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ Toyota Hiace (COE till
07/2021)

\$23,000

\$8,870 /yr

04-Sep-2006

2,494 cc

-

Bus

Available

Fuel Type: Diesel

Can Convert To School Bus (CB Plate) If Available As Where It Is Condition. Do Not Miss This Opportunity Again. Make An Exclusive Appointment To View Now.

Posted: 21-Nov-2018 Tags: 2006 Toyota Hiace, 2006 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, Hiace, Used Toyota

DIRECT OWNER



☐ Toyota Hiace (COE till
02/2022)

\$25,800

\$8,280 /yr

08-Feb-2007

2,982 cc

117,000 km

Van

Available

Fuel Type: Diesel

1 Owner, Mileage 117000Km Only, Suitable For New Business, Hassle Free, Wear And Tear Will Be Replaced, Call, Don't Miss This Superb Hiace.

SG Motor Link Pte Ltd

Posted: 20-Dec-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, Hiace, Used Toyota

PREMIUM AD

☐ Toyota Hiace (COE till
03/2022)

\$24,800

\$7,740 /yr

12-Mar-2007

2,982 cc

-

Van

Available

Fuel Type: Diesel

SHOW FILTERS HISTORY

Compare [2]



Coe Till March 2022. Excellent Condition. Call To View Now Before It Is Too Late. In House Loan Available.

Hui Hua Credit Pte Ltd

Posted: 20-Dec-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace (COE till 03/2022) \$24,800 \$7,680 /yr 21-Mar-2007 2,982 cc - Van Available

Fuel Type: Diesel

Suitable For New Business, Hassle Free, New Head Lamps, New Audio System. Don't Miss This Superb Hiace, New Paintwork. Very Good Condition. Please Call Only.

DIRECT OWNER

Posted: 10-Dec-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace (COE till 05/2022) \$27,800 \$8,270 /yr 09-May-2007 2,982 cc - Van Available

Fuel Type: Diesel

One And Only Auto Transmission Toyota Hiace At This Price And Condition! Full Carpet Upholstery Cargo Space! Full Glass Window Panels Done! Genuine Low Mileage! Agent Maintained! Borneo Unit! Call Now...

PREMIUM AD

Net Link Partners Pte Ltd

Posted: 21-Dec-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace (COE till 06/2022) \$30,800 \$8,960 /yr 06-Jun-2007 2,982 cc - Van Available

Fuel Type: Diesel

Very Well Maintained By Previous Owner, Most Importantly, Accident Free! Buy With No Worries As Toyota Usually Doesn't Give Much Headaches. Don't Want To Invest Too Much On A Brand New Vehicle? No Pro...

Posted: 29-Oct-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Sell your Car for \$3,000 More

With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quotz typically receive up to \$3000 above market value. Quotz Guarantees the Highest Selling Price in Singapore - if we fail, you get \$100 cash from us. Get your Car Listed Today.

Find out more!



☐ Toyota Hiace (COE till 07/2022) \$29,800 \$8,300 /yr 13-Aug-2007 2,982 cc 200,000 km Van Available

Fuel Type: Diesel

PREMIUM AD

Posted: 26-Oct-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace (COE till 07/2022) \$27,888 \$7,760 /yr 31-Aug-2007 2,982 cc - Van Available

Fuel Type: Diesel

Cheapest In The Market! Superb Condition Maintain By Previous Owner! No Need Introductions For It's Performance, Low On Diesel And Maintenance Cost! Great For New Business Start Up, Call Now For No Ob...

Net Link Partners Pte Ltd

Posted: 14-Dec-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace Commuter (COE till 11/2022) \$38,888 \$9,980 /yr 20-Nov-2007 2,982 cc 76,000 km Bus Available

Fuel Type: Diesel

One Owner Only With Low Mileage Unit! Road Tax Till May 2018! Brand New Paintwork, Definitely Good To Go For Another 5/10 Years. Most Popular Japan Make And Model Van. Most Of The Wear And Tear Has Be...

DIRECT OWNER

Posted: 17-Nov-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace (COE till 03/2023) \$30,800 \$7,230 /yr 01-Apr-2008 2,982 cc - Van Available

Fuel Type: Diesel

Additional Insurance Discount Will Be Given When You Purchase A Vehicle From Us! One Of The Most Durable And Reliable Workhorse For Sales! Just Renew 5 Years COE, No Repairs Needed, Easy To Maintenance...

PREMIUM AD

KSL Automotive Pte Ltd

Posted: 27-Nov-2018 Tags: 2008 Toyota Hiace, 2008 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace (COE till 05/2023) \$31,800 \$7,210 /yr 26-May-2008 2,494 cc - Bus Available

Fuel Type: Diesel

1 Careful Owner Only, Low Mileage Done Of 18.5k Km/yr Only, Normal Car Park Price, Well Maintain By Previous Owner, Sell As To Retire, Easy Loan, Trade In Welcome, Call To View Fast.

PREMIUM AD

SG Motor Link Pte Ltd

Posted: 24-Dec-2018 Tags: 2008 Toyota Hiace, 2008 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

☐ Toyota Hiace Commuter (COE till 04/2023) \$29,800 \$6,870 /yr 30-May-2008 2,982 cc - Bus Available

Fuel Type: Diesel

SHORTLISTED HISTORY

Compare [2]

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	8965R
Vehicle Details	
Vehicle No.:	GBF3581P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2KD1489823
Chassis No.:	JTFJS02PX05004169
Maximum Power Output:	-
Open Market Value:	\$26,612.00
Original Registration Date:	13 Sep 2006
First Registration Date:	13 Sep 2006
Transfer Count:	2
Actual ARF Paid:	\$1,331.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Details	
COE Expiry Date:	12 Sep 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,044.00
COE Rebate Amount:	\$13,196.00
Total Rebate Amount:	\$13,196.00
Message	

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 28 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/12/2018 13:31
Date Of Accident	13/12/2018 23:30
Exact Location Of Accident	PIE TOWARDS BENDEMEER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF3581P
Insured/Policyholder	
Name Of Registered Owner	NET LINK COMMERCIAL PTE. LTD.
Co Reg No	201618965R
Email Address	DJ_KAHWAI@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-88281661
Alternative Phone No	OFFICE-88281661

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-2.0 (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082689606-02
Cover Note Number	COMPREHENSIVE

Driver

Name of Driver	LOW KAH WAI
NRIC No	S9518866D
Date Of Birth	27/05/1995
Occupation	INDOOR
Date Of Driving Pass	22/12/2015
Driving Experience	2 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96560096
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 246 KIM KEAT LINK #06-23
Postcode	310246
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - PRIVATE HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEHICLE IN FRONT STOPPED AND I FOLLOWED SUIT WHEN VEHICLE B COULD NOT STOP IN TIME AND HIT INTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM5303G
Vehicle Make/Model/Colour	TOYOTA SIENTA
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	MANIKANDAN
NRIC/Passport Number	S8185572B
Contact Number	90621634
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LOW KAH WAI
------	-------------

Approximate Age	23
Injuries Sustain	NECK
Injured person in which vehicle?	GBF3581P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 246 KIM KEAT LINK #06-23
Postcode	310246

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

28th DECEMBER 2018

Bk 25 Kaki Bukit Rd 4
 # 05-26 SYNERGY @KB
 Singapore 417800

TP Sampo
 Denise

JTFJS02PX05004168

Accident date: 13th DECEMBER 2018

Estimated repair cost for vehicle no: GBF3581P TOYOTA HIACE

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		<u>\$2,500.10</u> 1755
2	1	Rear boot lid hiace logo <i>new</i>		\$38.10 X
3	1	Rear boot lid 70 KM logo <i>new</i>		\$35.00 15(SN)
4	1	Rear boot lid Toyota logo <i>new</i>		\$38.10 ✓
5	1	Rear boot lid emble logo <i>new</i>		\$66.10 X
6	1	Rear boot lid inner lock <i>new</i>		<u>\$509.10</u> 263
7	1	Rear boot lid inner rubber <i>new</i>		\$329.10 ✓
8	1	Rear boot lid inner trim board <i>new</i>		\$540.10 X
9	10	Rear boot lid inner trim board clips <i>new</i>	\$12.90	\$129.00 +
10	1	Rear boot lid centre moulding <i>new</i>		\$209.10 +
11	2	Rear boot lid number plate garnish <i>new</i>		\$166.40 +
12	1	Rear boot lid number plate <i>new</i>		\$50.00 +
13	2	Rear tail lamp <i>crushed</i>	\$320.20	\$640.40 ✓
14	1	Rear bumper <i>Dented</i>		\$520.10 ✓
15	1	Rear bumper reverse sensor <i>new</i>		\$350.00 200(SN)
16	2	Rear bumper side bracket <i>new</i>	\$121.25	\$242.50 58
17	10	Rear bumper clips <i>new</i>	\$12.90	\$129.00 30
18	1	Rear end panel <i>Dented</i>		\$580.15 ✓
19	1	Rear End Panel Top Garnish <i>new</i>		\$209.10 ✓
20	6	Rear End Panel Top garnish clips <i>new</i>	\$12.90	\$77.40 X
21	1	Rear Exhaust <i>Repair</i>		\$858.00 X

Subtotal :- \$8,216.85

4432.55

332471 SN: 200

Labour charges

To remove & re-fix rear windscreen

\$120.00 ✓

Gum *nel*

\$50.00 ✓

To remove & re-fix rear reverse sensor

~~\$100.00~~ 50

To remove & re-fix cushion

~~\$120.00~~ 60

to remove & Refix rear exhaust

~~\$200.00~~ 80

To Check Wiring System

~~\$80.00~~ 30

Tuff kote

~~\$120.00~~ 50

Panel beating

~~\$800.00~~ 700

Spray painting

~~\$800.00~~ 600

Subtotal :- \$2,390.00

Total:- \$10,606.85

*total: 5264.71
L/S: A.2K
06 Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18023106/ATD3N2

Date: 28/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01006903
Claimant Vehicle No :	GBF3581P	Insured Vehicle No :	SJM5303G
Date of Loss:	14/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805572

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF3581P	Engine No:	2KD1489823
Make & Model:	TOYOTA HIACE, 2.5 (M)	Chassis No:	JTFJS02PX05004169
Reg. Date:	13/09/2006 (Man. Year: 2006)	Odometer:	340332 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,266.85	3,589.71	4,677.14	56.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,690.00	650.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,606.85	5,279.71	5,327.14	50.22
Approved Total (Overridden) (\$\$)		4,200.00		
Nett Amount (\$\$)	10,606.85	4,200.00	6,406.85	60.40

INSPECTION

Date of Assignment:	26/12/2018	
Date Inspected:	27/12/2018 Inspected At:	F1 Autoclinic Pte Ltd (HQ) Blk 25 Kaki Bukit Road 4 #05-26 Synergy @ Kaki Bukit Singapore 417800

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Feb 2019)	
Parts:	N/A	TOYOTA HIACE 2.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3581P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	2,500.10 F	*1,755.00 FL
2	1		*REAR BOOT LID HIACE LOGO	Not Necessary	38.10 F	*- FL
3	1		*REAR BOOT LID TOYOTA LOGO	Necessary	38.10 F	*38.10 FL
4	1		*REAR BOOT LID EMBLEM LOGO	Not Necessary	66.10 F	*- FL
5	1		*REAR BOOT LID INNER LOCK	Damaged	509.10 F	*263.00 FL
6	1		*REAR BOOT LID INNER RUBBER	Cut	329.10 F	*329.10 FL
7	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	540.10 F	*- FL
8	10		*REAR BOOT LID INNER TRIM BOARD CLIPS	Not Necessary	129.00 F	*- FL
9	1		*REAR BOOT LID CENTRE MOULDING	Not Necessary	209.10 F	*- FL
10	2		*REAR BOOT LID NUMBER PLATE GARNISH	Not Necessary	166.40 F	*- FL
11	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
12	2		*REAR TAIL LAMP	Cracked	640.40 F	*640.40 FL
13	1		*REAR BUMPER	Deformed	520.10 F	*520.10 FL
14	2		*REAR BUMPER SIDE BRACKET	Necessary	242.50 F	*68.00 FL
15	10		*REAR BUMPER CLIPS	Necessary	129.00 F	*30.00 FL
16	1		*REAR END PANEL	Dented	580.15 F	*580.15 FL
17	1		*REAR END PANEL TOP GARNISH	Bent	209.10 F	*209.10 FL
18	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	77.40 F	*- FL
19	1		*REAR EXHAUST	Repair	858.00 F	*- FL
20	1		*REAR BOOT LID 70 KM LOGO	Necessary	35.00 FS	*15.00 FS
21	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
22	1		*GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,266.85	4,697.95
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,108.24
Total Parts (\$\$)	8,266.85	3,589.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RE-FIX REAR WINDSCREEN	New	120.00	120.00
2	TO REMOVE & RE-FIX REAR REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & RE-FIX CUSHION	New	120.00	60.00
4	TO REMOVE & RE-FIX REAR EXHAUST	New	200.00	80.00
5	TO CHECK WIRING SYSTEM	New	80.00	30.00
6	TUFF KOTE	New	120.00	50.00
7	PANEL BEATING	New	800.00	700.00
8	SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (\$\$)			2,340.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >