inverse Marcus	ASSIGNMENT (Office)
om (Person): Monica C	hung of MSIG Datestime 28/12/18 32 Gpt
stimated Cost:	Bill to:
D (TP)WS/TP RES/OD	RES/EVA/INV/MV/CS
o Inspect Vehicle No:	8 E 842 X Insured: FB 89388
t Workshop m/s	3 Motorworkz Tol: 927/2014
r25 k	aki Bukit Pd4 #01-40
olicy No: MSD/VMS/	18-997193 Claim No: MSC V 18-001634
Sum Insured:	Excess:
Aake of Veh:	D.O.A. 21/12/2018.
Client's Record)	
	24 HRS (Ψ)
CA / REV / REP. / REV	
CA / REV / REP. / REV Date/Time: 3.4600000	26/2/8 Person Contacted Chris Vehicle IN JOUT
Date/Time: 346m0	26/12/18 Person Contacted Chris Vehicle IN DUT
Date/Time: 346m0	26/12/18 Person Contacted: Chris Vehicle IN DUT
Date/Time: 3 46 m O Date/Time Action/Instruc	26/12/18 Person Contacted: Chris Vehicle Inibur
Date/Time: 3.46m0 Date/Time Action/Instruc	26/12/18 Person Contacted Chris Vehicle In DUT
Date/Time: 3 46 m O Date/Time Action/Instruc	26/12/18 Person Contacted: Chris Vehicle Injour
Date/Time Action/Instruc	26/12/18 Person Contacted: Chris Vehicle Inibur

REF: MSIG

...CLAIM SUBFOLDER...(New Assignment)

AIM SUBFO	LDER TRA	CKING					100000000000000000000000000000000000000			
Case N	otified	Est Submitted	Adj Assigned	Adj Rpt	Adj Subi	mitted	Ins Authled	Status		
Main 2	1 Dec 2018		26 Dec 2018 15:26 Assign					Cancel	Case Case	
M	ain	R	eference		Claim Details		Documer	nts	Sho	IIA wo
CLAIM SUB	FOLDER DE	TAILS				[Creat	ed by insurer]			
Insured:	TAY CHEE	WAH, ID: \$14	02276G							
Main Claimant:	REGINA T	EO GUAT KHEN	G , ID: S01456	38E						
Vehicle Reg. No.:	SJE8421	ıx			Date of Loss:	[127 M	2018 08:00 - :59 Ionths and 12 Days			lan Yr)
Claim Type:	TP / MS	C/V/18-00163	1		Policy/Cover Note No.:	100 per 15 per 1	D/VMS/18-997193 (TP, Fire & Theft) verage: 06/12/2018 - 05/12/2019			
Vehicle Reg. No. (Insured):	FBJ8938F	3			Policy No. (Claimant):					
7//					Excess:					
Repairer:	3 Motorw	erkz Concepts I	Pte Ltd (HQ) 25	Kaki Bukit R	oad 4, Synergy (@ KB #0	1-40, 417800 Kaki	Bukit - Tel:	97972800	
Handling Insurer:							d by Monica Chun	g Pei Zhei	n - 6594 255	52]
Adjuster:	LKK Auto	Consultants Pt	e Ltd (HQ) - Tel	6256-3561	[Imm.Adv	ice due	27/12/2018]			
Driver/Custo dian (Insured):		WAH (59 / Male)	NRIC: S14022	276G						
Adj Asg. Remarks:	Car in, pls	survey today. SJ	E AGREE LKK, LI	AB 100%. PL	S CONTACT CHR	IS CHAN	@ 92712214			
ASSOCIATI	D MAIL RE	CEIVED						View All	Compose C	ase Ma
There are no	mail for this	case.								
ALL ASSOC	CIATED TAS	SKS⊡				View	All Search Tasks	Create N	lew Task	Comple
Due Date	Priority	Type Tasl	Group Sub	ject Han	dler Assign	ned By	Completed 0	in Cre	eated On	Don
No results.	510000000000000000000000000000000000000	107.5								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid,	
	ACCIDENT STATEMENT
Date Of Report	21/12/2018 21:17
Date Of Accident	21/12/2018 08:30
Exact Location Of Accident	MCE TOWARD AYE
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SJE8421X
Insured/Policyholder	
Name Of Registered Owner	REGINA TEO GUAT KHENG
NRIC No	S0145638E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97267224
Alternative Phone No	OFFICE-97267224
Vehicle Particulars	
Manufacturer	HONDA
Model	FIT 1.3G A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-007154
Cover Note Number	
Driver	
Name of Driver	CHUNG DI YA VERA
NRIC No.	S8915797H

NRIC No S8915797H 08/05/1989 Date Of Birth INDOOR Occupation 07/07/2012 Date Of Driving Pass

6 YEARS AND 5 MONTHS **Driving Experience**

FEMALE Gender

(LOCAL) +65-97267224 Mobile Number

Fax Number Contact Number

VERACHUNG@PBT.COM.SG **EMail Address**

Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident
Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I was driving along mce towards Sentosa. Veh infront of me suddenly jammed brake. I manage to stop on time. Suddenly, veh b hit against my rear. My rear was damage and no injury involved.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBJ8938R

Vehicle Make/Model/Colour

SYM/JOYRIDE 2001

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

MR TAY

NRIC/Passport Number

S1402276G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

ĺ

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the socident to speed up the claims process.
 This Form must be completed by the Policyholder and/or the Authroised Driver.
 Information provided must be as truthful and accurate as possible. Any within misrepresentation or withholding of material facts may

- Information provided must be as truthfur and accurate as possible. Any water misrepresentation or withholding of material facts may allow insurance companies to repudiate policy flability.
 The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
 Any false reporting may be referred to the Police for investigation.
 The report will be forwarded by the insurance of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
 By the lodgement of this report to the insurance, you hereby consent to the archiving of this report at the centre and to doples of the report. being made available aforesaid 8. Consent under the Personal Data Protection Act (PDPA)
- - 6. Consent under the Personal Data Protection Act (PDPA). I understand, acknowledge, agree and consent that: I understand, acknowledge, acknowledge,
- (iii) derrying out and/or dealing with my instructions or responding to any enquiries by me;
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); end/or

- packages); end/or

 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

 (collectively the "Purposes")

 (b) all insurer(s) who have insured vehicle(s) involved in this addient and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and

 (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS REPORTING OFFICER MOHAMED SHARIL BIN SATAR

Policyholder's Signature / Date & Time - Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel


Sketch Plan

hide neuro e poi pro the) im i) oe /) ad dis pe-(oc all as

tisck ny P Incli

ync

tcl



Common Statement Pg. 1

CCIDENT STATEMENT (2000 characters)	
I was driving along mce towards Sent manage to stop on time. Suddenly, ve no injury involved.	osa. Veh infront of me suddenly jammed brake. I h b hit against my rear. My rear was damage and
Taxi Voucher No.:	
DECLARATION I/We declare that the above particulars & information p	rovided above are true in every aspect
VERIFIED BY AJAX MARS REPORTING OFFICER - MOHAMED SHARIL BIN SATAR	
MARS Officer	Registered Owner or Driver's Signature
Job Complete Date/Time	Date/Time:
21 December 2018 at 8:08 PM	21 December 2018 at 8:08 PM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Singapore NRIC Owner ID Type 5638E Owner ID: Vehicle Details SJE8421X Vehicle No.: Yes. Vehicle to be Exported: 25 Dec 2018 Intended Deregistration Date: HONDA Vehicle Make: FIT 13GA Vehicle Model: Blue Primary Colour: 2008 Manufacturing Year: L13A4049559 Engine No.: GE61044127 Chassis No. 73.0 kW (97 bhp) Maximum Power Output: \$13,858.00 Open Market Value: 09 May 2008 Original Registration Date: 09 May 2008 First Registration Date: Transfer Count: \$13,858.00 Actual ARF Paid: Intended PARF Rebate Details Forfeited PARF Eligibility: PARF Eligibility Expiry Date:

Intended COE Rebate Details

COE Expiry Date:

PARE Rebate Amount

COE Category

COE Period(Years):

PQP Paid

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 25 Dec 2018

OK

\$0.00

10

08 May 2028

\$38,192.00

\$35,781.00

\$35,781.00

A - Car (1600cc & below)

Login Sign up SGCARMART.COM Resources Articles Forum Products Insurance Directory Sell My Car **Used Cars** New Cars Self Import 5 series (G30) or X3 (G01) worthwhile? DO you use car covers ? 2018 / 2019 7th Generation Lexus ES Advanced Search Depreciation ✓ > 10 year(: ✓ Vehicle Type Price Range FIT Home » Used Cars » Monster Motors Pte Ltd » Honda Fit 1.3A G (COE till 05/2028) Resources Honda Fit 1.3A G (COE till 05/2028) Photos (CONSTGNAME)(I Similar Research Overview Financial Accessories Car Buying Car Selling CONSIGNMENT / BUY / SELL / SCRAP / EXPORT Car Ownership Car Aftermarket Share Add a Note Report Error More Actions Add to Shortlist Add to Compare On The Move Owner Consignment Car Car Details Lifestyle This car is for sale by direct owner via a consignment \$48,000 Price agent. Consignment agents help to market, sell and 0 Commercial Vehicle \$5,090 /yr Depreciation handle all documentation on the car seller's behalf. WAAND NEW FLEET List of owner consignment cars 30-May-2008 Reg Date AVAILABLE FOR List of consignment agents (9yrs 5mths 2days COE left) RENT/LEASE 0 Manufactured 108,000 km (10.2k /yr) Mileage Auto Transmission 1.339 cc **Engine Cap** 0 Road Tax \$590 /yr 73.0 kW (97 bhp) MONSTER Power View specs of the Honda Fit (2008-2013) 0 **Curb Weight** Fully Stock 1.3L I-VTEC Engine Combined With A Features Responsive, Quiet And Smooth 5 Speed CVT Auto Transmission Producing Up To 97 Bhp. SRS Airbags, ABS. Accessories 1 Owner Unit With Genuine Low Mileage, In Car Camera, Navigation, Factory Sound System. Honda's Signature Compact And Nimble VTEC Description Hatchback In Factory Black Exterior And Red On Black Leather Upholstery. Buy With A Peace Of Mind. Always Parked Under Shelter. Regularly Serviced At Reputable Honda Workshop, High Loan Up To 90% Available. All Trade Ins Accepted. Viewings Strictly By Appointment Only. Call Now, This Baby Could Be Yours Next! 0 COE \$38,192 0 Location Map OMV \$11,514 SHOP NOW 0 \$5,543 ARF Seller Information \$36,005 as of today (change) Dereg Value Monster Motors Pte Ltd Company » dealer's pricelist No. of Owners » 74 vehs sold | 132 vehs available Type of Veh Hatchback. 453 Tagore Industrial Avenue #01-Address COE Car, Consignment Car Category Available CONSIGNMENT) Search cars nearby this location Availability Compare

3 MOTORWERKZ CONCEPT PTE LTD

Block 25 Kaki Bukit Road 4, #01-40/42 Synergy @ KB Singapore 417800

HP: 96583371

Not Arthoral

Mula

Mercus

741.62563.561

27/1/18

The phe Aller 197 3200/.

26th December 2018

REGINA TEO GUAT KHENG Bk 25 Kaki Bukit Rd 4 # 01-40/42 SYNERGY @KB Singapore 417800

Accident date: 21st DECEMBER 2018

Estimated repair cost for vehicle no: SJE8421X HONDA FIT 1.3 A '08

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid 785-30	Bods		
	2	Rear Boot Lid Hinges	A CONTRACTOR OF THE PARTY OF TH	71 \$90.20	100000
	1	Rear Boot Lid Fit logo		200 \$40.00	
	1	Rear boot lid emble logo		71 \$95.00	
	1	Rear Boot Lid Number Plate		1 M \$50.00	
	2	Rear Boot Lid Number Plate Lamp	\$42.70	11 \$85.40	
7	4	Rear Boot Lid Inner Lock /09.60	D	2/shul \$186.30	
3	4	Rear boot lid inner rubber		7~1 \$128.10	
)	4	Rear Boot Lid Inner Trim board 2 45-30		selone \$296.70	
10	4	Rear Boot Lid Inner Lock side cover		17 \$28.50	
11	4	Rear Boot Lid windscreen solar film		17 \$200.00	
12	4	Rear boot lid windscreen seal		per \$136.21	
13	2	Rear tail lamp 285-40	\$338.10	0/SCM \$676.20	
	2	Rear tail lamp panel	\$128.40	2 \$256.8	
14	2	Rear tail lamp inner panel	\$110.00	R \$220.0	
15 16	Δ	Rear tail lamp clips	\$6.50	11 \$26.0	
17	4	Rear Bumper 486-30		2/3 \$853.0	
18	2	Rear Bumper Side Bracket 2 fdv	\$58.70	1/5/1/ \$117.4	0 11
19	8	Rear bumper clips 35.00	\$5.00	nei \$40.0	
20	4	Rear Bumper reverse sensor		shed \$300.0	
21	- 1	Rear Bumper towing cover 2 f-10		70.1 \$38.1	
	2	Rear bumper mud shield	\$54.10	11 \$108.2	
22	8	Rear Bumper mud shield clips	\$5.00	11 \$40.0	
23	0	Rear End Panel 296.60		9 \$492.9	0-
24	1	Rear End Panel Top Garnish		Y~1 \$110.1	0 .
25	1	Rear spare tire panel top cover		1 / \$260.4	0 0
26	4	Rear Exhaust		\$605.0	
27	4	Rear Exhaust chome pipe		11 \$160.0	00
28	1	Real Extiatist chome Piles	Subtotal :-	\$6,717.5	0

Page 322

2578.7

Sheet1

Labour charges			\$120.00	80
To remove & re-fix cushion			100000000000000000000000000000000000000	
To remove & re-fix reverse sensor			\$100.00	10
To remove & re-fix rear windscreen			\$120.00	
tum Reer wind screen seelant		rec	\$50.00	405.N
To remove & re-fix rear exhaust		1	\$250.00	60
To Check Wiring System			\$60.00	20
Tuff Kote			\$120.00	60
Towing charges		11	\$0.00	× .
Panel beating			\$800.00	600
Spray painting			\$800.00	700
	Subtotal :-		\$2,420.00	

Lieu Auto Consultants hence notify

It a Propose of the Ichowing:

• In representation stray, building

• The proposed partial compressively

• Part these a enablest to posternation

• The proposed partial of allowed

• Supplementary scouls) must be resurveyed and its subject to find approval from Insurance Company

Addingwiedged by Repairer

Signature:
Date:

P-2062-96 S.N-270-00 lahn-1690.00 402.96 145 202 3218.

\$9,137.50

Total:-

...CLAIM SUBFOLDER...(Pending for Survey Report)

	OLDER TRA	Est Submitted	Adj Assigned	Adj Rpt	Adj Sul	mitted	Ins Auth'ed	Status		900
WHY A.	21 Dec 2018	1.01	26 Dec 2018 15:26 Edit Adj Rpt	S\$3,200.00 Edit Estimate	The state of the s	and the same of th		Pending for Survey Report Cancel Case		ey
м	lain	Re	ference	CI	aim Details		Docume	nts	Si	now All
CLAIM SUE	SFOLDER DE	TAILS			***	[Creat	ed by insurer]			
Insured:	TAY CHEE	WAH, ID: S140	2276G							
Main Claimant:	REGINA 1	TEO GUAT KHEN	3, ID: S01456	38E		lacus:	2010 00 00 -50			
Vehicle Reg. No.:	SJE842	1X			Date of Loss	[127 M	2018 08:00 - :59 lonths and 12 Day			Man Yr)]
Claim Type:	TP / MS	C/V/18-001634			Policy/Cover Note No.:	Covera	MS/18-997193 (TP ge: 06/12/2018 -	05/12/2019	!	
Vehicle Reg. No. (Insured):	FBJ8938	R			Policy No. (Claimant):					
(11130100)1					Excess:				7072000	
Repairer:	3 Motory	verkz Concepts P	te Ltd (HQ) 25	Kaki Bukit Ro	ad 4, Synergy	@ KB #0	1-40, 417800 Kak	Bukit - Tel: 9	7972800)
Handling Insurer:	MSIG Ins	surance (Singapo	ore) Pte. Ltd. (HQ) - Tel: +6	5 6827 7888 .	[Handle	d by Monica Chu	ng Pei Zhen	6594 2	552] 2/2018
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel	: 6256-3561 .	[Handled by	MARCUS	S CHUA] [Imn	I.Advice di	16 2//1	2/2010
Driver/Cust dian (Insured):	TAY CHEE	WAH (59 / Male),								
Adj Asg. Remarks:	Car in, pl	s survey today. SJ	E AGREE LKK. LI	AB 100%. PLS	CONTACT CH	IRIS CHAN	N @ 92712214			
ASSOCIAT	ED MAIL R	ECEIVED						View All	Compose	Case Ma
There are n	o mail for thi	s case.								
ALL ASSO	CIATED TA	sks⊟			er py too	View	All Search Tasks			Comple
Due Date	e Priority	y Type Task	Group Sul	bject Hand	dler Assi	gned By	Completed (On Crea	ted On	Done
No results.										

Claim Documents

*SJE8421X (MSC/V/18-001634)

[FBJ8938R]

TP

REGINA TEO GUAT KHENG

Dec 21 2018 8:00AM

[TAY CHEE WAH]

3 Motorwerkz Concepts Pte Ltd

Up	Opload Documents Upload Photos Compose New Letter Vie		View	View in Brow	wser 🔻
Pho	tos/Images		3 per p	page 🔻	1
Vo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
1	27/12/18 18:28	Chassis Number	0	Load JPG	4
2	27/12/18 18:28	Odometer Reading	0	Load JPG	*
3	27/12/18 18:29	General View	0	Load JPG	1
4	27/12/18 18:29	General View	0	Load JPG	1
5	27/12/18 18:29	General View	0	Load JPG	4
5	27/12/18 18:29	General View	0	Load JPG	4
7	27/12/18 18:29	General View	0	Load JPG	2
3	27/12/18 18:29	General View	0	Load JPG	4
9	27/12/18 18:29	General View	0	Load JPG	1
10	27/12/18 18:29	General View	0	Load JPG	4
11	27/12/18 18:29	General View	0	Load JPG	
12	27/12/18 18:29	General View	0	Load JPG	
13	27/12/18 18:29	General View	0	Load JPG	•
14	27/12/18 18:29	General View	0	Load JPG	
15	27/12/18 18:29	General View	0	Load JPG	
16	27/12/18 18:29	General View	0	Load JPG	
17	27/12/18 18:29	General View	0	Load JPG	
18	27/12/18 18:29	General View	0	Load JPG	
19	27/12/18 18:29	General View	0	Load JPG	
20	27/12/18 18:29	General View	0	Load JPG	
21	27/12/18 18:29	General View	0	Load JPG	
22	27/12/18 18:29	General View	0	Load JPG	
23	27/12/18 18:29	General View	0	Load JPG	
24	27/12/18 18:29	General View	0	Load JPG	
25	27/12/18 18:29	General View	0	Load JPG	
26	27/12/18 18:29	General View	0	Load JPG	
27	27/12/18 18:29	General View	0	Load JPG	
28	27/12/18 18:29	General View	0	Load JPG	
29	27/12/18 18:29	General View	0	Load JPG	
30	27/12/18 18:29	General View	0	Load JPG	
31	27/12/18 18:29	General View	0	Load JPG	
32	27/12/18 18:29	General View	0	Load JPG	
33	27/12/18 18:29	General View	0	Load JPG	6
34	27/12/18 18:29	General View	0	Load JPG	
35	27/12/18 18:29	General View	0	Load JPG	

Photos/Images		3 per	page ▼	~	
No Relabel/Reorder		Relabel/Reorder LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
36	27/12/18 18:29	General View	0	Load JPG	•
37	27/12/18 18:29	General View	0	Load JPG	•
38	27/12/18 18:29	General View	0	Load JPG	•
39	27/12/18 18:29	General View	0	Load JPG	1
40	27/12/18 18:29	General View	0	Load JPG	•
41	27/12/18 18:29	General View	0	Load JPG	•
42	27/12/18 18:29	General View	0	Load JPG	•
43	27/12/18 18:29	General View	0	Load JPG	•
44	27/12/18 18:29	General View	0	Load JPG	•
45	27/12/18 18:29	General View	0	Load JPG	1
46	27/12/18 18:29	General View	0	Load JPG	•
47	27/12/18 18:29	General View	0	Load JPG	•
48	27/12/18 18:29	General View	0	Load JPG	•
49	27/12/18 18:29	General View	0	Load JPG	4
50	27/12/18 18:29	General View	0	Load JPG	•
51	27/12/18 18:29	General View	0	Load JPG	•
52	27/12/18 18:29	General View	0	Load JPG	•
53	27/12/18 18:29	General View	0	Load JPG	•
54	27/12/18 18:29	General View	0	Load JPG	•
55	27/12/18 18:29	General View	0	Load JPG	•
56	27/12/18 18:29	General View	0	Load JPG	•
57	27/12/18 18:29	General View	0	Load JPG	•
58	27/12/18 18:29	General View	0	Load JPG	•
59	27/12/18 18:29	General View	0	Load JPG	•
60	27/12/18 18:29	General View	0	Load JPG	•
61	27/12/18 18:29	General View	0	Load JPG	•
62	27/12/18 18:29	General View	0	Load JPG	•
63	27/12/18 18:29	General View	0	Load JPG	•
64	27/12/18 18:29	General View	0	Load JPG	•
65	27/12/18 18:29	General View	0	Load JPG	•
66	27/12/18 18:29	General View	0	Load JPG	•
67	27/12/18 18:29	General View	0	Load JPG	•
68	27/12/18 18:29	General View	0	Load JPG	•
Do	cumentation		1 pe	r page ▼	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnai	Prin
1	26/12/18 09:54	SJE AGREE LKK	0		
2	26/12/18 09:54	OI ACCIDENT REPORT	0		
3	26/12/18 09:54	TP SJE8421X E-REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18023110/UTD3S2

Date:

04/01/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

MSD/VMS/18-997193

Claimant Vehicle

SJE8421X

Insured Vehicle No: FBJ8938R

Date of Loss:

No:

21/12/2018

Nature of Claim:

TP

Claim No: MSC/V/18-001634

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJE8421X

Make & Model:

HONDA FIT, 1.3 G (A)

09/05/2008 (Man. Year: 2008)

Chassis No: Odometer:

Engine No:

L13A4049559 GE61044127

120464 km

Reg. Date: Colour:

Blue

1339 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Engine Capacity:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

195/55R15

Rear Tyre Size:

195/55R15

Front Left Side: Front Right Side: Dunlop 6 mm Dunlop 6 mm Rear Left Side:

Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,767.50	2,332.96	4,434.54	65.53
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,370.00	1,690.00	680.00	28.69
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
1	Calculated Gross Total (S\$)	9,137.50	4,022.96	5,114.54	55.97
	Approved Total (Overridden) (S\$)		3,200.00		
	Nett Amount (S\$)	9,137.50	3,200.00	5,937.50	64.98

INSPECTION

Date of Assignment:

Date Inspected:

26/12/2018

27/12/2018 Inspected At:

3 Motorwerkz Concepts Pte Ltd (HQ)

25 Kaki Bukit Road 4, Synergy @ KB #01-40

Singapore 417800

Estimated Period of Repair:

5.0 days

MARCUS CHUA Adjuster:

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other flability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 04 Jan 2019)

Parts:

144

HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJE8421X)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Badly Dented	1,077.00 F	*785.30 FL
2	2	*REAR BOOT LID HINGES	Not Necessary	90.20 F	*-FL
3	1	*REAR BOOT LID FIT LOGO	Necessary	40.00 F	*40.00 FL
4	1	*REAR BOOT LID EMBLEM LOGO	Not Necessary	95.00 F	*-FL
5	1	*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*-FL
6	2	*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	85.40 F	*-FL
7	1	*REAR BOOT LID INNER LOCK	Dented / Shorted	186.30 F	*109.60 FL
В	1	*REAR BOOT LID INNER RUBBER	Twisted	128.10 F	*128.10 FL
9	1	*REAR BOOT LID INNER TRIM BOARD	Deformed / Cracked	296.70 F	*245.30 FL
10	1	*REAR BOOT LID INNER LOCK SIDE COVER	Not Necessary	28.50 F	*-FL
11	1	*REAR BOOT LID WINDSCREEN SOLAR FILM	Not Necessary	200.00 F	*- FL
12	1	*REAR TAIL LAMP	O/s Cracked	676.20 F	*285.40 FL
13	2	*REAR TAIL LAMP PANEL	Repair	256.80 F	*- FL
14	2	*REAR TAIL LAMP INNER PANEL	Repair	220.00 F	*- FL
15	4	*REAR TAIL LAMP CLIPS	Not Necessary	26.00 F	*- FL
16	1	*REAR BUMPER	Distorted	853.00 F	*486.30 FL
17	1	*REAR BUMPER SIDE BRACKET	O/s Bent	117.40 F	*28.50 FL
18	1	*REAR BUMPER CLIPS 8pcs	Necessary	40.00 F	*35.00 FL
19	1	*REAR BUMPER TOWING COVER	Torn	38.10 F	*28.50 FL
20	2	*REAR BUMPER MUD SHIELD	Not Necessary	108.20 F	*- FL
21	8	*REAR BUMPER MUD SHIELD CLIPS	Not Necessary	40.00 F	*- FL
22	1	*REAR END PANEL	Dented	492.90 F	*296.60 FL
23	1	*REAR END PANEL TOP GARNISH	Twisted	110.10 F	*110.10 FL
24	1	*REAR SPARE TIRE PANEL TOP COVER	Not Necessary	260.40 F	*- FL
25	1	*REAR EXHAUST	Repair	605.00 F	*-FL
26	1	*REAR EXHAUST CHROME PIPE	Not Necessary	160.00 F	*-FL
27	1	*REAR BOOT LID WINDSCREEN SEAL	Necessary	136.20 FS	*30.00 FS
28	1	*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
29	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
	anchise part. S=Spc	Nett. L=ListItemDisc.	-		100000000000000000000000000000000000000
		- List Item Discoun	Sub Total (S\$) t on L Items 0.00/20.00% (S\$)	6,767.50 0.00	2,848.70 515.74
			Total Parts (S\$)	6,767.50	2,332.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recom	men	hah	12	hour
RECUIII	HIGH	ucu	La	Doui

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & RE-FIX CUSHION.	New	120.00	80.00
2	TO REMOVE & RE-FIX REVERSE SENSOR.	New	100.00	50.00
3	TO REMOVE & RE-FIX REAR WINDSCREEN.	New	120.00	120.00
4	TO REMOVE & RE-FIX REAR EXHAUST.	New	250.00	60.00
5	TO CHECK WIRING SYSTEM.	New	60.00	20.00
6	TUFF KOTE.	New	120.00	60.00
7	TOWING CHARGES.	New	0.00	0.00
8	PANEL BEATING.	New	800.00	600.00
9	SPRAY PAINTING.	New	800.00	700.00
		Gross Labour Cost (S\$)	2,370.00	1,690.00
C- ;-	Report was uns	submitted during this print-out.		

< END OF ESTIMATES >