

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

Attn :Bee Kok

VEHICLE NO : SHB 3431P (Supplementary)



DATE : 12/27/2018 12:27

MAKE :

TEL : 6542 5119

MODEL : Hyundai i40

Fax : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Windscreen Moulding Hec			\$ 113.30 ✓
	Front Windscreen Pillar Outer(LH/RH) N/S Denton	O/S N/S	372.75	\$ 1,745.50 ✓
			698.20	
	SUB TOTAL			\$ 1,858.80
	Less 20%			\$ 371.76
	DISCOUNTED TOTAL			\$ 1,487.04
	Front Windscreen Sealant Hec		46.00	\$ 46.00 ✓
				\$ 46.00
	Labour Charge			
	Remove/Refix Rear Windscreen Glass		80.00	\$ 120.00 80/-
	TOTAL LABOUR			\$ 120.00
	ESTIMATE TOTAL			\$ 1,653.04
	27/12/2018			824.20
				
	LKK Auto			
				30800.28
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				