

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 28 Dec 2018

**Preliminary Advice**

Vehicle No	: SGW8438P	Accident Date	: 20/12/2018
Make	: MAZDA M6	Policy No.	: D18MTPV01012744
Assignment Date	: 27/12/2018	Excess	: S\$0.00
Date of Inspection	: 28/12/2018	Est. Duration of Repair	: 2.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear n/s door and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,092.50
Revised Amount	:S\$	812.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	812.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	45,081.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,919.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Some of the parts,pending for parts prices.