



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
AUTOBAY @ KAKI BUKIT
No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883
TELEPHONE: 6748 2795 FAX: 6747 2373
Registration No.: 203165/00D

LKK

DATE: 29/12/2018 OUR REF: UAPL1170
REPAIR ESTIMATE TO THE MERCEDES BENZ C180 NO: SLL9679C
NETT ITEM:-

1 FRONT BUMPER ASSY / Cut
1 FRONT BUMPER INNER SPONGE / CRA
1 FRONT BUMPER REINFORCEMENT X
1 FRONT R/H BUMPER REINFORCEMENT STAY X
1 FRONT BUMPER LOWER COVER GARNISH X
1 FRONT R/H BUMPER FOG LAMP / BR / RL
1 FRONT R/H BUMPER SIDE RETAINER /
1 FRONT R/H BUMPER SIDE RETAINER HOLDER
1 FRONT R/H HEADLAMP ASSY / Cut
1 FRONT R/H FENDER ASSY X / Repair
1 FRONT R/H FENDER INNER SHIELD (FRONT) X
1 FRONT R/H SHOCK ABSORBER X
1 FRONT R/H SHOCK ABSORBER MOUNTING X
1 FRONT R/H KNUCKLE ARM X
1 FRONT R/H KNUCKLE BEARING / MC
1 FRONT R/H LINKAGE X
1 FRONT R/H LOWER ARM X
1 FRONT R/H STAY ARM X / BT

LESS 10 %.....

SPECIAL NETT:-

1 FRONT R/H SPORT WHEEL / Cut
1 FRONT R/H TIRE X

LABOUR CHARGES:-

TO DISM/REWIRE DAMAGED PORTION
TO SPARY UNDER COATING IN REPAIR
TO DISM/RENEW FRONT R/H UNDERCARRIER
TO COMPLETE WHEEL ALIGNMENT.
TO PANEL BEAT DAMAGED PORTION & RENEW PARTS
TO PUTTY AND RESPRAY DAMAGED PROTION

\$	1,728.00	1315.32
\$	212.00	155
\$	646.00	
\$	118.00	
\$	28.00	
\$	356.00	290
\$	35.20	
\$	76.00	
\$	1,476.00	/
\$	583.00	
\$	197.00	
\$	886.00	
\$	235.00	
\$	1,123.00	
\$	324.00	270 3860.52
\$	158.00	
\$	687.00	
\$	423.00	
\$	9,291.20	3544.52
\$	929.12	
\$	10,220.32	3187.36
\$	900.00	500
\$	350.00	
\$	120.00	30
\$	100.00	X
\$	350.00	50
\$	120.00	60
\$	1,000.00	200
\$	1,000.00	400. 740
\$	14,160.32	

3474.46

4714.46

4427.36

20%: 2500 3750

4 Days.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: