

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 21/12/2018

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ1743B

Reg.date : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, RADIATOR GRILLE, REINFORCEMENT, HEADLAMPS, WING MIRROR, RADIATOR, CONDENSER, BONNET, LHF FENDER, RH FENDER, ETC	0	4500.00	0		4,500.00 S	3600
800	TO PUTTY SPRAYPAINT ON FRT BUMPER, BONNET, LHF FENDER, RH FENDER, ETC	0	2400.00	0		2,400.00 S	2000
287	TO REPLACE DASHBOARD, DRIVER AIRBAG, PASSENGER AIRBAG, AIRBAG MODULE, ETC	0	2640.00	0		2,640.00 S	2200
287	TO REPLACE SEATBELTS IN VEHICLE	0	1760.00	0		1,760.00 S	1580
280	TO FOCUS HEADLAMP	0	110.00	0		110.00 S	
802	TO VACUUM & TOP UP A/C GAS	0	600.00	0		600.00 S	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	330.00	0		330.00 S	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL
Hp 90010068
15 days
P/P
28/12/18 @ 1100hrs
EXCESS: 500
Revert
Revy b & paint

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 21/12/2018

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ1743B

Reg.date. : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
R06	FRT NUMBER PLATE & HOLDER <i>3A/</i>		0	60.00	0		60.00	S
	BUMPER FRT M4H GT LI <i>70RN/</i>	1.0	EA	699.10			699.10	S
	COLLECTION ?	1.0	EA	78.10			78.10	S
	BUMPER FRT CENTER SU <i>CA/</i>	1.0	EA	166.30			166.30	S
	LOWER GRILLE <i>at/</i>	1.0	EA	309.60			309.60	S
	BUMPER FRT SPOILER M <i>at/</i>	1.0	EA	193.70			193.70	S
	BUMPER LOWER COVER ?	1.0	EA	121.50			121.50	S
	AIR INNER INTAKE GUI <i>DE/</i>	1.0	EA	126.80			126.80	S
	AIR INNER INTAKE GUI <i>DE/</i>	1.0	EA	244.70			244.70	S
	GUIDE AIR S <i>DE/</i>	1.0	EA	35.30			35.30	S
	AIR INTAKE GUIDE FRT <i>DE/</i>	1.0	EA	279.30			279.30	S
	BUMPER FRT GRILLE CH ?	1.0	EA	281.60			281.60	S
	BUMPER FRT GRILLE M4 ?	1.0	EA	649.40			649.40	S
	BUMPER FRT TOP GRILL <i>CA/</i>	1.0	EA	321.20			321.20	S
	R620367005R/BUMPER T ?	1.0	EA	874.50			874.50	S
	REINFORCEMENT FRT <i>BT/</i>	1.0	EA	653.80			653.80	S
	INNER AIR GUIDE PANE ?	1.0	EA	790.20			790.20	S

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 21/12/2018

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ1743B

Reg.date. : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HEADLAMP LHF W/XENON <i>Blo/</i>	1.0 EA	1264.40			1,264.40	S
	HEADLAMP RHF W/XENON <i>CR/</i>	1.0 EA	1264.40			1,264.40	S
	BULB HEADLAMP R26 DI ?	2.0 EA	219.00			438.00	S
	WING MIRROR SIGN LAM X	1.0 EA	296.80			296.80	S
	WING MIRROR SIGN LAM X	1.0 EA	229.00			229.00	S
	AIR COOLER GUIDE AIR ?	1.0 EA	35.30			35.30	S
	A/C CONDENSER COWING ?	1.0 EA	74.60			74.60	S
	A./C CONDENSER GS4 ?	1.0 EA	1274.60			1,274.60	S
	RADIATOR ASSY M4S M4 ?	1.0 EA	580.80			580.80	S
	AIR COOLER ASSY- GS4 ?	1.0 EA	689.80			689.80	S
	FAN MOTOR ?	1.0 EA	706.70			706.70	S
	LOGO FRT GRILLE GS4 <i>nu/</i>	1.0 EA	125.90			125.90	S
	BONNET <i>ht/</i>	1.0 EA	918.10			918.10	S
	BONNET HINGE LH ?	1.0 EA	175.30			175.30	S
	BONNET HINGE RH ?	1.0 EA	175.30			175.30	S
	BONNET LOCK ?	1.0 EA	139.90			139.90	S
	FENDER FRT LH M4S <i>TURN/</i>	1.0 EA	386.40			386.40	S

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 4

Inv.date. : 21/12/2018

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ1743B

Reg.date. : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FENDER FRT RH M4S ?	1.0 EA	386.40			386.40	S
	EQUERRE G F ?	1.0 EA	59.80			59.80	S
	BRACKET FENDER LH OU <i>neu</i> /	1.0 EA	87.70			87.70	S
	BRAS G PRT ?	1.0 EA	169.30			169.30	S
	FENDER BRACKET FRT R ?	1.0 EA	87.70			87.70	S
	EQUERRE D F ?	1.0 EA	61.40			61.40	S
	DASHBOARD, M4GT <i>Turn</i> /	1.0 EA	4239.30			4,239.30	S
	AIRBAG PASSENGERS <i>Act</i> /	1.0 EA	887.30			887.30	S
	E STEERING AIRBAG <i>Act</i> /	1.0 EA	699.10			699.10	S
	AIRBAG COMPUTER <i>Act</i> /	1.0 EA	1213.90			1,213.90	S
	BODY PANEL SEALANT X <i>neu</i> /	1.0 EA	942.20			942.20	S
	ADHESIVE SEALER FL2 <i>neu</i> /	1.0 EA	549.10			549.10	S
	SEATBELT RHF <i>Act</i> /	1.0 EA	986.20			986.20	S
	SEATBELT LHF <i>Act</i> /	1.0 EA	986.20			986.20	S
	SEATBELT RHR LHR <i>Act</i> /	2.0 EA	986.20			1,972.40	S
	SEATBELT CTR <i>Act</i> /	1.0 EA	986.20			986.20	S

Gross Total. 41,314.60

Labour Total 12,400.00
 Parts Total 28,914.60
 Package Total 0.00

Net..... 41,314.60
 GST @ 7.0% 2,892.02
 Total..... 44,206.60
 Paid..... 0.00
 Please Pay.. 44,206.60

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated