

ASS. REC. BY:

REF:

es/00518023159/RLS d3ub

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person): Joel Goh

of

EQI

Date/Time:

26/12/18 @ 5:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLQ 1743B

Insured:

at Workshop m/s

Wearnes Automotive

Tel:

9129 4556

of

249 Alexandra Road

Policy No:

Claim No:

DM18H003474-JG

Sum Insured:

Excess: \$500.00 (no waiver)

Make of Veh:

(Client's Record)

D.O.A.

18/12/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

27/12/18 @ 9:21am

Person Contacted:

Michelle

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 1743B - X
31/12/18	@ 10:28 am. revised RA & authorize repair & requested to Joel via email.
4/1/19	@ 11:58 am. authorize approved by Joel Goh via email.
4/1/19	@ 13:20 pm. revert authorize repair to Michelle (operator) via email.


Ream

REF:

0399N

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SLQ 1743B**
 at Workshop m/s: **WERNES**
 of: **249, MEGAN 249 R7**
 Insured: **EQ**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **500**
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **94K**
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / **REV** / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLQ 1743B** Yr Regn: **2017 Jun**
 Type: **M** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **RENAULT MEGANE 1.5** CC: **1461**
 Colour: **BLACK** A/C: Insured / Std / NI / NA
 Sp Reading: **28177** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **VF 1RF B00356852573**
 Gen. Cond: Good / **Fair** / Poor / Burnt
 Steering: **Order** / Jammed / Leaked / Burnt or
 Brake: **Order** / Jammed / Leaked / Burnt or
 Modi: **Nil** / R/Rim / STD A/Rim or
 Tyre Size: F: **205/50R17**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / **MIC** / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **18/12/18** D.O.I: **28/12/18**
 Survey held at: **WERNES**
 Des. of Damages: **FR** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
25/01/19 @ 09:35 a.m. Supplementary requested to **but** **Goh** via email.

07/05/19 Confirmed P/P \$ **43,272.81** @ 15 days with Resul
 (\$ **9,946.69** Red - 15%)

RECEIVED 06 MAY 2019

8/5/2019

Date/Time, File Pass to? **08/05/19**
 1) **Typist**
 Date/Time, File Return to?
 2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: **15**
 Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

1) G + R: \$

2) Photos

3) Others

TOTAL

300

300

Report Format :

Lump Sum / I.B.I: (\$ **43,272.81** P/P)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0399N

Vehicle Details

Vehicle No.:	SLQ1743B
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2018
Vehicle Make:	RENAULT
Vehicle Model:	MEGANE GT LINE 1.5DCI AT EU6
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	K9KG657D045662
Chassis No.:	VF1RFB00356852573
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$22,815.00
Original Registration Date:	29 Jun 2017
First Registration Date:	29 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2027
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	28 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$36,357.00
Total Rebate Amount:	\$40,107.00

The information contained herein is correct as at 31 Dec 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 8 May 2019 3:45 PM
To: 'Michelle Ong Siew Bee'
Cc: Rasul (LKKAuto); SUR
Subject: RE: Final Bill for SLQ1743B

Dear Michelle,

Confirmed final fig \$43,272.81 (part by part) @ 15 days of repairs before excess \$ 500/- & GST.

Final invoice and all supporting documents sent over to **EQ Insurance Company Ltd.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michelle Ong Siew Bee [mailto:michelle.ong@wearnes.com]
Sent: Friday, 26 April 2019 3:03 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; 'sur@lkkauto.com' <sur@lkkauto.com>
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: Final Bill for SLQ1743B
Importance: High

Dear Shirley,

Please find attached.

Best regards,

Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
249 Alexandra Road Singapore 159103
M (65) 9129 4556 F (65) 6264 7137
www.wearnes.com michelle.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Michelle Ong Siew Bee
Sent: Tuesday, April 23, 2019 6:51 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>; 'sur@lkkauto.com' <sur@lkkauto.com>

Shirley Hiew (LKK Auto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Wednesday, 30 January 2019 10:03 AM
To: Shirley Hiew (LKK Auto)
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Dear Shirley

Please proceed to authorize this claim up to S\$46,817.80.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, January 25, 2019 9:55 AM
To: Joel Goh
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Dear Joel,

Enclosed preliminary revised of vehicle SLQ 1743B
Date of survey: 28/12/2018
Number of days : 15 days

We have authorise repair.

Kindly let us have your approval of supplementary.

Thank you.
Best Regards,

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 8 May 2019 10:47 AM
To: 'Joel Goh'
Cc: 'SUR'; 'Admin-D (LKKAuto)'; 'assignments'
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Hi Joel,

As spoken, we will submit our file accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 8 May 2019 10:30 AM
To: 'Joel Goh' <joel.goh@eqinsurance.com.sg>
Cc: 'SUR' <sur@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'assignments' <assignments@lkkauto.com>
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Dear Joel,

Enclosed preliminary revised of vehicle SLQ 1743B
Date of survey: 28/12/2018
Number of days : 15 days

We have authorise repair.

Kindly let us have your approval of supplementary.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 25 January 2019 9:55 AM
To: 'Joel Goh'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)
Attachments: SUPPLEMENTARY.pdf; SLQ 1743B - Preli Advise.pdf; LKK RESURVEY PHOTO.pdf

Dear Joel,

Enclosed preliminary revised of vehicle SLQ 1743B
Date of survey: 28/12/2018
Number of days : 15 days

We have authorise repair.

Kindly let us have your approval of supplementary.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Friday, 4 January 2019 11:58 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Dear Shirley

Please proceed to authorize this OD up to \$38,828.80.

Best Regards,

Joel Goh
Executive | Claims


EQ Insurance Company Limited

Shirley Hiew (LKK Auto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Friday, 4 January 2019 11:58 AM
To: Shirley Hiew (LKK Auto)
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Dear Shirley

Please proceed to authorize this OD up to \$38,828.80.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, December 31, 2018 10:28 AM
To: Joel Goh
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Dear Joel,

Enclosed preliminary revised of vehicle SLQ 1743B
Date of survey: 28/12/2018
Number of days : 15 days

We have Not authorise repair.

Kindly let us have your approval please.

Thank you.
Best Regards,
Shirley Hiew | Case Handler

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 31 December 2018 10:28 AM
To: 'Joel Goh'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)
Attachments: SLQ 1743B - Preli Advise.pdf

Dear Joel,

Enclosed preliminary revised of vehicle SLQ 1743B
Date of survey: 28/12/2018
Number of days : 15 days

We have Not authorise repair.

Kindly let us have your approval please.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 27 December 2018 1:52 PM
To: 'Joel Goh' <joel.goh@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 26 December 2018 5:37 PM
To: assignments
Subject: W: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)
Attachments: SLQ1743B.PDF

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Singapore 610051, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Wednesday, 26 December 2018 5:33 PM
To: Michelle Ong Siew Bee <michelle.ong@wearnes.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018 (DM18HO03474-JG)

Dear Michelle

We will assign LKK to conduct OD survey.

Dear LKK

Please assist on this OD survey:
Excess: \$500.00 (no waiver)
Survey and revert

Best Regards,

Joel Goh
Executive - Claims



EQ Insurance Company Limited

5 Maxwell Road #05-01 MND Complex Singapore 069110
tel 65 6500 6772 | fax 65 6223 4190

www.eqinsurance.com.sg

A Member of City&Seaview

Privileged/Confidential

may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Michelle Ong Siew Bee [mailto:michelle.ong@wearnes.com]
Sent: Friday, December 21, 2018 6:18 PM
To: EQI PRS
Subject: OD Claim - Our Ref: SLQ1743B ; Your Insured SLQ1743B DOA 18/12/2018
Importance: High

Dear Sirs,

We refer to the above matter.
Attached for OD Claim.
Kindly revert asap.

Best regards,
Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
1101 Singapore 159103
Tel: (65) 6254 7137
michelle.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 4 January 2019 1:20 PM
To: 'Michelle Ong Siew Bee'
Cc: 'Paul Ong Qing Yong'; 'Richmond Ho'; SUR
Subject: SLQ 1743B OD (EQI)

Dear Michelle,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 1743B (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DMH18HO03474-JG

Date: 08 May 2019

Our Ref: CS/EQ118023159/R1sd3

The Motor Claims Department
EQ INSURANCE COMPANY LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 1743B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/12/2018 at the premises of M/s Wearnes Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>53,219.50</u> . (Inclusive Supp 1+2)
Revised Estimate Amount	: S\$ <u>43,272.81</u> . (Inclusive Supp 1+2)
"Check" Items Amount	: S\$ _____ .
Total	: S\$ <u>43,272.81</u> .
Market Value	: S\$ <u>94,000.00</u> .
LTA Reimbursement Value	: S\$ <u>40,107.00</u> .
Nett Value	: S\$ <u>53,893.00</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages Consistent.

Repair cost economical, we have authorize repair.

Kindly approve of the supplementary 2, amount is \$ 3,524.31

Repair days: 15 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE L, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DMH18HO03474-JG

Date: 25 January 2019

Our Ref: CS/EQ18023159/R1sd3

The Motor Claims Department
EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 1743B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/12/2018 at the premises of M/s Wearnes Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 49,303.60	(Inclusive Supplementary)
Revised Estimate Amount	: S\$ 38,967.60	(Inclusive Supplementary)
"Check" Items Amount	: S\$ 7,850.20	
Total	: S\$ 46,817.80	
Market Value	: S\$ 94,000.00	
LTA Reimbursement Value	: S\$ 40,107.00	
Nett Value	: S\$ 53,893.00	

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages Consistent.

Repair cost economical, we have authorize repair.

Kindly approve of supplementary amount is \$ 7,989.00

Repair days: 15 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DMH18HO03474-JG

Date: 31 December 2018

Our Ref: CS/EQI18023159/R1sd3

The Motor Claims Department
EQ INSURANCE COMPANY LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 1743B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/12/2018 at the premises of M/s Wearnes Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 41,314.60
Revised Estimate Amount	: S\$ 30,978.60
"Check" Items Amount	: S\$ 7,850.20
Total	: S\$ 38,828.80
Market Value	: S\$ 94,000.00
LTA Reimbursement Value	: S\$ 40,107.00
Nett Value	: S\$ 53,893.00

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages Consistent.

Repair cost economical, we have not authorise repair

Repair days: 15 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2018 17:34
Date Of Accident	18/12/2018 12:35
Exact Location Of Accident	EXIT OF AYE ALEXANDRA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ1743B
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67341222

Vehicle Particulars

Manufacturer	RENAULT
Model	MEGANE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	YEO KHUANG MENG, GAVIN
NRIC No	S7310352E
Date Of Birth	23/03/1973
Occupation	OUTDOOR
Date Of Driving Pass	04/12/2003
Driving Experience	15 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97306323
Fax Number	
Contact Number	
Email Address	YGAVIN2000@YAHOO.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was exiting AYE AT ALEXANDRA EXIT suddenly vehicle GX1934P jammed brake ahead of me and I was not able to stop my vehicle

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL UPLOAD TO MERIMEN ONCE INSURED SEND
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX1934P
Vehicle Make/Model/Colour	TOYOTA DYNA 150 D WHITE
Details Of Properties	N.A
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NA
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please input correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded to the Insurers of the GIA Records Management Centre established by the General Insurance Administration of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the claims end to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my solicitor and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";
 - (ii) all insurer(s) who have insured vehicles involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
Mohamed Saifullah S/O Syed
Masood
Witnessed by Reporting Centre
Representative

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was exiting AYE AT ALEXANDRA EXIT suddenly vehicle GX1934P jammed brake ahead of me and I was not able to stop my vehicle SLQ1743B on time and collided onto vehicle GX1934P rear. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

18 December 2018 at 4:20 PM

Date/Time

18 December 2018 at 4:20 PM

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

**PRIVATE CAR
Comprehensive**

Certificate No. : DMPPHQ18-003338

1. Index Mark and Registration Number of Vehicles

SLQ1743B

2. Name of Policyholder

Hitachi Capital Asia Pacific Pte Ltd

3. Effective Date of the Commencement of Insurance for the purpose of the Act

29/06/2018

4. Date of Expiry of Insurance

28/06/2019

5. Person or Classes of persons entitled to drive*

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his permission

Form: MX2

Excess:

Named Driver:

S\$500.00

Unnamed Drivers Add:

S\$2,000.00

YEID Additional:

S\$3,000.00

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitation as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover :

(a) use for hire or reward

(b) use for racing, pace-making, reliability trials or speed testing

(c) use for the carriage of goods (other than samples) in connection with any trade or business

(d) use for any purpose in connection with the Motor Trade

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Hire Purchase :

A000298/Tong Hin Insurance Agency Pte Ltd

Date of Issue : 23/05/2018 08:59



Authorised Signatory
EQ Insurance Company Limited

Exp No. : DMPPHQ17-003573

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S7310352E**

Name: **YEO KHUANG MENG, GAVIN**

Birth Date: **23 Mar 1973**

Issue Date: **04 Dec 2003**

001039568



SINGAPORE ARMP

IDENTITY CARD

Name: **YEO KHUANG MENG, GAVIN**

NRIC No: **57310352E**





This card is the property of the Singapore Armed Forces. Any person finding this card is requested to forward it without delay to Central Mailroom Base or any Police Station.

97306323

68336146 - Kelvin Hutechi

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **04 Dec 2003**

NP 426A

Licence No: **S7310352E**



NRIC No/Class: **S7310352E / PINK**

Race: **CHINESE**

Place: **CHINESE**

Group: **O+**

Date of Birth: **23031973**

Country of Birth: **SINGAPORE**

Sex: **M**

Service Status: **REGULAR**

Military Rank: **STATUS**

Military Expert: **M04715**

ADDRESS: **APT BLK 289G BLKT BATOK STREET 25 #05-114 SINGAPORE 656289**

DATE: **19.07.2011**

S7310352E



CardCard

Use Expiry on Card Card

Serial & Card No: **11162010195000**

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC
 Hitachi Capital Asia Pacific Pte Ltd
 Attn: Mr Ang
 484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 1
 Inv.date. : 21/12/2018
 WIP No. : 44407
 Veh.In/Out: 18/12/2018
 *Tel.No. : Mobile: 94564904
 Reg.No. : SLQ1743B
 Reg.date : 29/06/2017
 Mileage : 0
 Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, RADIATOR GRILLE, REINFORCEMENT, HEADLAMPS, WING MIRROR, RADIATOR, CONDENSER, BONNET, LHF FENDER, RHF FENDER, ETC	0	4500.00	0		4,500.00 S 3600	
800	TO PUTTY SPRAYPAINT ON FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, ETC	0	2400.00	0		2,400.00 S 2000	
287	TO REPLACE DASHBOARD, DRIVER AIRBAG, PASSENGER AIRBAG, AIRBAG MODULE, ETC	0	2640.00	0		2,640.00 S 2200	
287	TO REPLACE SEATBELTS IN VEHICLE	0	1760.00	0		1,760.00 S 1580	
280	TO FOCUS HEADLAMP	0	110.00	0		110.00 S	
802	TO VACUUM & TOP UP A/C GAS	0	600.00	0		600.00 S	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	330.00	0		330.00 S	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Handwritten notes:
 Rasul
 Hp 90010068
 15 days
 P/P
 28/12/18 @ 1100h
 EXCESS: 500
 Revert
 Reey b4 part

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 21/12/2018

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ1743B

Reg.date. : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

R06	FRT NUMBER PLATE & HOLDER <i>TH/</i>	0	60.00	0		60.00	S
	BUMPER FRT M4H GT LI <i>7020/</i>	1.0 EA	699.10			699.10	S <i>629.19</i>
	COLLECTION <i>? CRA/</i>	1.0 EA	78.10			78.10	S <i>75.80 70 29</i>
	BUMPER FRT CENTER SU <i>CA/</i>	1.0 EA	166.30			166.30	S <i>149.67</i>
	LOWER GRILLE <i>cut</i>	1.0 EA	309.60	<i>351.30</i>		309.60	S <i>317.07 P</i>
	BUMPER FRT SPOILER <i>H cut</i>	1.0 EA	193.70			193.70	S <i>174.33</i>
	BUMPER LOWER COVER <i>? CRA/ Xme</i>	1.0 EA	121.50			121.50	S
	AIR INNER INTAKE GUI <i>cut suc</i>	1.0 EA	126.80			126.80	S
	AIR INNER INTAKE GUI <i>cut</i>	1.0 EA	244.70			244.70	S <i>220.23</i>
	GUIDE AIR S <i>26-</i>	1.0 EA	35.30			35.30	S <i>31.77</i>
	AIR INTAKE GUIDE FRT <i>DE-</i>	1.0 EA	279.30			279.30	S <i>251.37</i>
	BUMPER FRT GRILLE CH <i>? DE/</i>	1.0 EA	281.60			281.60	S <i>253.44</i>
	BUMPER FRT GRILLE M4 <i>? DE/</i>	1.0 EA	649.40			649.40	S <i>584.46</i>
	BUMPER FRT TOP GRILL <i>CRA-</i>	1.0 EA	321.20			321.20	S <i>289.08</i>
	R620367005R/BUMPER T <i>? Xme</i>	1.0 EA	874.50			874.50	S
	REINFORCEMENT FRT <i>BI</i>	1.0 EA	653.80			653.80	S <i>578.42</i>
	INNER AIR GUIDE PANE <i>? DE-</i>	1.0 EA	790.20			790.20	S <i>711.18</i>

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 21/12/2018

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ1743B

Reg.date. : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HEADLAMP LHF W/XENON <i>B&P</i>	1.0 EA	1264.40			1,264.40 S	1137.96
	HEADLAMP RHF W/XENON <i>CRA</i>	1.0 EA	1264.40			1,264.40 S	1137.96
	BULB HEADLAMP R26 DI <i>? XSM</i>	2.0 EA	219.00			438.00 S	
	WING MIRROR SIGN LAM <i>XSCA</i>	1.0 EA	296.80			296.80 S	✓
	WING MIRROR SIGN LAM <i>XSM</i>	1.0 EA	229.00			229.00 S	
	AIR COOLER GUIDE AIR <i>? CRA</i>	1.0 EA	35.30			35.30 S	✓31.77
	A/C CONDENSER COWING <i>? CRA</i>	1.0 EA	74.60			74.60 S	✓67.14
	A./C CONDENSER GS4 <i>? MT</i>	1.0 EA	1274.60			1,274.60 S	✓1147.14
	RADIATOR ASSY M4S M4 <i>? HT</i>	1.0 EA	580.80			580.80 S	✓522.72
	AIR COOLER ASSY- GS4 <i>? MT</i>	1.0 EA	689.80			689.80 S	✓620.82
	FAN MOTOR <i>? XSM</i>	1.0 EA	706.70			706.70 S	
	LOGO FRT GRILLE GS4 <i>MT</i>	1.0 EA	125.90			125.90 S	113.31
	BONNET <i>HT</i>	1.0 EA	918.10			918.10 S	826.29
	BONNET HINGE LH <i>? MT</i>	1.0 EA	175.30			175.30 S	✓157.77
	BONNET HINGE RH <i>? HT</i>	1.0 EA	175.30			175.30 S	✓157.77
	BONNET LOCK <i>? XSM</i>	1.0 EA	139.90			139.90 S	
	FENDER FRT LH M4S <i>TURN</i>	1.0 EA	386.40			386.40 S	347.76

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC
 Hitachi Capital Asia Pacific Pte Ltd
 Attn: Mr Ang
 484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 4
 Inv.date. : 21/12/2018
 WIP No. : 44407
 Veh.In/Out: 18/12/2018
 *Tel.No. : Mobile: 94564904
 Reg.No. : SLQ1743B
 Reg.date. : 29/06/2017
 Mileage : 0
 Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	FENDER FRT RH M4S ? X repair	1.0 EA	386.40			386.40 S	
	EQUERRE G F ? X suc	1.0 EA	59.80			59.80 S	
	BRACKET FENDER LH OU ne	1.0 EA	87.70			87.70 S	78.93
	BRAS G PRT ? X suc	1.0 EA	169.30			169.30 S	
	FENDER BRACKET FRT R ? X suc	1.0 EA	87.70			87.70 S	
	EQUERRE D F ? X suc	1.0 EA	61.40			61.40 S	75.40
	DASHBOARD, M4GT Turn	1.0 EA	4239.30			4,239.30 S	3715.37
	AIRBAG PASSENGERS Act	1.0 EA	887.30			887.30 S	798.57
	E STEERING AIRBAG Act	1.0 EA	699.10			699.10 S	629.19
	AIRBAG COMPUTER Act	1.0 EA	1213.90			1,213.90 S	1092.51
	BODY PANEL SEALANT X ne	1.0 EA	942.20			942.20 S	843.28
	ADHESIVE SEALER FL2 ne	1.0 EA	549.10			549.10 S	494.19
	SEATBELT RHF Act	1.0 EA	986.20			986.20 S	887.58
	SEATBELT LHF Act	1.0 EA	986.20			986.20 S	887.58
	SEATBELT RHR LHR Act	2.0 EA	986.20			1,972.40 S	1725.16
	SEATBELT CTR Act	1.0 EA	986.20			986.20 S	887.58

Gross Total. 41,314.60

Labour Total 12,400.00
 Parts Total 28,914.60
 Package Total 0.00

Net..... 41,314.60
 GST @ 7.0% 2,892.02
 Total..... 44,206.60
 Paid..... 0.00
 Please Pay.. 44,206.60

53219.50

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

53290.06

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M2B920628X

Inv.No. : B&P 0 Page 1

Inv.date : 17/01/2019

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ17438

Reg.date : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE BONNET COMPONENT, ENGINE COMPONENT, ETC	0	1350.00	0		1,350.00	S ✓
	LOWER FRT AIR INNER CA ✓	1.0 EA	126.80			126.80	S 114.12 A
	RENFORT CTL MTX ✓ SUC	1.0 EA	551.30	47.70		551.30	S 420.93 A
	BUMPER TOP GRILLE IN CA ✓	1.0 EA	874.50			874.50	S 787.05 A
	FOG LAMP MOULDING H4 son ✓	1.0 EA	221.90			221.90	S 199.71 A
	DEFLECTEUR CA ✓	1.0 EA	54.10			54.10	S 48.69 A
	RADIATOR GRILLE COVE CA ✓	1.0 EA	167.80			167.80	S 151.02 A
	FENDER BAR BRACKET S neu ✓	1.0 EA	29.10			29.10	S 26.19 A
	EQUERRE D F (Phon's lower bar clasp) CA ✓	1.0 EA	75.40			75.40	S 67.86 A
	FENDER CLIP C3 neu ✓	10.0 EA	10.70			107.00	S 96.30 A
	BONNET INSULATOR DE ✓	1.0 EA	200.30			200.30	S 170.27 A
	INSULATOR CLIP H2 neu ✓	10.0 EA	3.80			38.00	S 34.20 A
	TUYAU COMPR BT ✓	1.0 EA	225.60			225.60	S 203.04 A
	SUPPORT CAL neu ✓	1.0 EA	45.70			45.70	S 41.13 A
	BAC BATTERI CA X SUC ✓	1.0 EA	282.20			282.20	S 255.78 A
	BOITIER ELC BT ✓	1.0 EA	2341.10			2,341.10	S 2106.99 A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

GST Reg.No:M2B92062BX

Inv.No. . : B&P 0 Page 2

Inv.date. : 17/01/2019

WIP No. . : 44407

Veh.In/Out: 18/12/2018

*Tel.No. . : Mobile: 94564904

Reg.No. . : SLQ1743B

Reg.date. : 29/06/2017

Mileage . : 0

Chassis No: VF1RFB00356852573

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

CONDUIT AIR	car	1.0 EA	39.60			39.60 S	35.64 A
PROTECTOR	car	1.0 EA	51.40			51.40 S	46.26 A
WING MIRROR SIGN LAM	car	1.0 EA	296.80			296.80 S	263.12 A
CONDUIT AIR	car	1.0 EA	354.70			354.70 S	319.23 A
CONDUIT AIR	car	1.0 EA	279.20			279.20 S	251.28 A
BONNET INNER HANDLE	car	1.0 EA	55.20			55.20 S	49.68 A
LABEL TOP PANEL	car	1.0 EA	11.70			11.70 S	10.53 A
R978184671R/STICKER	car	1.0 EA	22.40			22.40 S	20.16 A
RIVET BLACK, BUMPER	car	20.0 EA	6.70			134.00 S	120.60 A
SUPPORT CAL	car	1.0 EA	53.20			53.20 S	47.88 A

Gross Total. 7,989.00

Labour Total 1,350.00
Parts Total 6,639.00
Package Total 0.00

Net..... 7,989.00
GST @ 7.0% 559.23
Total..... 8,548.25
Paid..... 0.00
Please Pay.. 8,548.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

LKK Auto Consultants hence notify
the Repairs of the following:

- To survey before start of repair
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Notional Repaired" basis
- No illegal modifications to be allowed
- Supplementary items must be received and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY



SERVICE ESTIMATE

O - E00004 SL: EQ INSURANCE COMPANY LTD
EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17 00 TOWER CLOCK
MND COMPLEX
SINGAPORE 069110

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
Inv.date : 26/04/2017
WIP No. : 44407
Veh.In/Out: 18/12/2018 29/03/2019
*Tel.No. : 62239433
Reg.No. : SLQ17438
Reg.date : 29/06/2017
Mileage : 20,257
Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be
% Consultant : ACC
Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	R244280249R/TRAY-MUL	1.0 EA	282.20			282.20	S
	R620360534R/REINF-FR	1.0 EA	467.70			467.70	S
	FUSE BOX COVER	1.0 EA	148.20			148.20	S
	BONNET-SAFETY HOOK M	1.0 EA	103.10			103.10	S
	ROTARY SWITCH KJ	1.0 EA	818.10			818.10	S
	STEERING-WHEEL M4H	1.0 EA	1800.80			1,800.80	S
	PILLAR COVER	1.0 EA	147.90			147.90	S
	PILLAR COVER	1.0 EA	147.90			147.90	S

		Gross Total.	3,915.90
Labour Total	0.00	Net.....	3,915.90
Parts Total	3,915.90	GST @ 7.0%	274.11
Package Total	0.00	Total.....	4,190.01
		Paid.....	0.00
		Please Pay..	4,190.01

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - E00004	SL: EQ INSURANCE COMPANY LTD	GST Reg.No:M28920628X
EQ INSURANCE COMPANY LTD		Inv.No. : B&P 0 Page 1
5 MAXWELL ROAD		Inv.date. : 23/04/2019
#17-00 TOWER BLOCK		WIP No. : 44407
MND COMPLEX		Veh.In/Out: 18/12/2018 29/03/2019
SINGAPORE 069110		*Tel.No. : 62239433
		Reg.No. : SLQ1743B
Closed by : Michelle Ong Siew Be		Reg.date : 29/06/2017
Svc Consultant : ACC		Mileage .. : 20,257
Remarks : Hitachi Capital Asia		Chassis No: VF1RFB00356852573

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, RADIATOR GRILLE, REINFORCEMENT, HEADLAMPS, WING MIRROR, RADIATOR, CONDENSER, BONNET, LHF FENDER, RHF FENDER, ETC	0	3600.00	0		3,600.00	S ✓
800	TO PUTTY SPRAYPAINT ON FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, ETC	0	2000.00	0		2,000.00	S ✓
287	TO REPLACE DASHBOARD, DRIVER AIRBAG, PASSENGER AIRBAG, AIRBAG MODULE, ETC	0	2200.00	0		2,200.00	S ✓
287	TO REPLACE SEATBELTS IN VEHICLE	0	1540.00	0		1,540.00	S ✓
280	TO FOCUS HEADLAMP	0	110.00	0		110.00	S ✓
802	TO VACUUM & TOP UP A/C GAS	0	600.00	0		600.00	S ✓
280	TO CHECK WIRING INCLUDE	0	330.00	0		330.00	S ✓
	RESETTING OF ALL ELECTRICAL MODULES						

SERVICE ESTIMATE

O - E00004 SL: EQ INSURANCE COMPANY LTD EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 2 Inv.date. : 23/04/2019 WIP No. . : 44407 Veh.In/Out: 18/12/2018 29/03/2019 *Tel.No. . : 62239433 Reg.No. . : SLQ17438 Reg.date. : 29/06/2017 Mileage . : 20,257 Chassis No: VF1RFB00356852573
---	--

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
R06	FRT NUMBER PLATE & HOLDER	0	60.00	0		60.00	S ✓
802	TO REPLACE BONNET COMPONENT,	0	1350.00	0		1,350.00	S <i>supp</i> ✓
ENGINE COMPONENT, ETC							
EXC	Excess cost	0	500.00	0		-500.00	S ✓
	① BUMPER FRT M4H GT LI	1.0 EA	699.10	10		629.19	S ✓
	② BUMPER FRT CENTER SU	1.0 EA	166.30	10		149.67	S ✓
	④ LOWER GRILLE	1.0 EA	352.30	10		317.07	S ✓
	⑤ BUMPER FRT SPOILER M	1.0 EA	193.70	10		174.33	S ✓
	⑧ AIR INNER INTAKE GUI	1.0 EA	244.70	10		220.23	S ✓
	⑨ GUIDE AIR S	1.0 EA	35.30	10		31.77	S ✓
	⑩ AIR INTAKE GUIDE FRT	1.0 EA	279.30	10		251.37	S ✓
	⑫ BUMPER FRT TOP GRILL	1.0 EA	321.20	10		289.08	S ✓
	⑮ REINFORCEMENT FRT	1.0 EA	653.80	10		588.42	S ✓
	⑭ HEADLAMP LHF W/XENON	1.0 EA	1264.40	10		1,137.96	S ✓
	⑯ HEADLAMP RHF W/XENON	1.0 EA	1264.40	10		1,137.96	S ✓
	⑰ LOGO FRT GRILLE GS4	1.0 EA	125.90	10		113.31	S ✓
	⑳ FENDER FRT LH M4S	1.0 EA	386.40	10		347.76	S ✓

SERVICE ESTIMATE

0 - E00004 SL: EQ INSURANCE COMPANY LTD
 EQ INSURANCE COMPANY LTD GST Reg.No:M28920628X
 5 MAXWELL ROAD Inv.No. . : B&P 0 Page 3
 #17-00 TOWER BLOCK Inv.date. : 23/04/2019
 MND COMPLEX WIP No. . : 44407
 SINGAPORE 069110 Veh.In/Out: 18/12/2018 29/03/2019
 *Tel.No. . : 62239433
 Reg.No. . : SLQ1743B
 Reg.date. : 29/06/2017
 Mileage . : 20,257
 Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
36	BRACKET FENDER LH OU	1.0 EA	87.70	10		78.93	S ✓
40	DASHBOARD, M4GT	1.0 EA	4239.30	10		3,815.37	S ✓
42	*E* STEERING AIRBAG	1.0 EA	699.10	10		629.19	S ✓
43	AIRBAG COMPUTER	1.0 EA	1213.90	10		1,092.51	S ✓
44	SEATBELT RHF	1.0 EA	986.20	10		887.58	S
45	SEATBELT LHF	1.0 EA	986.20	10		887.58	S
46	SEATBELT RHR LHR	2.0 EA	986.20	10		1,775.16	S
47	SEATBELT CTR	1.0 EA	986.20	10		887.58	S
	LOWER FRT AIR INNER - supp ①	1.0 EA	126.80	10		114.12	S
16	INNER AIR GUIDE PANE	1.0 EA	790.20	10		711.18	S ✓
17	BUMPER TOP GRILLE IN	1.0 EA	874.50	10		787.05	S
2	COLLECTION	1.0 EA	78.10	10		70.29	S
	FOG LAMP MOULDING M4 - supp ④	1.0 EA	221.90	10		199.71	S
	DEFLECTEUR - supp ⑤	1.0 EA	54.10	10		48.69	S
	RADIATOR GRILLE COVE - supp ⑥	1.0 EA	167.80	10		151.02	S
12	BUMPER FRT GRILLE M4	1.0 EA	649.40	10		584.46	S
11	BUMPER FRT GRILLE CH	1.0 EA	281.60	10		253.44	S

SERVICE ESTIMATE

0 - E00004	SL: EQ INSURANCE COMPANY LTD	GST Reg.No:M28920628X
EQ INSURANCE COMPANY LTD		Inv.No. . : B&P 0 Page 4
5 MAXWELL ROAD		Inv.date. : 23/04/2019
#17-00 TOWER BLOCK		WIP No. . : 44407
MND COMPLEX		Veh.In/Out: 18/12/2018 29/03/2019
SINGAPORE 069110		*Tel.No. . : 62239433
		Reg.No. . : SLQ1743B
Closed by : Michelle Ong Siew Be		Reg.date. : 29/06/2017
Svc Consultant : ACC		Mileage . : 20,257
Remarks : Hitachi Capital Asia		Chassis No: VF1RFB00356852573

Op.No	Description	Mech Qty	Price Disc% Pkg	Amount G
	22 AIR COOLER GUIDE AIR	1.0 EA	35.30 10	31.77 S
	23 RADIATOR ASSY M4S M4	1.0 EA	580.80 10	522.72 S
	24 A./C CONDENSER GS4	1.0 EA	1274.60 10	1,147.14 S
	25 A/C CONDENSER COWING	1.0 EA	74.60 10	67.14 S
	26 AIR COOLER ASSY- GS4	1.0 EA	689.80 10	620.82 S
	FENDER BAR BRACKET S -supp ⑦	1.0 EA	29.10 10	26.19 S
	EQUERRE D F -supp ②	1.0 EA	75.40 10	67.86 S
	FENDER CLIP C3 -supp ②	10.0 EA	10.70 10	96.30 S
	27 BONNET HINGE RH	1.0 EA	175.30 10	157.77 S
	28 BONNET HINGE LH	1.0 EA	175.30 10	157.77 S
	BONNET INSULATOR -supp ⑩	1.0 EA	200.30 10	180.27 S
	INSULATOR CLIP M2 -supp ⑪	10.0 EA	3.80 10	34.20 S
	TUYAU COMPR -supp ⑫	1.0 EA	225.60 10	203.04 S
	SUPPORT CAL -supp ⑬	1.0 EA	45.70 10	41.13 S
	CONDUIT AIR -supp ⑭	1.0 EA	39.60 10	35.64 S
	PROTECTEUR -supp ⑮	1.0 EA	51.40 10	46.26 S
	WING MIRROR SIGN LAM -supp ⑯	1.0 EA	296.80 10	267.12 S

SERVICE ESTIMATE

O - E00004 SL: EQ INSURANCE COMPANY LTD
 EQ INSURANCE COMPANY LTD GST Reg.No:M28920628X
 5 MAXWELL ROAD Inv.No. : B&P 0 Page 5
 #17-00 TOWER BLOCK Inv.date. : 23/04/2019
 MND COMPLEX WIP No. : 44407
 SINGAPORE 069110 Veh.In/Out: 18/12/2018 29/03/2019
 *Tel.No. : 62239433
 Reg.No. : SLQ1743B
 Closed by : Michelle Ong Siew Be Reg.date. : 29/06/2017
 Svc Consultant : ACC Mileage : 20,257
 Remarks : Hitachi Capital Asia Chassis No: VF1RFB00356852573

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	CONDUIT AIR - supp ①	1.0 EA	354.70	10		319.23	S ✓
	CONDUIT AIR - supp ②	1.0 EA	279.20	10		251.28	S ✓
	BONNET INNER HANDLE - supp ③	1.0 EA	55.20	10		49.68	S ✓
	LABEL TOP PANEL - supp ④	1.0 EA	11.70	10		10.53	S ✓
	R978184671R/STICKER - supp ⑤	1.0 EA	22.40	10		20.16	S ✓
	RIVET BLACK, BUMPER - supp ⑥	20.0 EA	6.70	10		120.60	S ✓
	SUPPORT CAL - supp ⑦	1.0 EA	53.20	10		47.88	S ✓
	R237107343R/UNIT-ELE - supp ⑧	1.0 EA	2341.10	10		2,106.99	S ✓
	R244280249R/TRAY-MUL } supp	1.0 EA	282.20	10		253.98	S ✓
	R620360534R/REINF-FR }	1.0 EA	467.70	10		420.93	S ✓
⑨	R985252978R/AIRBAG P	1.0 EA	887.30	10		798.57	S ✓
	FUSE BOX COVER - supp	1.0 EA	148.20	10		133.38	S ✓
⑩	BONNET FRT M4H GTL	1.0 EA	918.10	10		826.29	S ✓
	BONNET-SAFETY HOOK M - supp	1.0 EA	103.10	10		92.79	S ✓
⑪	ADHESIVE SEALER FL2	1.0 EA	549.10	10		494.19	S ✓
⑫	BODY PANEL SEALANT X	1.0 EA	942.20	10		847.98	S ✓
	ROTARY SWITCH KJ - supp	1.0 EA	818.10	10		736.29	S ✓



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CS/EQ18023159/R1sd3e2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 21-05-2019	
			Code : EQI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SLQ 1743B
Policy No.		Coverage (\$)		0.00
Claim No.	DM18HO03474-JG	Excess (\$)		500.00
Assign From	JOEL GOH	Assign Date		26/12/2018
2. Vehicle Particulars & Condition				
Make & Model	RENAULT MEGANE 1.5	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1RFB00356852573	Colour	BLACK	
Odometer	28177	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R17	MICHELIN	6 mm	
L/H Front Tyre	205/50 R17	MICHELIN	6 mm	
R/H Rear Tyre	205/50 R17	MICHELIN	6 mm	
L/H Rear Tyre	205/50 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/12/2018	Inspection Date	28/12/2018	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935			
5a. Remarks				
A)THE MARKET VALUE IS S\$94,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 1743B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT NUMBER PLATE & HOLDER (SN)	BENT	60.00	60.00
1	BUMPER FRT M4H GT LI (SN)	TORN	699.10	629.19
1	COLLECTION (SN)	CRACKED	78.10	70.29
1	BUMPER FRT CENTER SU (SN)	CRACKED	166.30	149.67
1	LOWER GRILLE (SN)	CUT	352.30	317.07
1	BUMPER FRT SPOILER M (SN)	CUT	193.70	174.33
1	BUMPER LOWER COVER (SN)	SERVICEABLE	121.50	-
1	AIR INNER INTAKE GUI (SN)	SERVICEABLE	126.80	-
1	AIR INNER INTAKE GUI (SN)	DEFORMED	244.70	220.23
1	GUIDE AIR S (SN)	DEFORMED	35.30	31.77
1	AIR INTAKE GUIDE FRT (SN)	DEFORMED	279.30	251.37
1	BUMPER FRT GRILLE CH (SN)	DEFORMED	281.60	253.44
1	BUMPER FRT GRILLE M4 (SN)	DEFORMED	649.40	584.46
1	BUMPER FRT TOP GRILL (SN)	CRACKED	321.20	289.08
1	R620367005E/BUMPER T (SN)	SERVICEABLE	874.50	-
1	REINFORCEMENT FRT (SN)	BENT	653.80	588.42
1	INNER AIR GUIDE PANE (SN)	DEFORMED	790.20	711.18
1	HEADLAMP LHF W/XENON (SN)	BROKEN	1,264.40	1,137.96
1	HEADLAMP RH F W/XENON (SN)	CRACKED	1,264.40	1,137.96
1	BULB HEADLAMP R26 DI (SN)	SERVICEABLE	438.00	-
1	WING MIRROR SIGN LAM (SN)	SERVICEABLE	296.80	-
1	WING MIRROR SIGN LAM (SN)	SERVICEABLE	229.00	-
1	AIR COOLER GUIDE AIR (SN)	CRACKED	35.30	31.77
1	A/C CONDENSER COWING (SN)	CRACKED	74.60	67.14
1	A/C CONDENSER GS4 (SN)	BENT	1,274.60	1,147.14
1	RADIATOR ASSY M4S M4 (SN)	BENT	580.80	522.72
1	AIR COOLER ASSY - GS4 (SN)	BENT	689.80	620.82
1	FAN MOTOR (SN)	SERVICEABLE	706.70	-
1	LOGO FRT GRILLE GS4 (SN)	NECESSARY	125.90	113.31
1	BONNET (SN)	BENT	918.10	826.29
1	BONNET HINGE LH (SN)	BENT	175.30	157.77

Report Ref No. CS/EQI18023159/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH (SN)	BENT	175.30	157.77
1	BONNET LOCK (SN)	SERVICEABLE	139.90	-
1	FENDER FRT LH M4S (SN)	TORN	386.40	347.76
1	FENDER FRT RH M4S (SN)	TO REPAIR SEE LABOUR	386.40	-
1	EQUERRE G F (SN)	SERVICEABLE	59.80	-
1	BRACKET FENDER LH OU (SN)	NECESSARY	87.70	78.93
1	BRAS G PRT (SN)	SERVICEABLE	169.30	-
1	FENDER BRACKET FRT R (SN)	SERVICEABLE	87.70	-
1	EQUERRE D F (SN)	SERVICEABLE	61.40	-
1	DASHBOARD, M4GT (SN)	TORN	4,239.30	3,815.37
1	AIRBAG PASSENGERS (SN)	ACTIVATED	887.30	798.57
1	*E* STEERING AIRBAG (SN)	ACTIVATED	699.10	629.19
1	AIRBAG COMPUTER (SN)	ACTIVATED	1,213.90	1,092.51
1	BODY PANEL SEALANT (SN)	NECESSARY	942.20	847.98
1	ADHESIVE SEALER FL2 (SN)	NECESSARY	549.10	494.19
1	SEATBELT RHF (SN)	ACTIVATED	986.20	887.58
1	SEATBELT LHF (SN)	ACTIVATED	986.20	887.58
2	SEATBELT RHR LHR (SN)	ACTIVATED	1,972.40	1,775.16
1	SEATBELT CTR (SN)	ACTIVATED	986.20	887.58
1	LOWER FRT AIR INNER (SN) (ADDITIONAL)	CRACKED	114.12	114.12
1	REINFORT CTL (SN) (ADDITIONAL)	SERVICEABLE	551.30	-
1	BUMPER TOP GRILLE IN (SN) (ADDITIONAL)	CRACKED	787.05	787.05
1	FOG LAMP MOULDING M4 (SN) (ADDITIONAL)	SCRATCHED	199.71	199.71
1	DEFLECTEUR (SN) (ADDITIONAL)	CRACKED	48.69	48.69
1	RADIATOR GRILLE COVE (SN) (ADDITIONAL)	CRACKED	151.02	151.02
1	FENDER BAR BRACKET S (SN) (ADDITIONAL)	NECESSARY	26.19	26.19
1	EQUERRE D F (FRONT LOWER BRACKET) (SN) (ADDITIONAL)	CRACKED	67.86	67.86
10	FENDER CLIP C3 (SN) (ADDITIONAL)	NECESSARY	96.30	96.30
1	BONNET INSULATOR (SN) (ADDITIONAL)	DEFORMED	180.27	180.27
10	INSULATOR CLIP M2 (SN) (ADDITIONAL)	NECESSARY	34.20	34.20
1	TUYAU COMPR (SN) (ADDITIONAL)	BENT	203.04	203.04
1	SUPPORT CAL (SN) (ADDITIONAL)	NECESSARY	41.13	41.13

Report Ref No. CS/EQ118023159/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BAC BATTERY (SN) (ADDITIONAL)	SERVICEABLE	282.20	-
1	BOITIER ELC (SN) (ADDITIONAL)	BENT	2,106.99	2,106.99
1	CONDUIT AIR (SN) (ADDITIONAL)	CRACKED	35.64	35.64
1	PROTECTEUR (SN) (ADDITIONAL)	CRACKED	46.26	46.26
1	WING MIRROR SIGN LAM (SN) (ADDITIONAL)	CRACKED	267.12	267.12
1	CONDUIT AIR (SN) (ADDITIONAL)	CRACKED	319.23	319.23
1	CONDUIT AIR (SN) (ADDITIONAL)	CRACKED	251.28	251.28
1	BONNET INNER HANDLE (SN) (ADDITIONAL)	CRACKED	49.68	49.68
1	LABEL TOP PANEL (SN) (ADDITIONAL)	NECESSARY	10.53	10.53
1	R978184671R/STICKER (SN) (ADDITIONAL)	NECESSARY	20.16	20.16
20	RIVET BLACK, BUMPER (SN) (ADDITIONAL)	NECESSARY	120.60	120.60
1	SUPPORT CAL (SN) (ADDITIONAL)	NECESSARY	47.88	47.88
1	R244280249R/TRAY-MUL (SN) (ADDITIONAL)	CRACKED	253.98	253.98
1	R620360534R/REINF-FR (SN) (ADDITIONAL)	BENT	420.93	420.93
1	FUSE BOX COVER (SN) (ADDITIONAL)	CRACKED	133.38	133.38
1	BONNET-SAFETY HOOK M (SN) (ADDITIONAL)	CUT	92.79	92.79
1	ROTARY SWITCH KJ (SN) (ADDITIONAL)	BENT	736.29	736.29
1	STEERING-WHEEL M4H (SN) (ADDITIONAL)	NECESSARY	1,620.72	1,620.72
1	PILLAR COVER (SN) (ADDITIONAL)	CRACKED	133.11	133.11
1	PILLAR COVER (SN) (ADDITIONAL)	CRACKED	133.11	133.11
			38,600.06	31,542.81
	LABOUR			
	TO REPLACE FRT BUMPER, RADIATOR GRILLE, REINFORCEMENT, HEADLAMPS, WING MIRROR, RADIATOR, CONDENSER, BONNET, LHF FENDER, RHF FENDER, ETC. INCLUSIVE OF THE REPAIR OF FENDER FRT RH M4S.		4,500.00	3,600.00
	TO PUTTY SPRAYPAINT ON FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, ETC.		2,400.00	2,000.00
	TO REPLACE DASHBOARD, DRIVER AIRBAG, PASSENGER AIRBAG, AIRBAG MODULE, ETC.		2,640.00	2,200.00
	TO REPLACE SEATBELTS IN VEHICLE.		1,760.00	1,540.00
	TO FOCUS HEADLAMP.		110.00	110.00
	TO VACUUM & TOP UP A/C GAS.		600.00	600.00

Report Ref No. CS/EQI18023159/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		330.00	330.00
	TO REPLACE BONNET COMPONENT, ENGINE COMPONENT, ETC. (ADDITIONAL)		1,350.00	1,350.00
			13,690.00	11,730.00
GRAND TOTAL			52,290.06	43,272.81

RECOMMENDED COST OF REPAIRS				43,272.81
LESS EXCESS				-500.00
NETT LIABILITY				42,772.81

Report Ref No. CS/EQI18023159/R1sd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.