

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 17/01/2019

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ1743B

Reg.date : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE BONNET COMPONENT, ENGINE COMPONENT, ETC	0	1350.00	0		1,350.00 S	
	LOWER FRT AIR INNER <i>CA</i>	1.0 EA	126.80			126.80 S	114.12 A
	RENFORT CTL <i>XX SUC</i>	1.0 EA	551.30	467.70		551.30 S	420.93 A
	BUMPER TOP GRILLE IN <i>CA</i>	1.0 EA	874.50			874.50 S	787.05 A
	FOG LAMP MOULDING M4 <i>SC</i>	1.0 EA	221.90			221.90 S	199.71 A
	DEFLECTEUR <i>CA</i>	1.0 EA	54.10			54.10 S	48.69 A
	RADIATOR GRILLE COVE <i>CA</i>	1.0 EA	167.80			167.80 S	151.02 A
	FENDER BAR BRACKET S <i>NE</i>	1.0 EA	29.10			29.10 S	26.19 A
	EQUERRE D F (<i>Front Lower Bar (Left) CA</i>)	1.0 EA	75.40			75.40 S	67.86 A
	FENDER CLIP C3 <i>NE</i>	10.0 EA	10.70			107.00 S	96.30 A
	BONNET INSULATOR <i>DE</i>	1.0 EA	200.30			200.30 S	180.27 A
	INSULATOR CLIP M2 <i>NE</i>	10.0 EA	3.80			38.00 S	34.20 A
	TUYAU COMPR <i>BT</i>	1.0 EA	225.60			225.60 S	203.04 A
	SUPPORT CAL <i>NE</i>	1.0 EA	45.70			45.70 S	41.13 A
	BAC BATTERI <i>CA XX SUC</i>	1.0 EA	282.20			282.20 S	253.78 A
	BOITIER ELC <i>BT</i>	1.0 EA	2341.10			2,341.10 S	2106.99 A

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



WEARNES

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 17/01/2019

WIP No. : 44407

Veh.In/Out: 18/12/2018

*Tel.No. : Mobile: 94564904

Reg.No. : SLQ1743B

Reg.date. : 29/06/2017

Mileage : 0

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

CONDUIT AIR	CRX	1.0 EA	39.60			39.60 S	35.64 A
PROTECTEUR	CRX	1.0 EA	51.40			51.40 S	46.26 A
WING MIRROR SIGN LAM	CRX	1.0 EA	296.80			296.80 S	267.12 A
CONDUIT AIR	CRX	1.0 EA	354.70			354.70 S	319.23 A
CONDUIT AIR	CRX	1.0 EA	279.20			279.20 S	251.28 A
BONNET INNER HANDLE	CRX	1.0 EA	55.20			55.20 S	49.68 A
LABEL TOP PANEL	CRX	1.0 EA	11.70			11.70 S	10.53 A
R978184671R/STICKER	CRX	1.0 EA	22.40			22.40 S	20.16 A
RIVET BLACK, BUMPER	CRX	20.0 EA	6.70			134.00 S	120.60 A
SUPPORT CAL	CRX	1.0 EA	53.20			53.20 S	47.88 A

Gross Total. 7,989.00

Labour Total 1,350.00

Parts Total 6,639.00

Package Total 0.00

Net..... 7,989.00

GST @ 7.0% 559.23

Total..... 8,548.25

Paid..... 0.00

Please Pay.. 8,548.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4930 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY



SERVICE ESTIMATE

0 - E00004 SL: EQ INSURANCE COMPANY LTD

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD

#17 CC TOWER BLOCK

MND COMPLEX

SINGAPORE 069110

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 26/04/2019

WIP No. : 44407

Veh.In/Out: 18/12/2018 29/03/2019

*Tel.No. : 62239433

Reg.No. : SLQ1743B

Reg.date : 29/06/2017

Mileage : 20,257

Chassis No: VF1RFB00356852573

Closed by : Michelle Ong Siew Be

Cyc Consultant : ACC

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

R244280249R/TRAY-MUL

1.0 EA

282.20

253.93

282.20 S

R620360534R/REINF-FR

1.0 EA

467.70

420.93

467.70 S

FUSE BOX COVER

1.0 EA

148.20

133.38

148.20 S

BONNET-SAFETY HOOK M

1.0 EA

103.10

92.79

103.10 S

ROTARY SWITCH KJ

1.0 EA

818.10

736.29

818.10 S

STEERING-WHEEL M4H

1.0 EA

1800.80

1620.72

1,800.80 S

PILLAR COVER

1.0 EA

147.90

135.11

147.90 S

PILLAR COVER

1.0 EA

147.90

135.11

147.90 S

Gross Total. 3,915.90

Labour Total 0.00

Parts Total 3,915.90

Package Total 0.00

Net..... 3,915.90

GST @ 7.0% 274.11

Total..... 4,190.01

Paid..... 0.00

Please Pay.. 4,190.01

GST: S=StdRated; O=OutOfScope; Z=ZeroRated