



51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 25 December 2018

Ukh - Bryan
26/12/2018 @ 1140h

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid <i>Bnc</i>	\$ 1,019.10
02	1 set	tailgate lid lock top and bottom <i>bt</i>	\$ 509.10
03	1 pc	tailgate lid weatherstrip <i>deformed</i>	\$ 309.10
04	1 pc	tailgate lid centre emblem badge <i>Hec</i>	\$ 81.10
05	1 pc	tailgate lid inner trim cover <i>deformed</i>	\$ 680.20
06	2 ps	tailgate lid damper stay @ \$222.10 <i>bt</i>	\$ 444.20
07	2 ps	tailgate lid hinges @ \$61.10 <i>bt</i>	\$ 122.20
08	1 pc	tailgate lid spoiler with third brake lamp <i>crack</i>	\$ 333.00
09	1 pc	rear windscreen glass <i>shortened</i>	\$ 990.10
10	1 pc	rear windscreen glass weatherstrip <i>Hec</i>	\$ 105.00
11	1 pc	rear windscreen glass inner garnish <i>svc</i>	\$ 123.00
12	1 pc	rear windscreen inner top garnish <i>svc</i>	\$ 95.00
13	1 set	rear wiper nozzle pipe <i>HD</i>	\$ 24.00
14	1 pc	rear end panel <i>Bnc</i>	\$ 519.80
15	1 pc	rear end panel inner trim <i>deformed</i>	\$ 450.10
16	1 pc	rear luggage floor panel <i>van</i>	\$ 650.00
17	1 pc	rear luggage floor panel insulator <i>svc</i>	\$ 595.00
18	1 pc	rear luggage floor partition garnish <i>HD</i>	\$ 400.00
19	2 ps	rear luggage floor side board @ \$117.60 <i>H/S Bnc o/s HD</i>	\$ 235.20
20	1 pc	rear bumper <i>torn</i>	\$ 1,019.10
21	8 ps	rear bumper fastener clips @ \$4.30 <i>Hec</i>	\$ 34.40
22	2 ps	rear bumper bracket @ \$121.10 <i>H/S broken o/s HD</i>	\$ 242.20
23	1 pc	rear bumper side holders <i>H/S broken o/s HD</i>	\$ 81.10
24	2 ps	rear bumper screw spacer @ \$8.00 <i>HD</i>	\$ 16.00
25	2 ps	rear bumper reflector @ \$81.10 <i>H/S dislodged o/s svc</i>	\$ 162.20
26	2 ps	rear lamps @ \$433.00 <i>H/S broken o/s svc</i>	\$ 866.00
27	1 pc	rear lamp quarter panel outer <i>Bnc</i>	\$ 233.00
28	2 ps	rear fender @ \$739.10 <i>H/S Bnc o/s HD</i>	\$ 1,478.20
29	2 ps	rear fender air vent @ \$80.70 <i>H/S dislodged o/s HD</i>	\$ 161.40
30	1 pc	rear fender inner trim <i>deformed</i>	\$ 561.10
31	8 ps	rear fender inner trim clips @ \$4.50 <i>Hec</i>	\$ 36.00
32	1 pc	left rear fender window glass with moulding <i>broken</i>	\$ 380.00
33	1 pc	left rear fender window glass inner garnish <i>bt</i>	\$ 123.00
34	1 pc	rear fender inner trim centre <i>deformed</i>	\$ 561.10
35	1 pc	rear fender outer extension panel <i>Bnc</i>	\$ 224.00
36	2 ps	rear fender inner cowling @ \$290.30 <i>H/S torn o/s svc</i>	\$ 580.60
37	12 ps	rear fender inner cowling clips @ \$4.50 <i>H/S Hec o/s HD</i>	\$ 54.00
38	1 pc	left rear fender inner wheel house panel <i>Bnc</i>	\$ 631.10
39	1 pc	exhaust box <i>van</i>	\$ 785.00



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SGC665H
Date of Accident : 24 December 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Heng Huat Heng

Date : 25 December 2018

Estimate To Repair SGQ3331C - Toyota Wish 1.8 A
Chassis No : ZNE100339257

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	1 pc	exhaust box moulding <i>HN</i>	\$ 58.00
41	1 pc	roof panel <i>Dented</i>	\$ 890.00
42	1 pc	left roof gutter moulding <i>SVU</i>	\$ 121.10
43	4 ps	left roof gutter moulding clips @ \$4.50 <i>SVU</i>	\$ 18.00
44	1 pc	roof-lining <i>crumpled</i>	\$ 490.80
45	1 pc	left rear door <i>Dented</i>	\$ 1,335.20
46	1 pc	left rear door lock <i>bt</i>	\$ 560.10
47	1 pc	left rear door outer handle <i>HN</i>	\$ 121.10
48	1 pc	left rear door weatherstrip <i>HN</i>	\$ 176.50
49	1 pc	rear chassis frame <i>new</i>	\$ 650.00
50	1 pc	tailgate lid centre logo badge <i>HN</i>	\$ 90.00
51	1 pc	tailgate lid upper garnish <i>chrome grade</i>	\$ 456.10
52	1 pc	tailgate lid third brake light <i>HN</i>	\$ 189.80
53	1 pc	tyre-mechanical jack <i>HN</i>	\$ 258.00
54	1 pc	tyre-mechanical jack bracket <i>new</i>	\$ 89.50
55	1 pc	spare tyre holder <i>HN</i>	\$ 85.00
56	1 pc	bonnet <i>Bnc</i>	\$ 933.40
57	1 pc	bonnet - emblem badge <i>HN</i>	\$ 72.20
58	2 ps	bonnet hinges @ \$56.50 <i>new</i>	\$ 113.00
59	1 pc	bonnet insulator <i>SVU</i>	\$ 395.00
60	8 ps	bonnet clips @ \$4.30 <i>HN</i>	\$ 34.40
61	2 ps	bonnet rubber stoppers @ \$18.50 <i>SVU</i>	\$ 37.00
62	3 ps	bonnet underseal weatherstrip with clips @ \$45.00 <i>SVU</i>	\$ 135.00
63	1 pc	bonnet lock <i>bt</i>	\$ 95.00
64	1 pc	front support panel <i>bt</i>	\$ 1,428.65
65	1 pc	front support panel cover <i>dented</i>	\$ 88.80
66	8 ps	front support panel top cover clips @ \$4.30 <i>HN</i>	\$ 34.40
67	1 pc	front bumper <i>dented</i>	\$ 592.00
68	1 pc	front bumper reinforcement <i>bt</i>	\$ 292.60
69	2 ps	front bumper side retainers @ \$60.30 <i>SVU</i>	\$ 120.60
70	1 pc	front bumper absorber foam <i>new</i>	\$ 88.30
71	2 ps	front bumper spot lamps @ \$300.90 <i>HN</i>	\$ 601.80
72	2 ps	front bumper spot lamp grille @ \$83.30 <i>HN</i>	\$ 166.60
73	2 ps	front bumper spot lamp side grille @ \$54.70 <i>HN</i>	\$ 109.40
74	8 ps	front bumper clips @ \$4.50 <i>HN</i>	\$ 36.00
75	1 pc	front bumper lower splashshield cover <i>torn</i>	\$ 124.60
76	2 ps	headlamps @ \$1689.20 <i>mainly broken</i>	\$ 3,378.40
77	1 pc	radiator grille <i>broken</i>	\$ 397.70
78	1 pc	radiator grille brace panel <i>bt</i>	\$ 88.80



陳林隆摩托有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SGC665H
Date of Accident : 24 December 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Heng Huat Heng

Date : 25 December 2018

Estimate To Repair SGQ3331C - Toyota Wish 1.8 A
Chassis No : ZNE100339257

S/No	Quantity	Description	Amount	
		<u>LIST ITEMS</u>		
79	1 pc	aircon condenser <i>BT</i>	\$ 1,489.00	✓
80	1 pc	radiator assy <i>BT</i>	\$ 1,499.00	✓
81	1 pc	radiator fan assy <i>HN</i>	\$ 980.50	X
82	2 ps	front fender @ \$827.50 <i>Dental</i>	\$ 1,655.00	✓
83	2 ps	front fender inner cowling @ \$156.00 <i>SVC</i>	\$ 312.00	X
84	8 ps	front fender inner cowling clips @ \$4.50 <i>HN</i>	\$ 36.00	X
85	1 pc	petrol tank <i>HN</i>	\$ 789.00	X
86	1 pc	petrol tank panel <i>reg</i>	\$ 125.20	X
87	1 pc	aircon condenser hose - condenser to compressor <i>HN</i>	\$ 407.90	X
88	1 pc	aircon condenser pipe - condenser to evaporator <i>HN</i>	\$ 407.90	X
			\$ 38,569.05	
		Less 25 %	\$ 9,642.26	
			\$ 28,926.79	
		<u>SPECIAL NETT ITEMS</u>		
89	1 pc	rear windscreen sealant <i>HN</i>	\$ 80.00	40/-
90	1 pc	rear windscreen inner sponge seal <i>HN</i>	\$ 120.00	40/-
91	1 pc	rear fender window glass sealant <i>HN</i>	\$ 50.00	20/-
92	1 pc	rear fender window glass inner sponge seal <i>HN</i>	\$ 120.00	20/-
93	1 pc	rear licence plate <i>SVC</i>	\$ 50.00	X
94	1 pc	right rear tyre <i>Wgt cut 50% depreciation</i>	\$ 220.00	350.00 110.00
95	1 pc	right rear wheel rim <i>cut</i>	\$ 650.00	350.00
96	1 pc	front licence plate <i>dislodged</i>	\$ 50.00	45.00
			\$ 1,470.00	
		<u>LABOUR & MISC. CHARGES</u>		
01		Towing with king dolly. <i>HN</i>	\$ 150.00	80/-
02		To check electrical lighting concerned.	\$ 80.00	30/-
03		To rust-proofing of the affected areas.	\$ 180.00	80/-
04		To reinstall of rear bumper parking sensor.	\$ 60.00	40/-
05		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 300.00	150/-
06		To remove and refit rear windscreen glass.	\$ 120.00	80/-
07		To remove and refit left rear fender window glass.	\$ 120.00	40/-
08		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00	60/-
09		To transfer of right rear door fittings and perform water seepage test.	\$ 150.00	60/-
10		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 200.00	120/-
11		To drop petrol tank, hoses to facilitate bodywork repair, final checking and testing.	\$ 250.00	80/-



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SGC665H
Date of Accident : 24 December 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Heng Huat Heng

Date : 25 December 2018

Estimate To Repair SGQ3331C - Toyota Wish 1.8 A
Chassis No : ZNE100339257

S/No	Quantity	Description	Amount
<u>LABOUR & MISC. CHARGES</u>			
12		To drop rear exhaust box and renew the same.	\$ 200.00
13		To check steering geometry and computer wheel alignment.	\$ 80.00
14		To transfer of tyre, rim and on wheel balancing.	\$ 50.00
15		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 250.00
16		To dismantle and refit rear seat, backrest, trimming, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$ 450.00
17		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,950.00
18		Putty and spray painting of the affected portion.	\$ 1,800.00
			\$ 7,540.00
Total			\$ 37,936.79

60/-
60/-
30/-
150/-
120/-
1800/-
1400/-

26/12/2018 @ 1100am

NA Antenna

L/Smr

28 days.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Repairer Limit 12.5K

Photo after repair.