

ASS. REC. BY:

REF:

CS/CTU8023173 / Aq3n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Ong Chin Kiat

of

CTL

Date/Time: 27/2/2018 1158am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 3562C

Insured:

GBF 6290J

at Workshop m/s

Reliable Carz

Tel:

of

8 Kuli Bukit Ave 4 #05-50

Policy No:

DMCVSN 3003191800

Claim No:

SNM19020001602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/2/2018

CA / REV / REP. / REV 24 HRS 'wpi

H.O.D. Endorsement:

Date/Time:

27/2/2018 1233pm

Person Contacted:

Justin

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 3562C - NA / INC18003138 / 24
	GBF 6290J - X
	US \$ 3750, 4 days (Rel \$ 8567.77, 72%)

REF: CTI

ASSIGNMENT

From: Date: 15/4/2019

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 3562C

at Workshop m/s Reliable Carz

of 8 Kaki Bukit Ave 4 # 05-50 Premier

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Jason 8166 9797

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLT3562C Yr Regn: 2017.10ct.

Type: ☒ M.Car / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle Hybrid .c.c 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 135 715 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 6P71120735

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Newton.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 15/04/19

Survey held at Reliable Carz.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chan.

RECEIVED 01 AUG 2019

Date/Time, File Pass to?

1) 01/8 Mark

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

2434 4815 2355

Survey Fee:

Transportation:

S+RS, SI

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018		27 Dec 2018 11:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PLUS-AIR ENGINEERING WORKS, Co. Reg. No.: 52827110E								
Main Claimant:	RELIABLE RIDES PTE LTD, Co. Reg. No.: 201611527N								
Vehicle Reg. No.:	SLT3562C	Date of Loss:	24/12/2018 23:00 - :59 [13 Months and 28 Days From LTA Reg Date (Mon Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	DMCVSN3003191800 (Comprehensive) Coverage: 11/01/2018 - 10/01/2019						
Vehicle Reg. No. (Insured):	GBF6290J	Policy No. (Claimant):							
		Excess:	S\$0.00						
Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:									
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/01/2019]								
Adjusting Remarks:	Workshop choose Adrian Ling for SJE. Please assist to assign Adrian to conduct the PRS. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

TP China Xiao Chen

No. :

Date: ~

SLT 3562 C

HONDA SHUTTLE
(GPT-1120735)

BONNET	Dented	\$ 890.30	—
BONNET HINGE X 2 pcs	new	\$ 42 X 2 pcs	+ 84
BONNET LOCK	3 new	\$ 116.00	+
BONNET INSULATOR		\$ 132.30	+
FRONT BUMPER	Dented	\$ 1740	— 1100.
FRONT BUMPER REINFORCEMENT	new	\$ 493.40	+
FRONT BUMPER LOWER GRILLE	new	\$ 132.20	✓
FRONT BUMPER RETAINER X 2 pcs	new	\$ 25.20 X 2 pcs	— 50.40
FRONT GRILLE	new	\$ 545.20	— 363.30
FRONT GRILLE CHROME MOULDING	new	\$ 182.40	✓
FRONT GRILLE CHROME MOULDING (Top)	new	\$ 385.40	— 292.60
HEAD LAMP LH	new	\$ 2237.30	+
HEAD LAMP RH	new	2237.30	2 850
FRONT EMBLEM (Logo)	new	\$ 18.17	—
HEAD LAMP LOWER BRACKET RH	new	\$ 88.30	+
HEAD LAMP LOWER BRACKET LH	new	\$ 88.30	+
SUPPORT PANEL		\$ 611.10	+
FRONT BUMPER TOWING COVER		\$ 16.60	+

4017.37

3213.89

SPECIAL NETT ITEM

FRONT BUMPER CLIP (SET)	new	\$ 50.30	— 80
FRONT NUMBER PLATE W CASING	new	\$ 50	—

LABOUR CHARGE

TO REMOVE, REPLACE & REPAIR ABOVE PART
TO SPRAY PAINTING ON AFFECTED AREA

\$ 800 400 800.
\$ 800 400

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4053.89 Adnan L
L/s: 3250 L/s 15/04/19.

04 days.

11817.77



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118023173/AQD3N2

Date: 02/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3003191800
Claimant Vehicle No :	SLT3562C	Insured Vehicle No :	GBF6290J
Date of Loss:	24/12/2018	Nature of Claim:	TP
		Claim No:	SNM19D20001602

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3562C	Engine No:	LEB6325564
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71120735
Reg. Date:	26/10/2017 (Man. Year: 2017)	Odometer:	135715 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,217.77	3,293.90	6,923.87	67.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	800.00	800.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,817.77	4,093.90	7,723.87	65.36
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	11,817.77	3,250.00	8,567.77	72.50

INSPECTION

Date of Assignment:	27/12/2018	Inspected At:	Reliable Carz Pte Ltd (HQ)
Date Inspected:	15/04/2019		8 Kaki Bukit Ave 4, #05-50
			Singapore 415875

Estimated Period of Repair: 4.0 days**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Aug 2019)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT3562C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	892.30 F	*892.30 FL
2	2		*BONNET HINGE	Not Necessary	84.00 F	*- FL
3	1		*BONNET LOCK	Not Necessary	116.00 F	*- FL
4	1		*BONNET INSULATOR	Not Necessary	122.30 F	*- FL
5	1		*FRONT BUMPER	Deformed	1,740.00 F	*1,100.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	493.40 F	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Cracked	132.20 F	*132.20 FL
8	2		*FRONT BUMPER RETAINER	Necessary	50.40 F	*50.40 FL
9	1		*FRONT GRILLE	Cracked	545.30 F	*363.30 FL
10	1		*FRONT GRILLE CHROME MOULDING	Cut	182.40 F	*182.40 FL
11	1		*FRONT GRILLE CHROME MOULDING (TOP)	Cracked	382.40 F	*292.60 FL
12	1		*HEAD LAMP LH	Not Necessary	2,237.30 F	*- FL
13	1		*HEAD LAMP RH	Cracked	2,237.30 F	*850.00 FL
14	1		*FRONT EMBLEM (LOGO)	Necessary	98.17 F	*98.17 FL
15	1		*HEAD LAMP LOWER BRACKET RH	Cracked	88.30 F	*56.00 FL
16	1		*HEAD LAMP LOWER BRACKET LH	Not Necessary	88.30 F	*- FL
17	1		*SUPPORT PANEL	Not Necessary	611.10 F	*- FL
18	1		*FRONT BUMPER TOWING COVER	Not Necessary	16.60 F	*- FL
19	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1		*FRONT NUMBER PLATE & CASING	Cut	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,217.77	4,097.37
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	803.47
Total Parts (\$\$)	10,217.77	3,293.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACE & REPAIR ABOVE PART	New	800.00	400.00
2	TO SPRAY PAINTING ON AFFECTED AREA	New	800.00	400.00
Gross Labour Cost (\$\$)			1,600.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >