

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 02 Jan 2019

Preliminary Advice

Insured Vehicle No	: FBE3104P		
TP Vehicle No	: SKE2637T	Accident Date	: 24/12/2018
Make	: MERCEDES-BENZ E250	Assignment Date	: 27/12/2018
Date of Inspection	: 28/12/2018	Est. Duration of Repair	: 2 days
Inspection At	: Jin Huat & Co (HQ) 176 SIN MING DRIVE #05-01, SIN MING AUTOCARE Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,576.00
Revised Amount	:S\$	2,117.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,117.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP