

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7042Y

DATE 12/27/2018 10:43

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>X repz</i>			\$ 2,174.90
	Boot Lid Rubber <i>X</i>			\$ 96.50
	Boot Lid 'H' Emblem <i>/</i>			\$ 28.70
	Boot Lid CRDI Plate <i>/</i>			\$ 27.90
	Boot Lid Lamp (LH) <i>/</i>			\$ 565.60
	Bootlid Moulding <i>/</i>			\$ 85.00
	Bootlid i40 Emblem <i>/</i>			\$ 27.90
	Bootlid Lower Garnish <i>/</i>			\$ 227.90
	Rear Bumper <i>/</i>			\$ 553.00
	Rear Bumper Reinforcement <i>?</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>?</i>		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>/</i>			\$ 22.00
	Rear Bumper Bracket (LH) <i>/</i>			\$ 35.60
	Rear Bumper Sponge <i>?</i>			\$ 103.50
	Rear Bumper Under Cover <i>/</i>			\$ 228.00
	Rear Bumper Reflector Lamp (LH) <i>/</i>			\$ 30.60
	Tail Lamp (LH) <i>/</i>			\$ 697.80
	Tail Lamp Quarter Panel (LH) <i>X repz</i>			\$ 226.50
	Rear Panel <i>X repz</i>			\$ 526.70
	Rear Panel Garnish <i>?</i>			\$ 57.70
	Rear Panel Lower Panel <i>X repz</i>			\$ 495.50
	Rear Fender (LH) <i>X repz</i>			\$ 2,171.40
	Rear Fender Inner Lining (LH) <i>?</i>			\$ 169.30
	Rear Fender Air-Duct (LH) <i>?</i>			\$ 51.60
	Rear Windscreen Moulding <i>X</i>			\$ 28.30
	SUB TOTAL			\$ 9,220.90
	LESS 20%			\$ 1,844.18
	DISCOUNTED TOTAL			\$ 7,376.72
	Boot Lid Comfort Logo & Tel No. Sticker <i>/</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>X</i>			\$ 50.00
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00
	Rear Windscreen Sealant <i>X</i>			\$ 46.00
				\$ 311.70
	Labour Charge			800
	Panel Beating (Repair)			\$ 1,600.00
	Spray Painting Charge			\$ 1,250.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00

Alls

Chang

Nett
Nett
Nett
Nett
Nett

1000
20
30
50
X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Remove/Refix Reverse Sensor			\$ 80.00 X
	TOTAL LABOUR			\$ 3,350.00
	ESTIMATE TOTAL			\$ 11,038.42
Kahwille ✓ 27/12/18 1250h 4 by, PIP Before Post photo				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				