



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 2015366H
3RD PARTY CLAIM ESTIMATION

AIG Asia Pacific Insurance Pte. Ltd
 78 Shenton Way
 #08-16
 Singapore(079120)

Vehicle number	SKT5775D
Make / Model	NISSAN ELGRAND
Chassis number	JN1TBAE52Z0802379
Accident date	12-Dec-18
Reference	1812-27

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER distorted	3419.88 ✓
1	REAR BUMPER SPONGE torn	167.25 ✓
1	REAR BUMPER REINFORCEMENT Dented	900.63 ✓
1	REAR END PANEL - INNER HH	1351.50 X
1	REAR END PANEL - OUTER Dented	1051.25 ✓
1	TAILGATE Dented	3382.00 ✓
1	REAR LH CORNER PANEL SVC	1938.25 X
1	REAR RH CORNER PANEL SVC	1938.25 X
1	REAR RH FENDER INNER TRIM SVC	531.44 X
1	FRONT BUMPER Crd.	3135.90 ✓
		17816.35
	Less 30%	5344.90
	Subtotal	12471.45
	Balance C/F	12471.45
1	REAR RH INNER LAMP momentarily broken	310.50 ✓
2	REAR REINFORCEMENT BRACKET reg	401.50 X
1	TAILGATE EMBLEM Hec	65.63 ✓
1	FRONT RH SIDE RETAINER SVC	48.00 X
2	REAR BUMPER RETAINER SVC	83.00 X
2	REAR BUMPER REFLECTOR HH	119.76 X
1	REAR LOCK SENSOR broken	92.63 ✓
1	TAILGATE WEATHERSTRIP deformed	183.25 ✓
1	REAR END PANEL TOP GARNISH COVER momentarily deformed	376.88 ✓
		1681.15
	Less 10 %	167.80
	Subtotal	1513.35
	Balance C/F	13984.80
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	13984.80
1	REAR NUMBER PLATE HH	80.00 X
1 SET	REAR BUMPER CLIP Hec	40.00 30/-
1 SET	REAR REVERSE SENSOR Dem	400.00 220/-

1	WINDSCREEN SEALANT <i>huc</i>	150.00
1	JOINT SEALANT <i>huc</i>	150.00
1 BOT	BRAKE FUILD <i>huc</i>	50.00
1 BOT	COOLANT <i>huc</i>	50.00
Subtotal		920.00
Balance C/F		14904.80
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
Balance B/F		14904.80
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	70.00 30/-
4	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
5	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
6	REMOVE AND RENEW FLOOR INSULATOR	150.00 <i>huc</i>
7	REMOVE AND REFIT REAR WINDSCREEN	150.00 80/-
12	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60/-
14	PANEL BEATING ON AFFECTED AREAS	2000.00 800/-
15	SPRAY PAINTING ON AFFECTED AREAS	1800.00 800/-
16	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
Subtotal		4870.00
Grand total		19774.80

27/12/2018 @ 1100hrs

huc Andrew

L/Sure 5 dgs.

ryan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Check part prices.