



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SKA 5035 G
VOLKSWAGEN GOLF

not Alud
may
27/12/18
1/5 @ 2600/-
307.

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	TAILGATE	1	11X
2	TAILGATE LOGO	1	11X
3	TAILGATE EMBLEM '1.4TSI'	1	11X
4	TAILGATE INNER TRIM	1	11X
5	TAILGATE LAMP RH	1	11X
6	TAILGATE WEATHERSTRIP	1	11X
6	TAILLAMP RH 563.28	1	\$ 598.34
7	REAR BUMPER	1	\$ 867.95
8	REAR BUMPER LOWER	1	\$ 530.72
9	REAR BUMPER REINFORCEMENT BAR	1	\$ 399.10
10	REAR BUMPER BEAM	1	\$ 162.40
11	REAR BUMPER SENSOR 225	2	\$ 680.00
12	REAR BUMPER SENSOR WIRE	1	\$ 266.40
13	REAR BUMPER NUMBER PLATE	2	\$ 86.20
14	REAR BUMPER BRACKET RH	1	\$ 88.40
15	REAR BUMPER REFLECTOR RH	1	\$ 85.90
16	REAR BUMPER RETAINER RH	1	\$ 92.60
17	REAR FENDER RH	1	\$ 1,785.60
18	REAR FENDER COWLING RH	1	
19	REAR FENDER INNER TRIM RH	1	
20	END PANEL	1	\$ 773.17
21	END PANEL TOP GARNISH	1	\$ 190.19
22	END PANEL SENSOR	1	\$ 266.30
SUBTOTAL			\$ 6,873.27
LESS 10%			\$ 687.33
PARTS TOTAL			\$ 6,185.94
SPECIAL NETT		QTY	PRICE
1	REAR NUMBER PLATE 11	1	\$ 100.00
2	REAR END PANEL SEALANT 11	1	\$ 120.00
3	REAR BUMPER CLIPS	10	\$ 120.00
4	REAR FENDER COWLING CLIPS 11	10	\$ 120.00
5	REAR FENDER INNER TRIM CLIPS 11	10	\$ 120.00
6	TAILGATE INNER TRIM CLIPS 11	10	\$ 120.00
7	REAR WINDSCREEN SEALANT 11		
SPECIAL NETT TOTAL			\$ 700.00
LABOUR		QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN 400	1	\$ 2,500.00

2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$ 2,000.00	600
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$ 120.00	X
4	TO RNR REAR WINDSCREEN	1	\$ 400.00	X
5	TO RNR REAR BOOT MECHANISM	1	\$ 120.00	X
6	TO RNR REAR LUGGAGE COMPARTMENT	1	\$ 400.00	60
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	1	\$ 120.00	50
8	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	1	\$ 120.00	20
9	TO CHECK WIRING LAYOUT AND TAILGATE LAMP FUNCTION	1	\$ 120.00	X
10	TO DO WATER LEAK TEST .	1	\$ 120.00	X
11	TO RNR FUEL TANK TO ASSIST WORK LOAD	1	\$ 250.00	X
LABOUR TOTAL			\$ 6,270.00	
GRAND TOTAL COST			\$ 13,155.94	

PAGE 2 OF 2

LK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-2367.95
 102
 2131.15
 S.N 50.00
 10km 1130.00
 3311.15
 1055 2020
 2648