LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

GNOH PAU LOONG Date: 28 Dec 2018 Attn:

Preliminary Advice

Vehicle No : SLC5928H **Accident Date** : 24/12/2018

Policy No. Make : VOLVO V40 : D18MTPV01008957

: S\$0.00 Assignment Date : 27/12/2018 **Excess** Date of Inspection : 28/12/2018 Est. Duration of Repair : 7.00

Inspection At : ACCORD AUTO SERVICES PTE LTD (HQ)

10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT

SINGAPORE 568047

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,562.50
Revised Amount	:S\$	8,199.40
Check Items (Estimated)	:S\$	4,921.30
Total	:S\$	13,120.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 70,000.00 COE / PARF Rebate :S\$ 48,795.00

Salvage Value :S\$

Margin for Repair :S\$ 21,205.00

Remarks

(X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :