

21/03/2013

ASS. REC. BY:

REP

CS/MSG18023193/USD3N2

Special Instruction

Surveyor:

Menmen

Markus

ASSIGNMENT (Office)

From (Person)

Christopher Wong

of

MSG

Date/Time

27/12/18 @ 1.56pm

Estimated Cost:

Bill to:

OD (V) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGK 8285B

Insured:

SLT 2597J

at Workshop m/s:

Zoom Autowerks

Tel:

9450 7920

of

15 Kaki Bukit Rd 4 # 01-53

Policy No:

A29069766MKF

Claim No:

580082

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/12/2018

CA / REV / REP. / REV 24 HRS

kup?

28/12/2018

H.O.D. Endorsement:

Date/Time:

3:44pm @ 27/12/18

Person Contacted:

Elin

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGK 8285B - X
	SLT 2597J - X

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MSL 61

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGK8285at Workshop m/s: Zoom

of \_\_\_\_\_

Insured: GBC 4726M

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 18k

IDAC/Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

483K

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGK8285B Yr Regn: 8, 06Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: maxda 3 Lux c.c. 1598Colour: white A/C: Insured / Std / NI / NASp. Reading: 171416 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6BK106100207238

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 24/12/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear L & R

Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 28/12/18Date / Time Action / Instruction col 31-7-20212yrs. Take. L1A 12792 net 5284/6/19 2/5 # 5000 confirmed with ElinParts Prices checked by Marcus4/6/19 Confirmed HS \$5,000/- @ 7 days with Marcus(\$ 11,844.84 Red - 70%)

RECEIVED 07 JAN 2019

Date/Time, File Pass to?

07/01/191) Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐

: Prel. Report

☒

: Final Report

Days Of Repair: 7Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

10

210

Report Format :

Lump Sum / I.B.I.: (\$ 5,000/- HS)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018		27 Dec 2018 13:56 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	LIM BEE PHENG, ID: S0094837C		
Vehicle Reg. No.:	SGK8285B	Date of Loss:	24/12/2018 00:00 - :59 [147 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 580082	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019
Vehicle Reg. No. (Insured):	SLT2597J	Policy No. (Claimant):	
		Excess:	
Repairer:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53, 417808 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Imm.Advice due 28/12/2018]</b>		
Driver/Custodian (Insured):	LAI YAW TING (), NRIC: S7281196H, Tel: +6591075542		
Adj Asg. Remarks:	Liability is down due to bola. TP want to use Marcus frm LKK as the SJE. Contact Person: Elin Cai / 9450 7920.		

#### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



mazda 3

Price Range ▼

Depreciation ▼

&gt; 10 year(s) ▼

Vehicle Type ▼



Home » Used Cars » Jia Leong Trading Enterprise » Mazda 3 1.6A Luxury (COE till 07/2021)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Mazda 3 1.6A Luxury (COE till 07/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map



# Jia Leong Trading Enterprise Pte Ltd

- Since 1988 -

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

Price	\$17,800	?
Depreciation	\$6,950 /yr	?
Reg Date	24-Jul-2006 (2yrs 6mths 22days COE left)	?
Manufactured	2006	?
Mileage	109,330 km (8.8k /yr)	?
Transmission	Auto	?
Engine Cap	1,598 cc	?
Road Tax	\$890 /yr	?
Power	79.0 kW (105 bhp) View specs of the Mazda 3 Sedan (2004-2009)	?
Curb Weight	1,235 kg	?
Features	Smooth And Fuel Efficient 1.6L DOHC 16 Valves Engine, 5 Speed Auto With Activematic, ABS, Airbags, Multi Function Steering Control.	?
Accessories	Black Leather Upholstery, Factory Fitted Audio With Multi Function Control Steering, Parking Sensors, Auto Retractable Wing Mirrors.	?
Description	Beautiful Metallic Silver. 2 Careful Owners. Well Maintained, Seldom Used, Accident Free, Under Warranty, Just Serviced, Undergone A 120 Points Safety Check By Our In House Mechanics Peace Of Mind! Can Loan Up To 80%. Down Payment \$5800 Negotiable. Loan \$12K x 18 Months, Monthly \$698, Interest Rate From 3.18%, Can Trade In, Must View.	?
COE	\$24,760	?
OMV	\$15,853	?



Location Map

## Seller Information

Company	Jia Le » deale » 19 ve
Address	61 Ubi Search
Location	Automc
Office No	684154

## Car Tyres



Compare

## View Sent Message

This mail is associated with :

**\*SGK8285B (580082)**  
**[SLT2597J]**

TP  
LIM BEE PHENG  
Dec 24 2018 12:00AM  
[GRAB RENTALS PTE LTD]  
Zoom Autowerks Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **02/01/2019 11:40 AM.**  
**To** christina\_wong@sg.msg-asia.com  
**CC** sur@lkkauto.com  
**Subject** **SGK8285B (580082) [SLT2597J] TP**

Dear Christina,

Please be informed that we have inspected the vehicle SGK 8285B on 28/12/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	4837C

### Vehicle Details

Vehicle No.:	SGK8285B
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA 3 LUX
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	Z6455375
Chassis No.:	JM6BK106100207238
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$15,853.00
Original Registration Date:	28 Aug 2006
First Registration Date:	28 Aug 2006
Transfer Count:	1
Actual ARF Paid:	\$10,714.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	31 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,760.00
COE Rebate Amount:	\$12,792.00
<b>Total Rebate Amount:</b>	<b>\$12,792.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/12/2018 09:15
Date Of Accident	24/12/2018 12:15
Exact Location Of Accident	CTE (SLE) AFTER JALAN BAHAGIA EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK8285B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM BEE PHENG
NRIC No	S0094837C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81126623
Alternative Phone No	OFFICE-81126623

### Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	LIM BEE PHENG
NRIC No	S0094837C
Date Of Birth	26/03/1953
Occupation	INDOOR
Date Of Driving Pass	07/07/1980
Driving Experience	38 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81126623
Fax Number	
Contact Number	OFFICE-81126623
EEmail Address	NOEMAIL



Address 469A ADMIALTY DRIVE #09-111 S751469

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 5

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : LYDIA LIM HUI FERN  
GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

refer to attached

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLT2597J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SLH2412Y  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number SKD2588G  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number GZ4806X  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name LYDIA LIM  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SGK8285B  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

**DETAILS OF INJURED PERSON 2**

Name

LIMBEE PHENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGK8285B

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

# Sketch Plan

## SKETCH PLAN



CIE > SLE Before PLE CHAND EXIT

'A' SGK 8285 B  
'B' SLI 2597 J  
'C' SLH 2412 Y  
'D' SKD 2588 G  
'E' GZ 4806 X


## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On the stated date and time, I vehicle 'A' was travelling on the  
stated venue. Front Vehicle stopped I stopped. After a short moment  
Vehicle 'B' rear ended my vehicle causing me to propel forward to  
hit the vehicle 'D'.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Person's Signature  
Name: Suhaimi  
NRIC/TIN No.: S8040377A

## Sketch Plan #2


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name: Suhaimi  
NRIC/FIN No.: S8040377A



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130  
Tel: 9450 7920  
\* zoomautowerks@gmail.com

28 DECEMBER 2018

D.O.A: 24 DECEMBER 2018

OWNER: LIM BEE PHENG

REG NO.: SGK 8285 B

MAKE/MODEL: MAZDA 3

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$S)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	\$ 11 68.90 X
1	Rear boot lid	\$ 20/24 972.00
1	Rear boot inner lock	\$ 20/24 221.80
1	Rear boot rubber	\$ 20/24 118.80
2	Rear boot hinges	\$ 11 280.80 X
1	Rear boot "3" emblem	\$ 20 29.60
1	Rear boot "MAZDA" emblem	\$ 20 25.20
1	Rear boot logo	\$ 20 62.60
2	Rear boot lamps	\$ 11 523.00 X
2	Rear number plate lamps	\$ 11 417.60 X
2	Rear taillamps	\$ 20 2,076.80 12C
2	Rear taillamp panels	\$ 20 204.00 X
1	Rear end panel	\$ 20 357.00
1	Rear end panel inner garnish	\$ 20 212.50
1	Rear bumper	\$ 20 1,026.70
1	Rear bumper reinforcement	\$ 20 547.00
2	Rear bumper side retainers	\$ 20 77.20
2	Rear bumper reflectors	\$ 11 124.00 X
1	Rear floor board	\$ 11 411.20 X
1	Rear floor panel	\$ 20 2,221.00 X
1	Rear exhaust silencer	\$ 20 953.80 X
2	Rear exhaust moutings	\$ 11 91.00 X
1	Rear fender -LH	\$ 20 1,091.00 X
1	Rear fender air gate	\$ 11 41.50 X
2	Rear fender inner trims	\$ 11 385.30 X
2	Rear fender inner shields	\$ 11 97.00 X
		\$ 12,637.30
Less 20%		\$ 2,527.46
		\$ 10,109.84

not allocated  
LHR  
1/5 \$ 5000/2  
7 day  
28/12/18

3810.7  
202  
P 3080.56  
10hr 3205  
6261.56

c/f: \$ 10,109.84

**SPECIAL NETT ITEMS**

1	Rear windscreen sealant	\$ 11	80.00	X
1	Rear bumper clip (1 set)	\$ 11	45.00	✓
1	Rear number plate	\$ 11	50.00	40
1	Rear reverse sensor (1 set)	\$ 11	350.00	200
		\$	525.00	

**S/N LABOUR CHARGES**

1	To check wiring and reset headlamps focusing.	\$	80.00	30
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	
3	To remove and refit inner garnishes.	\$	150.00	80
4	To remove and refit rear reverse sensor.	\$	120.00	50
5	To transfer rear boot lid mechanism and wiring assembly.	\$	120.00	60
6	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$ 11	180.00	X
7	To remove and refit rear windscreen glass.	\$ 11	180.00	X
8	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	60
9	To apply undercoating.	\$	250.00	60
10	Panel beating.	\$	2,500.00	1080
11	To re-spray painting on the affected areas.	\$	2,400.00	1500
		\$	6,210.00	

3205

**GRAND TOTAL :**

**\$ 16,844.84**

LHK Auto Centres hereby notify the Repairs shop the following:

- To ensure full coverage spray painting
- To ensure all parts are replaced during recovery
- Repairs must be done to satisfaction
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18023193/USD3N2

Date: 07/01/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29069766MKF
Claimant Vehicle No :	SGK8285B	Insured Vehicle No :	SLT2597J
Date of Loss:	24/12/2018	Nature of Claim:	TP
		Claim No:	580082

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGK8285B	Engine No:	Z6455375
Make & Model:	MAZDA 3, 1.6 LUX (A)	Chassis No:	JM6BK106100207238
Reg. Date:	28/08/2006 (Man. Year: 2006)	Odometer:	171416 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,634.84	3,365.56	7,269.28	68.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,210.00	2,920.00	3,290.00	52.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,844.84	6,285.56	10,559.28	62.69
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	16,844.84	5,000.00	11,844.84	70.32

## INSPECTION

Date of Assignment:	27/12/2018		
Date Inspected:	28/12/2018	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2019)
Parts:	143	MAZDA 3 1.6 LUX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGK8285B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	68.90 FL	*- FL
2	1		*REAR BOOT LID	Dented/Bent	972.00 FL	*972.00 FL
3	1		*REAR BOOT INNER LOCK	Twisted/Shorted	221.80 FL	*221.80 FL
4	1		*REAR BOOT RUBBER	Twisted	118.80 FL	*118.80 FL
5	2		*REAR BOOT HINGES	Not Necessary	280.80 FL	*- FL
6	1		*REAR BOOT 3 EMBLEM	Necessary	29.60 FL	*29.60 FL
7	1		*REAR BOOT MAZDA EMBLEM	Necessary	25.20 FL	*25.20 FL
8	1		*REAR BOOT LOGO	Necessary	62.60 FL	*62.60 FL
9	2		*REAR BOOT LAMPS	Not Necessary	523.00 FL	*- FL
10	2		*REAR NUMBER PLATE LAMPS	Not Necessary	417.60 FL	*- FL
11	1		*REAR TAILLAMPS	N/s Cracked	2,076.80 FL	*365.00 FL
12	2		*REAR TAILLAMP PANELS	Repair	204.00 FL	*- FL
13	1		*REAR END PANEL	Dented	357.00 FL	*357.00 FL
14	1		*REAR END PANEL INNER GARNISH	Twisted	212.50 FL	*212.50 FL
15	1		*REAR BUMPER	Dented	1,026.70 FL	*862.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Dented	547.00 FL	*547.00 FL
17	2		*REAR BUMPER SIDE RETAINERS	Bent	77.20 FL	*77.20 FL
18	2		*REAR BUMPER REFLECTORS	Not Necessary	124.00 FL	*- FL
19	1		*REAR FLOOR BOARD	Not Necessary	411.20 FL	*- FL
20	1		*REAR FLOOR PANEL	Repair	2,221.00 FL	*- FL
21	1		*REAR EXHAUST SILENCER	Repair	953.80 FL	*- FL
22	2		*REAR EXHAUST MOUNTINGS	Not Necessary	91.00 FL	*- FL
23	1		*REAR FENDER-LH	Repair	1,091.00 FL	*- FL
24	1		*REAR FENDER AIR GATE	Not Necessary	41.50 FL	*- FL
25	2		*REAR FENDER INNER TRIMS	Not Necessary	385.30 FL	*- FL
26	2		*REAR FENDER INNER SHIELDS	Not Necessary	97.00 FL	*- FL
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
29	1		*REAR NUMBER PLATE	Cracked	50.00 FS	*40.00 FS
30	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,162.30	4,135.70
- List Item Discount on L Items 20.00/20.00% (S\$)	2,527.46	770.14
Total Parts (S\$)	10,634.84	3,365.56

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	-
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
5	TO TRANSFER REAR BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
6	TO REMOVE,REPLACE AIR-CON CONDENSER,REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	-
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	-
8	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	60.00
9	TO APPLY UNDERCOATING	New	250.00	60.00
10	PANEL BEATING	New	2,500.00	1,080.00
11	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,400.00	1,500.00
Gross Labour Cost (S\$)			6,210.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >