
REF:

ASSIGNMENT

CSE 2024 Dec

Dec 2016

From:

Date:

Estimated Cost:

Veh No:

SHC 1285C

Yr Regt:

Dec 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry ☒ Taxi Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

Make:

Hyundai I40

G.C.

1685

at Workshop m/s:

Colour:

Blue

A/C

Insured / Std / NI / NA

of

Sp. Reading

190381

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

D4FDGU694113

Policy No:

C/No:

KMHLEB41UMHU097152

Claims No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:


F:

205/60 R16

R:

11

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Campeon

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR. Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

10/12/20

days

Res.: Yes or No

D.O.A.

23/12/2018

D.O.I.

27/12/2018

Lump Sum:

3 Val.: Yes or No

Survey held at

Chunni AMK

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

H/S Rev

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Burst 11 SHC 10942

22/01/19 Jharna 2/S 109501 - with 12 days of repair

(RED: + 6.686.93 38%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18023194/Deb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 27-12-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1094L	Veh. Inspected	SHC 1285C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/12/2018	Inspection Date		
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 1285C

DATE : 24.12.2018

MAKE :

TEL : 6542 5119


MODEL : HYUNDAI i40

FAX : 6542 6039

INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>mounty broken / distorted</i>			\$ 553.00	✓
	Rear Bumper Clip 10 pcs <i>huc</i>			\$ 22.00	✓
	Rear Bumper Bracket, LH <i>SL</i>			\$ 35.60	X
	Tail Lamp (LH) <i>CRACK</i>			\$ 697.80	✓
	Rear Fender With Housing (LH) <i>Buc</i>			\$ 4,736.80	✓
	Rear Fender Inner Lining (LH) <i>deformed</i>			\$ 169.30	✓
	Rear Fender Air-Duct <i>HH</i>			\$ 51.60	X
	Rear Windscreen Moulding <i>huc</i>			\$ 28.30	✓
	Fuel Tank <i>HH</i>			\$ 962.90	X
	Rear Door (LH) <i>Buc</i>			\$ 2,201.10	✓
	Rear Door Gear/Regulator (LH) <i>mounty broken</i>			\$ 242.80	✓
	Rear Door Power Motor (LH) <i>HH</i>			\$ 158.60	X
	Rocker Panel Outer Garnish (LH) <i>St</i>			\$ 341.40	✓
	Rocker Panel Outer <i>may Deformed</i>			\$ 1,310.60	✓
	Rear Tyre Rim (LH) <i>St</i>			\$ 325.30	✓
	Rear Wheel Hup-Cap (LH) <i>CRACK</i>			\$ 107.10	✓
	Rear Wheelbearing ING & Hub <i>St Dam</i>			\$ 362.00	✓
	Rear Trailing Arm (LH) <i>St distorted</i>			\$ 192.00	✓
	Rear Assist (LH) <i>St distorted</i>			\$ 145.70	✓
	Rear Shock Absorber (LH) <i>St</i>			\$ 276.30	✓
	Rear Shock Absorber Mounting (LH) <i>HH</i>			\$ 81.30	X
	Rear Crossmember <i>St</i>			\$ 1,021.50	✓
	Stabilizer Bar <i>St</i>			\$ 199.60	✓
	Stabilizer Link <i>St</i>			\$ 85.90	✓
	Rear Upper Arm (LH) <i>St</i>			\$ 335.75	✓
	Rear Lower Arm (LH) <i>St</i>			\$ 353.80	✓
	Rear Knuckle Arm (LH) <i>St distorted</i>			\$ 545.60	✓
			14253.65		
			11402.92		
	SUB TOTAL			\$ 15,543.65	
	LESS 20%			\$ 3,108.73	
	DISCOUNTED TOTAL			\$ 12,434.92	
	Rear Windscreen Sealant <i>huc</i>			\$ 46.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>huc</i>			\$ 80.00	Nett ✓
	Rear Tyre (LH) <i>cut 50% deprent</i>			\$ 216.00	Nett ✓
			234.00	108.00	
				\$ 342.00	

SHC 1285C

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 800/-
	Spray Painting Charge			\$ 1,250.00 700/-
	Wiring Charge			\$ 50.00 20/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 4/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Fuel Tank			\$ 150.00 4/-
	Transfer of Door			\$ 120.00 60/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00 4/-
	Re-set Rear Power Window System			\$ 200.00 4/-
	Diagnostic & Resetting To Erase Fault Code		2030.80	\$ 480.00 4/-
	TOTAL LABOUR			\$ 4,810.00
	ESTIMATE TOTAL			\$ 17,586.92
	27/12/2018 @ 1145hrs		13666.92	
	N/A Actual			
	215hrs @ 12 days.		1/5 10900/-	
	 Ryan			
	LKK Auto			
				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 26 December, 2018 5:40 PM
To: Chunni Motor; Catherine Chong (LKK Auto); 'sur@lkkauto.com'
Cc: Pooi Chin Han Daniel
Subject: RE: Accident involving veh no: SHC 1285C & SHC 1094L on 23.12.18
Attachments: 26122018094651.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHC1094L and let us have your report urgently.

This claim will be handled by

*Kindly upload this survey request email to merimen.

Thank You.

Bryan

Warmest regards,

Stanley Lai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: Wednesday, 26 December, 2018 2:57 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: Accident involving veh no: SHC 1285C & SHC 1094L on 23.12.18

Dear Sir,

We appoint LKK Auto Consultants P/L

Thank you

Regards,

Chunni Motor Work P/L

On Wed, Dec 26, 2018 at 11:43 AM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 10 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Warmest regards,

Stanley Lai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: Wednesday, 26 December, 2018 9:55 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Accident involving veh no: SHC 1285C & SHC 1094L on 23.12.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.
Registration No. 198703792-K

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	27 Dec 2018 16:53	Clim Veh Model Changed	(204155) HYUNDAI I40 1.7 D (A).	[A] Lau Shu Pei
2	27 Dec 2018 16:53	Clim Created	Reg No: SHC1285A. Acct Date: 2018/12/23. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: India International Insurance Pte Ltd (HQ). Workshop: Chunni Motor Work Pte Ltd (HQ)	[A] Lau Shu Pei
3	27 Dec 2018 16:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	27 Dec 2018 16:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/08	[A] Lau Shu Pei
5	27 Dec 2018 16:53	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	27 Dec 2018 16:53	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	27 Dec 2018 16:53	Adj Adjuster Assigned	[None] -> BRYAN TANI	[A] Lau Shu Pei
8	03 Jan 2019 11:02	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	03 Jan 2019 11:02	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	03 Jan 2019 16:49	Clim Registration Modified	Reg No:SHC1285A->SHC1285C.	[A] Lau Shu Pei
11	26 Jan 2019 21:04	Adj Mandate Request	Cur.Req:0.00:PODS: LIABILITY: 100% REMARK: B:NIL OID TRAVEL STRAIGHT WITH RED LIGHT	[A] Asher Sng Rong Yi
12	28 Jan 2019 16:51	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/01/08. Mandate Remarks: Agreed to do direct settlement. Please revert with your quantum advic	[I] Sundari Nagarajan
13	28 Jan 2019 16:51	Adj Mandate Set	Approved:0.00:Agreed to do direct settlement. Please revert with your quantum advic	[I] Sundari Nagarajan
14	11 Feb 2019 10:40	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
15	11 Feb 2019 10:40	Clim Dtl Modified	Claimant's ID: -> -,	[A] NUR SHAQILAH BTE ABDOL WAHAB
16	11 Feb 2019 10:40	Clim Dtl Modified	JPJ Reg. Date: -> 2016/12/08.	[A] NUR SHAQILAH BTE ABDOL WAHAB
17	11 Feb 2019 10:40	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
18	14 Feb 2019 09:34	Adj Mandate Request	Cur.Req:14065.50:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST: \$11,663.00 + (b) LOR : \$1,782.50 (15.5days x \$115) + (c) LOI \$620.00 (15.5days x \$40) Total: a+b+c = \$14,065.50 VEH MODEL: HYUNDAI I40E 1685cc PLEASE REVERT WITH YOUR APPROVAL / MAND	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2041950	28/01/2019 08:54	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SHC1285C	Pooi Chin Han Daniel	xx.xx
2051934	11/02/2019 10:40	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHC1285C	SHC1094L	10.70

Print Received Message

This mail is associated with :

***SHC1285C (MCT18120661)**
[SHC1094L]

TP

COMFORT TRANSPORTATION PTE LTD

Dec 23 2018 2:00PM

[COMFORT TRANSPORTATION PTE LTD]

Chunni Motor Work Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 22/03/2019 10:01 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8500.00) - SHC1285C - Claim Handler: Pooi Chin Han Daniel

Approved:8500.00.

Print Received Message

This mail is associated with :

***SHC1285C (MCT18120661)**
[SHC1094L]

TP

COMFORT TRANSPORTATION PTE LTD

Dec 23 2018 2:00PM

[COMFORT TRANSPORTATION PTE LTD]

Chunni Motor Work Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 16/04/2019 16:37 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11500.00) - SHC1285C - Claim Handler: Pooi Chin Han Daniel

Approved:11500.00.

Our Ref : SHC 1285 C (231218)

Your Ref : CC4/III18023194/Deb3

Date : 29 April 2019

M/s LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
#02-25
Ubi Avenue 1
Singapore 408933

WITHOUT PREJUDICE

Attention : Asher Sng
Case Handler

**ACCIDENT INVOLVING SHC 1285 C & SHC 1094 L ALONG TELOK BLANGAH JUNCTION OF
SENTOSA GATEWAY ON 23-12-2018**

Your email of 26 April 2019 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair and loss of income and rental during the period of repair) at a global sum of \$11,500.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the relief driver of SHC 1285 C, Sim Kim Khoo's injury claim and other losses against your insured, if any.

As requested, we return the attached Discharge Voucher duly executed together with original documents for your onward transmission.

Kindly expedite payment and forward us your cheque for the settlement sum of **\$11,500.00** made in favour of **M/s Chunni Motor Work Pte Ltd** as soon as possible.

Thank you.

Your faithfully

For **Chunni Motor Work Pte Ltd**

Claims Department

Enc

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2019 Edit Reg		26 Dec 2018 00:00 Edit Adj Rpt	\$S\$10,900.00 Edit Estimates	\$S\$10,900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC1285C	Date of Loss:	23/12/2018 14:00 - :59 [24 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18120661	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SHC1094L	Policy No. (Claimant):	MCOM0015
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 08/01/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (16/04/2019): Alert - Adj Mandate Approved (\$S\$11500.00) - SHC1285C - Claim Handler: Pooi Chin ...
- III_SG (09/04/2019): Alert - Adj Mandate Maintained - SHC1285C - Claim Handler: Pooi Chin Han Daniel
- III_SG (22/03/2019): Alert - Adj Mandate Approved (\$S\$8500.00) - SHC1285C - Claim Handler: Pooi Chin H...
- III_SG (12/03/2019): Alert - Adj Mandate Approved (\$S\$0.00) - SHC1285C - Claim Handler: Pooi Chin Han ...
- III_SG (26/02/2019): Alert - Adj Mandate Approved (\$S\$0.00) - SHC1285C - Claim Handler: Pooi Chin Han ...
- III_SG (28/01/2019): Alert - Adj Mandate Approved (\$S\$0.00) - SHC1285C - Claim Handler: Pooi Chin Han ...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC1285C (MCT18120661)**
[SHC1094L]

TP

COMFORT TRANSPORTATION PTE LTD

Dec 23 2018 2:00PM

[COMFORT TRANSPORTATION PTE LTD]

Chunni Motor Work Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Video

No	Finalized On	India International Insurance Pte Ltd (HQ)	1 per page ▼	Thumbnail	Print
1	28/01/19 08:54	Video - Accident IV		Load MP4	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	19/01/19 14:08	Rear View Right		Load JPG	
2	19/01/19 14:08	Rear View Left		Load JPG	
3	19/01/19 14:09	General View		Load JPG	
4	19/01/19 14:09	General View		Load JPG	
5	19/01/19 14:09	General View		Load JPG	
6	19/01/19 14:09	General View		Load JPG	
7	19/01/19 14:09	General View		Load JPG	
8	19/01/19 14:09	General View		Load JPG	
9	19/01/19 14:09	General View		Load JPG	
10	19/01/19 14:09	General View		Load JPG	
11	19/01/19 14:09	General View		Load JPG	
12	19/01/19 14:09	General View		Load JPG	
13	19/01/19 14:09	General View		Load JPG	
14	19/01/19 14:09	General View		Load JPG	
15	19/01/19 14:09	General View		Load JPG	
16	19/01/19 14:09	General View		Load JPG	
17	19/01/19 14:09	General View		Load JPG	
18	19/01/19 14:09	General View		Load JPG	
19	19/01/19 14:09	General View		Load JPG	
20	19/01/19 14:09	General View		Load JPG	
21	19/01/19 14:09	General View		Load JPG	
22	19/01/19 14:09	General View		Load JPG	
23	19/01/19 14:09	General View		Load JPG	
24	19/01/19 14:09	General View		Load JPG	
25	19/01/19 14:09	General View		Load JPG	
26	19/01/19 14:09	General View		Load JPG	
27	19/01/19 14:09	General View		Load JPG	
28	19/01/19 14:09	General View		Load JPG	
29	19/01/19 14:09	General View		Load JPG	
30	19/01/19 14:09	General View		Load JPG	
31	19/01/19 14:09	General View		Load JPG	
32	19/01/19 14:09	General View		Load JPG	

Video			1 per page ▾	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
33	19/01/19 14:09	General View	 Load JPG	☒
34	19/01/19 14:09	General View	 Load JPG	☒
35	19/01/19 14:09	General View	 Load JPG	☒
36	19/01/19 14:09	General View	 Load JPG	☒
37	19/01/19 14:09	General View	 Load JPG	☒
38	19/01/19 14:09	General View	 Load JPG	☒
39	19/01/19 14:09	Odometer Reading	 Load JPG	☒
40	19/01/19 14:09	Chassis Number	 Load JPG	☒
41	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
42	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
43	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
44	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
45	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
46	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
47	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
48	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
49	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
50	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
51	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
52	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
53	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
54	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
55	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
56	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
57	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
58	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
59	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
60	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
61	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
62	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
63	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
64	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
65	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
66	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
67	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
68	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
69	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
70	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
71	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
72	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
73	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
74	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
75	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
76	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
77	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
78	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
79	19/01/19 14:10	Reinspection Photo	 Load JPG	☒
80	19/01/19 14:10	Reinspection Photo	Load JPG	☒

Video			1 per page ▾	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
81	19/01/19 14:10	Reinspection Photo	Load JPG	✓
82	19/01/19 14:10	Reinspection Photo	Load JPG	✓
83	19/01/19 14:10	Reinspection Photo	Load JPG	✓
84	19/01/19 14:10	Reinspection Photo	Load JPG	✓
85	19/01/19 14:10	Reinspection Photo	Load JPG	✓
86	19/01/19 14:10	Reinspection Photo	Load JPG	✓
87	19/01/19 14:10	Reinspection Photo	Load JPG	✓
88	19/01/19 14:10	Reinspection Photo	Load JPG	✓
89	19/01/19 14:10	Reinspection Photo	Load JPG	✓
90	19/01/19 14:10	Reinspection Photo	Load JPG	✓
91	19/01/19 14:10	Reinspection Photo	Load JPG	✓
92	19/01/19 14:10	Reinspection Photo	Load JPG	✓
93	19/01/19 14:10	Reinspection Photo	Load JPG	✓
94	19/01/19 14:10	Reinspection Photo	Load JPG	✓
95	19/01/19 14:11	Finishing Photo	Load JPG	✓
96	19/01/19 14:11	Finishing Photo	Load JPG	✓
97	19/01/19 14:11	Finishing Photo	Load JPG	✓
98	19/01/19 14:11	Finishing Photo	Load JPG	✓
99	19/01/19 14:11	Finishing Photo	Load JPG	✓
100	19/01/19 14:11	Finishing Photo	Load JPG	✓
101	19/01/19 14:11	Finishing Photo	Load JPG	✓
102	19/01/19 14:11	Finishing Photo	Load JPG	✓
103	19/01/19 14:11	Finishing Photo	Load JPG	✓
104	19/01/19 14:11	Finishing Photo	Load JPG	✓
105	19/01/19 14:11	Finishing Photo	Load JPG	✓
106	19/01/19 14:11	Finishing Photo	Load JPG	✓
107	19/01/19 14:11	Finishing Photo	Load JPG	✓
108	19/01/19 14:11	Finishing Photo	Load JPG	✓
109	19/01/19 14:11	Finishing Photo	Load JPG	✓
110	19/01/19 14:11	Finishing Photo	Load JPG	✓
111	19/01/19 14:11	Finishing Photo	Load JPG	✓
112	19/01/19 14:11	Finishing Photo	Load JPG	✓
113	19/01/19 14:11	Finishing Photo	Load JPG	✓
114	19/01/19 14:11	Finishing Photo	Load JPG	✓
Documentation			1 per page ▾	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/12/18 16:53	EMAIL FROM III DD 26122018	Load PDF	
2	27/12/18 16:53	TP EST & GIA REPORT	Load PDF	
3	04/01/19 09:27	TP ESTIMATE- MARKED	Load PDF	
4	11/02/19 10:58	LOD	Load PDF	
5	11/02/19 10:58	RENTAL MILEAGE	Load PDF	
6	11/02/19 10:58	RENTAL RECEIPT	Load PDF	
7	11/02/19 10:58	WORKSHOP INVOICE	Load PDF	
8	04/04/19 16:44	EMAIL FROM WSP DD 270319	Load PDF	
9	14/05/19 13:17	AUTHORISATION TO ACT	Load PDF	
10	14/05/19 13:17	DISCHARGE VOUCHER	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	28/12/18 08:30	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18023194/DEB3S2

Date: 14/05/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHC1285C	Insured Vehicle No :	SHC1094L
Date of Loss:	23/12/2018	Nature of Claim:	TP
		Claim No:	MCT18120661

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1285C	Engine No:	D4FDGU694113
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMHU097152
Reg. Date:	08/12/2016 (Man. Year: 2016)	Odometer:	190381 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Campeon 5 mm	Rear Left Side:	Campeon 5 mm
Front Right Side:	Campeon 5 mm	Rear Right Side:	Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,776.92	11,636.92	1,140.00	8.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,810.00	2,030.00	2,780.00	57.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,586.92	13,666.92	3,920.00	22.29
Approved Total (Overridden) (\$\$)		10,900.00		
(\$\$)	17,586.92	10,900.00	6,686.92	38.02
+ GST 7.00/7.00% (\$\$)	1,231.08	763.00	468.08	38.02
Nett Amount (\$\$)	18,818.00	11,663.00	7,155.00	38.02
+ Loss of Use (15.5 x S\$40.00/day) (\$\$)		620.00		
+ Car Rental (15.5 x S\$115.00/day) (\$\$)		1,782.50		
Nett Liability (\$\$)		14,065.50		
Global Sum Settlement (\$\$)		11,500.00		

INSPECTION

Date of Assignment: 26/12/2018

Date Inspected: 27/12/2018 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 12.0 days

Adjuster: BRYAN TANI

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2019)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1285C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Broken / Distorted	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER BRACKET, LH	Serviceable	35.60 FL	*- FL
4	1		*TAIL LAMP (LH)	Cracked	697.80 FL	*697.80 FL
5	1		*REAR FENDER WITH HOUSING (LH)	Buckled	4,736.80 FL	*4,736.80 FL
6	1		*REAR FENDER INNER LINING (LH)	Deformed	169.30 FL	*169.30 FL
7	1		*REAR FENDER AIR-DUCT	Not Necessary	51.60 FL	*- FL
8	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
9	1		*FUEL TANK	Not Necessary	962.90 FL	*- FL
10	1		*REAR DOOR (LH)	Buckled	2,201.10 FL	*2,201.10 FL
11	1		*REAR DOOR GEAR / REGULATOR (LH)	Mtg Broken	242.80 FL	*242.80 FL
12	1		*REAR DOOR POWER MOTOR (LH)	Not Necessary	158.60 FL	*- FL
13	1		*ROCKER PANEL OUTER GARNISH (LH)	Bent	341.40 FL	*341.40 FL
14	1		*ROCKER PANEL OUTER	Dented	1,310.60 FL	*1,310.60 FL
15	1		*REAR TYRE RIM (LH)	Bent	325.30 FL	*325.30 FL
16	1		*REAR WHEEL HUP-CAP (LH)	Cracked	107.10 FL	*107.10 FL
17	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
18	1		*REAR TRAILING ARM (LH)	Distorted	192.00 FL	*192.00 FL
19	1		*REAR ASSIST (LH)	Distorted	145.70 FL	*145.70 FL
20	1		*REAR SHOCK ABSORBER (LH)	Bent	276.30 FL	*276.30 FL
21	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	81.30 FL	*- FL
22	1		*REAR CROSSMEMBER	Bent	1,021.50 FL	*1,021.50 FL
23	1		*STABILIZER BAR	Bent	199.60 FL	*199.60 FL
24	1		*STABILIZER LINK	Bent	85.90 FL	*85.90 FL
25	1		*REAR UPPER ARM (LH)	Bent	335.75 FL	*335.75 FL
26	1		*REAR LOWER ARM (LH)	Bent	353.80 FL	*353.80 FL
27	1		*REAR KNUCKLE ARM (LH)	Distorted	545.60 FL	*545.60 FL
28	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
29	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
30	1		*REAR TYRE (LH) (50%)	Cut	216.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,885.65 14,487.65
- List Item Discount on L Items 20.00/20.00% (\$\$) 3,108.73 2,850.73

Total Parts (\$\$) 12,776.92 11,636.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	1,500.00	800.00
2	SPRAY PAINTING CHARGE.	New	1,250.00	700.00
3	WIRING CHARGE.	New	50.00	20.00
4	TUFF KOTE.	New	100.00	40.00
5	TOWING CHARGE.	New	50.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	80.00
8	REMOVE / REFIX REVERSE SENSOR.	New	120.00	40.00
9	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
10	TRANSFER OF DOOR.	New	120.00	60.00
11	REMOVE / REFIX UNDERCARRIAGE (RR).	New	200.00	150.00
12	REAR WHEEL ALIGNMENT.	New	120.00	60.00
13	RE-SET REAR ABS SYSTEM.	New	200.00	0.00
14	RE-SET REAR POWER WINDOW SYSTEM.	New	200.00	0.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	New	480.00	0.00
Gross Labour Cost (S\$)			4,810.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >