

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 1285C

DATE : 24.12.2018

MAKE :

TEL : 6542 5119


MODEL : HYUNDAI i40

FAX : 6542 6039

INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper mounting broken / distorted			\$ 553.00 ✓
	Rear Bumper Clip 10 pcs H/c			\$ 22.00 ✓
	Rear Bumper Bracket, LH S/c			\$ 35.60 X
	Tail Lamp (LH) C/W/C			\$ 697.80 ✓
	Rear Fender With Housing (LH) B/c			\$ 4,736.80 ✓
	Rear Fender Inner Lining (LH) deformed			\$ 169.30 ✓
	Rear Fender Air-Duct H/H			\$ 51.60 X
	Rear Windscreen Moulding H/c			\$ 28.30 ✓
	Fuel Tank H/H			\$ 962.90 X
	Rear Door (LH) B/c			\$ 2,201.10 ✓
	Rear Door Gear/Regulator (LH) B/c mounting broken			\$ 242.80 B/c ✓
	Rear Door Power Motor (LH) H/H			\$ 158.60 X
	Rocker Panel Outer Garnish (LH) B/c			\$ 341.40 ✓
	Rocker Panel Outer H/c deformed			\$ 1,310.60 B/c ✓
	Rear Tyre Rim (LH) B/c B/c			\$ 325.30 B/c ✓
	Rear Wheel Hup-Cap (LH) C/W/C			\$ 107.10 ✓
	Rear Wheelbearing ING & Hub B/c Deformed			\$ 362.00 B/c ✓
	Rear Trailing Arm (LH) B/c distorted			\$ 192.00 B/c ✓
	Rear Assist (LH) B/c distorted			\$ 145.70 B/c ✓
	Rear Shock Absorber (LH) B/c B/c			\$ 276.30 B/c ✓
	Rear Shock Absorber Mounting (LH) H/H			\$ 81.30 X
	Rear Crossmember B/c B/c			\$ 1,021.50 B/c ✓
	Stabilizer Bar B/c B/c			\$ 199.60 B/c ✓
	Stabilizer Link B/c B/c			\$ 85.90 B/c ✓
	Rear Upper Arm (LH) B/c B/c			\$ 335.75 B/c ✓
	Rear Lower Arm (LH) B/c B/c			\$ 353.80 B/c ✓
	Rear Knuckle Arm (LH) B/c distorted			\$ 545.60 B/c ✓
	SUB TOTAL			\$ 15,543.65
	LESS 20%			\$ 3,108.73
	DISCOUNTED TOTAL			\$ 12,434.92
	Rear Windscreen Sealant H/c			\$ 46.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) H/c			\$ 80.00 Nett ✓
	Rear Tyre (LH) cut 50% deformed			\$ 216.00 Nett ✓ 108.00
				\$ 342.00

SHC 1285C

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 800/-
	Spray Painting Charge			\$ 1,250.00 700/-
	Wiring Charge			\$ 50.00 20/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Fuel Tank			\$ 150.00 40/-
	Transfer of Door			\$ 120.00 60/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00 40/-
	Re-set Rear Power Window System			\$ 200.00 40/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 40/-
	TOTAL LABOUR			\$ 4,810.00
	ESTIMATE TOTAL			\$ 17,586.92
	27/12/2018 @ 1145hrs N/A Actual 2/5 hrs 7 days.  Ryan LKK Auto 			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			