



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2018 SKODA KODIAQ 1.4 TSI (SMD9891K)

Date of Loss 21 December 2018

Time of Loss 23.30

Loss Description SMD9891K (INSD) C/W SHD2520L (TP)

Comment

Workshop Details

Total Rebate Amount 53545

Nett Loss Amount \$56,455.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 80



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SMD9891K

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

13/09/2018



Mileage

7135

Age of Vehicle

0

Driver Details

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2018

2018

Make

SKODA

SKODA

Model

KODIAQ 1.4 TSI

KODIAQ 1.4 TSI A

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

YEE MEI LIAN ELIZA (YU
MEILIAN)

Date of Birth

8 June 1984

dd/mm/yyyy



Age

34

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	TMBKC7NS1J8098347	TMBKC7NS1J8098347
Engine No	CZE821178	CZE821178
Engine Capacity		1395
Sum Insured	0	0
Market Value	0	110000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	13	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy
License Expiration Date		dd/mm/yyyy
Address	1 PASIR RIS RISE, #05-02, 518080, Singapore	
Address type	Residential	

Gender

Female

Marital
status

Married

Identification
#

S8416943I



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

28/12/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

750

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

235/55R18

Rear Tyre Size

235/55R18

Front left side

PIRELLI9mm

Rear left side

PIRELLI9mm

Front right side

PIRELLI9mm

Rear right side

PIRELLI9mm

Assessment Details



- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

Dep'r./Bttr%		Salvage%	
--------------	----------------------	----------	----------------------

Discount%		Settlement%	100
-----------	----------------------	-------------	----------------------------------

Paint Labour/Material Ratio

Paint Labour Ratio	20	Paint Material Ratio	80
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			BUMPER BRACKET LH			Serviceable	0	0	0	0	0	Deny	
		2	1			FRT BUMPER			Deformed	1292.84				1292.84	Reviewing	
		3	1			SUPPORT ELEMENT LEFT			Serviceable	0	0	0	0	0	Deny	
		4	1			FRONT LHS FENDER			Repair	0	0	0	0	0	Deny	
		5	1			FENDER BRACKET LH			Serviceable	0	0	0	0	0	Deny	
		6	1			FENDER BRACKET UPPER LH			Serviceable	0	0	0	0	0	Deny	
		7	1			LATCH LH			Serviceable	0	0	0	0	0	Deny	
		8	1			BONNET LOCK			Serviceable	0	0	0	0	0	Deny	
		9	1			BONNET SEAL			Serviceable	0	0	0	0	0	Deny	
		10	9			GROMMET			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		11	1			SENSOR O-RING			Necessary	1.2				1.2	Reviewing	
		12	1			BUMPER LOWER SPOILER			Cut	340.63				340.63	Reviewing	
		13	1			FRONT FOG LIGHT GRILLE LEFT			Damaged	38.53				38.53	Reviewing	
		14	1			FRONT BONNET			Buckled	2478.24				2478.24	Reviewing	
		15	1			FRONT BONNET SKODA EMBLE			Necessary	38.49				38.49	Reviewing	
		16	1			RADIATOR GRILLE			Damaged	270.79				270.79	Reviewing	
		17	1			FOG LAMP GRILLE SENSOR TRIM			Serviceable	0	0	0	0	0	Deny	
		18	1			CENTRE LOWER GRILLE			Serviceable	0	0	0	0	0	Deny	
		19	1			RADIATOR GRILLE CHROME			Serviceable	215.22				215.22	Reviewing	
		20	1			FENDER PROTECTOR LH			Damaged	121.25				121.25	Reviewing	
		21	1			SENSOR BRACKET LH			Necessary	14.92				14.92	Reviewing	
		22	1			SENSOR BRACKET RH			Necessary	14.92				14.92	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		23	1			FRONT LHS HEADLAMP ASSY			Cracked	1821.82				1821.82	Reviewing	
		24	1			2KADHESIVE			Necessary	64.68				64.68	Reviewing	
		25	1			BONDAGENT			Necessary	46.28				46.28	Reviewing	
		26	2			SPEED NUT			Necessary	0.33				0.66	Reviewing	

Labour

Add	Approve	Deny	Submit All							
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		LABOUR	1740	0	0	Reviewing		
		2		SPRAY PAINT	2500	0	0	Reviewing		
		3		PROGRAMMING & CALIBRATION	360	0	0	Reviewing		
		4		CHECK WIRE HARNESS, ECU, S	200	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 7 DAYS	Reviewing			
		2	WIPER TANK	Reviewing	110.96	CRACKED (SUPPLEMENTARY)	
		3	GASKET	Reviewing	1.04	NECESSARY (SUPPLEMENTARY)	
		4	WINDSHIELD CLEANER 1 LITRE BTL	Reviewing	14.74	NECESSARY (SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		5	LHS LOCK CARRIER SIDE PANEL	Reviewing	41.93	BENT (SUPPLEMENTARY)	
		6	FOAM FILLER	Reviewing	29.56	CRACKED (SUPPLEMENTARY)	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$11,008.70

Claim Amount

\$11,008.70

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$6,760.47

\$6,760.47

Labour

\$4,800.00

\$4,800.00

Miscellaneous

\$198.23

\$198.23

Excess

-\$750.00

-\$750.00

[Submit for Review](#)