

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 22 TAMPINES ST 92 (S  
528876)

Jimmy Goh KI  
CLAIM DEPARTMENT  
DID : 66547618  
FAX :

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.  
Certificate No : PNPV2018-00008174 Accident Date : 24/12/2018  
Vehicle No : SKS-8483-G Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|-------------|-------------------|---------------|
|-----|-------------|-------------------|---------------|

#### List Item

|    |                           |          |   |
|----|---------------------------|----------|---|
| 1  | FRONT WINDSCREEN GLASS    | 1,644.70 | ✓ |
| 1  | FRONT WINDSCREEN MOULDING | 86.70    | ✓ |
| 1  | BONNET                    | 574.20   | ✓ |
| 1  | BONNET HINGE LH           | 65.40    | ✓ |
| 1  | BONNET HINGE RH           | 65.40    | ✓ |
| 1  | BONNET WEATHER STRIP      | 42.80    | ✓ |
| 1  | BONNET INSULATOR          | 105.40   | ✓ |
| 10 | BONNET INSULATOR CLIPS    | 55.00    | ✓ |
| 1  | BONNET LOCK               | 118.70   | ✓ |

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174

Accident Date : 24/12/2018

Vehicle No : SKS-8483-G

Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                     | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|---------------------------------|-------------------|---------------|
| 1   | FRONT GRILLE BASE               | CM 165.40         | /             |
| 1   | FRONT GRILLE CHROME MOULDING    | CM 192.90         | /             |
| 1   | FRONT GRILLE LOGO               | nu 42.80          | /             |
| 4   | FRONT GRILLE CLIPS              | nee 18.00         | /             |
| 1   | FRONT BUMPER 638                | D.S 856.50        | /             |
| 1   | FRONT BUMPER SIDE RETAINER (LH) | sy 26.80          | /             |
| 1   | FRONT BUMPER SIDE RETAINER (RH) | sy 26.80          | /             |
| 1   | FRONT BUMPER REINFORCEMENT      | sy 276.50         | /             |
| 1   | FRONT BUMPER NUMBER PLATE BASE  | de 50.80          | /             |
| 10  | FRONT BUMPER CLIPS 30           | nu 45.00          | /             |

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174

Accident Date : 24/12/2018

Vehicle No : SKS-8483-G

Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                     | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|---------------------------------|-------------------|---------------|
| 1   | FOG LAMP COVER LH               | 7m 65.90          | /             |
| 1   | FOG LAMP COVER RH               | 7m 65.90          | /             |
| 1   | HEADLAMP (LH)                   | cm 942.10         | /             |
| 1   | HEADLAMP LOWER BRACKET LH       | 3m 50.70          | /             |
| 1   | HEADLAMP (RH)                   | cm 942.10         | /             |
| 1   | HEADLAMP LOWER BRACKET RH       | 3m 50.70          | /             |
| 1   | FRONT SUPPORT PANEL             | 3m 617.80         | /             |
| 1   | FRONT SUPPORT TOP GARNISH       | 7.5 105.40        | /             |
| 10  | FRONT SUPPORT TOP GARNISH CLIPS | 2m 45.00          | /             |
| 2   | FRONT SUPPORT TOP STOPPER       | 11 30.40          | X             |

440.50

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.  
Certificate No : PNPV2018-00008174 Accident Date : 24/12/2018  
Vehicle No : SKS-8483-G Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                   | REPAIRER AMT (\$)     | SURVEYOR APP.     |
|-----|-------------------------------|-----------------------|-------------------|
| 1   | FRONT CHASSIS MEMBER LH       | RESTORE               | <i>2</i> <i>X</i> |
| 1   | FRONT CHASSIS MEMBER RH       | RESTORE               | <i>2</i> <i>X</i> |
| 1   | AIR DUCT TOP                  | <i>11</i> 202.60      | <i>2</i> <i>X</i> |
| 1   | HORN LH                       | <i>11</i> 69.40       | <i>2</i> <i>X</i> |
| 1   | HORN RH                       | <i>11</i> 69.40       | <i>2</i> <i>X</i> |
| 1   | BATTERY TRAY                  | <i>11</i> 35.80       | <i>2</i> <i>X</i> |
| 1   | BATTERY BRACKET               | <i>11</i> 25.80       | <i>2</i> <i>X</i> |
| 1   | WIPER WASHER TANK             | <i>11</i> 113.40      | <i>2</i> <i>X</i> |
| 1   | AIRCON CONDENSOR ASSY         | <i>Bel/p11</i> 816.50 | <i>2</i> <i>X</i> |
| 1   | AIRCON CONDENSOR AIR GUIDE LH | <i>2</i> 25.30        | <i>2</i> <i>X</i> |

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174

Accident Date : 24/12/2018

Vehicle No : SKS-8483-G

Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                   | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|-------------------------------|-------------------|---------------|
| 1   | AIRCON CONDENSOR AIR GUIDE RH | 25.30             | ✓             |
| 1   | AIRCON PIPE (COND TO COMP)    | 241.20            | ✓             |
| 1   | AIRCON PIPE (COND TO COIL)    | 205.90            | ✓             |
| 1   | AIRCON FAN MOTOR              | 364.70            | ✓             |
| 1   | AIRCON FAN BLADE              | 69.40             | ✓             |
| 1   | AIRCON FAN COWLING            | 118.90            | ✓             |
| 1   | RADIATOR ASSY                 | 1,361.20          | ✓             |
| 1   | RADIATOR TOP BRACKET LH       | 17.20             | ✓             |
| 1   | RADIATOR TOP BRACKET RH       | 17.20             | ✓             |
| 1   | RADIATOR UPPER HOSE           | 45.80             | ✓             |

Date : 27/12/2018

To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174

Accident Date : 24/12/2018

Vehicle No : SKS-8483-G

Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                    | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|--------------------------------|-------------------|---------------|
| 1   | RADIATOR LOWER HOSE            | 11 47.20          | X             |
| 1   | RADIATOR FAN MOTOR             | 371.80            | 7             |
| 1   | RADIATOR FAN BLADE             | 81.40             | 7             |
| 1   | RADIATOR FAN COWLING           | 131.80            | ?             |
| 1   | FRONT FENDER (LH)              | 2uc 632.90        | —             |
| 1   | FRONT FENDER TOP GARNISH LH    | 11 57.20          | X             |
| 1   | FRONT FENDER INNER SHIELD (LH) | 2c/711 118.90     | —             |
| 1   | FRONT FENDER (RH)              | 3uc 632.90        | —             |
| 1   | FRONT FENDER TOP GARNISH RH    | 11 57.20          | X             |
| 1   | FRONT FENDER INNER SHIELD (RH) | 2c/711 118.90     | —             |

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174 Accident Date : 24/12/2018  
Vehicle No : SKS-8483-G Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                     | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|---------------------------------|-------------------|---------------|
| 18  | FRONT FENDER INNER SHIELD CLIPS | 17 81.00          | X             |
| 1   | FRONT DOOR (LH)                 | RESTORE n         |               |
| 1   | FRONT DOOR (RH)                 | RESTORE n         | X             |
| 1   | FRONT A-PILLAR L/H              | RESTORE n         | X             |
| 1   | FRONT A-PILLAR R/H              | RESTORE n         | X             |
| 1   | DRIVER AIR BAG UNIT 1827.80     | Actual 2,033.40   |               |
| 1   | DRIVER AIR BAG SLIP RING 185.80 | 329.50            |               |
| 1   | PASSENGER AIR BAG UNIT 2236.80  | Actual 2,488.90   |               |
| 1   | PASSENGER AIRCON VENT LH        | one 114.80        |               |
| 1   | PASSENGER AIRCON VENT RH        | one 114.80        |               |

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174

Accident Date : 24/12/2018

Vehicle No : SKS-8483-G

Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                  | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|------------------------------|-------------------|---------------|
| 1   | DASH BOARD TOP UNIT          | Bus 829.50        | /             |
| 1   | FRONT IMPACT SENSOR LH       | Hand 158.90       | /             |
| 1   | FRONT IMPACT SENSOR RH       | Hand 158.90       | /             |
| 1   | AIR BAG CONTROL MODULE & ECU | Hand 947.10       | /             |
| 1   | FRONT SEAT BELT LH 494.10    | Hand 582.40       | /             |
| 1   | FRONT SEAT BELT (RH) 494.10  | Hand 582.40       | /             |
| 1   | FRONT SEAT BELT BUCKLE (LH)  | 17 229.50         | X             |
| 1   | FRONT SEAT BELT BUCKLE (RH)  | 17 229.50         | X             |

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174 Accident Date : 24/12/2018  
Vehicle No : SKS-8483-G Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                 | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|-----------------------------|-------------------|---------------|
|     | Sub Total                   | 22331.60          |               |
|     | Discount 20% On Parts       | (4466.32)         |               |
|     | <u>Special Nett Item</u>    |                   |               |
| 1   | IU BRACKET                  | RM 15.00          | ✓             |
| 1   | FRONT WINDSCREEN SEALANT    | RM 60.00          | 40            |
| 1   | FRONT NUMBER PLATE & HOLDER | RM 45.00          | 40            |
| 1   | RADIATOR COOLANT            | RM 25.00          | ✓             |
| 1   | BATTERY ASSY                | RM 180.00         | X             |

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174

Accident Date : 24/12/2018

Vehicle No : SKS-8483-G

Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                                                         | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|---------------------------------------------------------------------|-------------------|---------------|
|     | <b>Sub Total</b>                                                    | <b>325.00</b>     |               |
|     | <b><u>Labour &amp; Misc</u></b>                                     |                   |               |
|     | LABOUR TO FACILITATE REPAIR                                         | 1,200.00          | SPB           |
|     | TO REMOVE & INSTALL FRONT WINDSCREEN GLASS                          | 140.00            | 120           |
|     | TO REMOVE & INSTALL RADIATOR INCLUDING PRESSURE TEST                | 17 80.00          | X             |
|     | TO REMOVE & INSTALL AIRCON CONDENSOR INCLUDING CHARGE UP GAS        | 120.00            | 120           |
|     | TO REMOVE & INSTALL AIR BAG COMPONENTS INCLUDING SEAT BELT & BUCKLE | 350.00            | 300           |

Date : 27/12/2018  
To : FWD SINGAPORE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : TAN HOW WEE  
: FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00008174 Accident Date : 24/12/2018  
Vehicle No : SKS-8483-G Make & Model : HONDA CIVIC 1.6 VTI (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                                                | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|------------------------------------------------------------|-------------------|---------------|
|     | TO RESET & RE-PROGRAM AIR BAG WARNING LIGHT                | 180.00            | α             |
|     | TO CONDUCT PULLING & STRAIGHTENING OF FRONT CHASSIS MEMBER | 250.00            | X             |
|     | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS               | 30.00             | ✓             |
|     | TO SPRAY PAINT ON AFFECTED AREAS                           | 1,800.00          | 1080          |
|     | <b>Sub Total</b>                                           | <b>4150.00</b>    |               |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Remarks:

22,340.28

S.N - 120  
cash - 2510

### SUB TOTAL

GST 7.0 % 1,563.82

TOTAL 23,904.10

Surveyor's name: marcus n.kn

Principal's name: TAN HOW WEE

Survey Date & Time: 27/12/18

H/S  
Sdy.  
Z. Hoyle & Others