



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

### ESTIMATE FOR SLW1053C

Chew Siew Bee Serena

Blk 538 Pasir Ris Street 51  
#02-36  
Singapore 510538

Mobile: 93898810

#### Vehicle & Document Information

WIP No **29619**  
Reg No/Reg Date **SLW1053C / 30/01/2018**  
Date In/Mileage **/ 0**  
Chassis No **WDD2050402R348485**  
Engine No **27491031105806**  
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**  
Colour/Trim **021 197 Obsidian Bi/ 041 118 ARTICO Leat**

**SLW1053C**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	26/12/2018/ 15:53	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 98173502 REAR BUMPER TRIM MOLDING APPLY TOP FINISH COAT AND SPRAY ON ACCENT PAINTWORK				600 / 840.00
M BPNSUN POLICY NO/ACC DATE : 1800006935-01 // 25-12-2018 DRIVE IN/TP VEHICLE : // SCL1511L AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				960 / 1680.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00
M REAR BUMPER <del>DE</del> <i>cut</i>	1.00	1559.46	00.00	1559.46
M REAR BUMPER LOWER TRIM	1.00	208.27	00.00	208.27
M CHROME MOULDING	1.00	245.09	00.00	245.09
M BLIND RIVET	6.00	3.43	00.00	20.58
M DISTANCE SENSOR	2.00	172.07	00.00	344.14
M ELECTRICAL WIRING HARNESS	1.00	348.87	00.00	348.87
M RH/REAR BUMPER BRACKET	1.00	29.98	00.00	29.98

ESTIMATE

*Reserve*  
*Hp 90010068*  
*3 days*  
*20/02/19 @ 1236*  
*Reserve before paint*

Confirmed & accepted by

Nett **5,776.39**  
7% GST on **5776.39** **404.35**  
**Total Payable 6,180.74**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg