

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 14/12/2018

AXA

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 13/12/2018 @ 08:40
 VRN : SLE9952A
 MODEL : TOYOTA ALTIS 1.6
 TP VRN : FBN7387R

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 BOOTLID	1	\$ 755.00	\$ 755.00	bt ✓
2 BOOTLID HINGE R/L	2	\$ 68.00	\$ 136.00	Rp ✓
3 BOOTLID INSULATOR	1	\$ 355.00	\$ 355.00	x
4 BOOTLID INSULATOR CLIP	10	\$ 5.50	\$ 55.00	x
5 BOOTLID LAMP R/L	2	\$ 355.00	\$ 710.00	x
6 BOOTLID LOGO	1	\$ 60.00	\$ 60.00	re ✓
7 BOOTLID LOGO "COROLLA"	1	\$ 45.00	\$ 45.00	re ✓
8 BOOTLID LOGO "ALTIS"	1	\$ 45.00	\$ 45.00	re ✓
9 BOOTLID CHROME	1	\$ 217.00	\$ 217.00	x
10 REAR BUMPER	1	\$ 485.00	\$ 485.00	de ✓
11 REAR BUMPER CLIP	10	\$ 5.50	\$ 55.00	re ✓
12 REAR BUMPER REFLECTOR R/L	2	\$ 58.00	\$ 116.00	x
13 REAR BUMPER SIDE RETAINER INNER R/L	2	\$ 120.00	\$ 240.00	x
14 REAR BUMPER SIDE RETAINER OUTER R/L	2	\$ 80.00	\$ 160.00	x
15 BOOTLID LOCK	1	\$ 382.00	\$ 382.00	?
16 BOOTLID WEATHERSTRIP	1	\$ 185.00	\$ 185.00	end ✓
17 TAILLAMP R/L	2	\$ 395.00	\$ 790.00	?
18 REAR REINFORCEMENT	1	\$ 395.00	\$ 395.00	bt ✓
19 REAR END PANEL	1	\$ 590.00	\$ 590.00	Re bt ✓
20 REAR END PANEL GARNISH	1	\$ 240.00	\$ 240.00	de ✓
21 REAR END PANEL GARNISH CLIP	8	\$ 5.50	\$ 44.00	re ✓
22 EXHAUST TAILPIPE	1	\$ 939.00	\$ 939.00	x
			\$ 6,999.00	
Discount -25%			\$ 1,749.75	
			\$ 5,249.25	
<u>Special Nett</u>				
23 REAR LICENSE PLATE WITH CASING	1	\$ 45.00	\$ 45.00	x
24 REVERSE SENSOR	1	\$ 200.00	\$ 200.00	re ✓
			\$ 245.00	
25 REAR FENDER RH	Repair			
26 REAR FENDER LH	Repair			
	PARTS TOTAL		\$ 5,494.25	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	1250	\$ 2,000.00
Putty, Blend And Spray Paint on REAR Affected Area => plus for fender before paint.	1250	\$ 2,000.00
Check Wiring, Re-align Taillamps, Ensure Proper Functioning	\$ 30	80.00
Remove & Reinstall Cushions, Seats, Backrests, Inner Trim, Garnish, Roof Lining and/or Upholstery to Facilitate Repair	\$ 60	180.00
Towing Charge => Repair?	\$?	100.00
Remove and Refit Rear End Panel Lining and Garnish to Facilitate Repair	\$ x	150.00
Remove and Reinstall Rear Trim Compartment to Facilitate Cutting and Repairing Work	\$ y	150.00
Dismantle and Transfer Tailgate Fittings & Mechanisms to New Tailgate	\$ 60	180.00
Remove and Replace Exhaust Pipe/System to Facilitate Repair	\$ x	250.00
Remove and Reinstall Reverse Sensors	\$ 30	120.00
Remove and Reinstall Rear Reverse Camera	\$ 30	120.00
Cavity Treatment on New Parts	\$ 40	160.00
Conduct Water Seepage Test	\$ 30	120.00

LABOURS TOTAL \$ 5,610.00

Grand Total : \$ 11,104.25

Add 7% GST : \$ 777.30

Nett Total : \$ 11,881.55

No. of repair days: 16

Tanjah 97495749
- wp'
27/12/18 1250
Resurvey before paint
340 @ 11kauto.com
7 days



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: