

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Chew Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDG 8283M. Yr Regn: 2015 Sept.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 Adventure 1595.Colour: Grey. A/C: Insured / Std / NI / NASp. Reading: 34/663. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD205242 2095626Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50R17.R: 225/50R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. ob mmR/Bal. ob mmL/Bal. ob mmL/Bal. ob mm

D.O.A.

D.O.I. 27/12/18Survey held at Chew MotorDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAXA.4/5 \$9000 with 7 repair days.MV: 1101KPV: 75.2KNett;(Red = \$12295 / 58%.)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18023220/Apb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 27-12-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 9769B	Veh. Inspected	SDG 8283M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/12/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/12/2018	Inspection Date	27/12/2018
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545 Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Adrian LKK-AXA
Cecilia

26/12/2018

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPA x A

Xiao Tong

WDD2050402R095626

Accident date: 24/12/2018

Estimated repair cost for vehicle no: SDG8283M MERCEDES C180 1.6 A '15

CHASSIS: WDD2050402R095626

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper <i>Reformed</i>	1687	\$1,769.00 ✓
2	1	Rear Bumper Lower <i>Not new</i>		\$268.00 x
3	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>
4	1	Rear R/H Bumper Side Retainer <i>New</i>		\$55.00 ✓
5	1	Rear R/H Bumper Chrome Moulding <i>lit</i>		\$95.00 ✓
6	1	Rear R/H Bumper Reverse Sensor <i>Not new</i>		\$296.00 x
7	1	Rear R/H Tail Lamp <i>lit</i>		\$712.00 ✓
8	1	Rear R/H Fender <i>Distorted</i>	2066	\$2,233.00 ✓
9	1	Rear R/H Fender Inner Panel <i>Repair</i>		\$1,596.00 x
10	1	Rear R/H Fender Cowling <i>new</i>		\$184.00 x
11	6	Rear R/H Fender Cowling Clip <i>new</i>	\$6.50	\$39.00 x
12	1	Rear R/H Petrol Tank Cover <i>Not new</i>		\$81.00 +
13	1	Rear R/H Tyre <i>lit</i>		\$450.00 <i>254/50</i>
14	1	Rear R/H Rim <i>lit</i>		\$1,142.00 <i>800/50</i>
15	1	Rear R/H Lower Arm <i>Best</i>		\$356.00 ✓
16	1	Rear R/H Upper Arm <i>Best</i>		\$239.00 ✓
17	1	Rear R/H Knuckle Arm <i>Best</i>	1035	\$1,706.00 ✓
18	1	Rear R/H Knuckle Arm Bearing <i>and</i>		\$239.00 ✓
19	1	Rear R/H Shock Absorber <i>Best</i>		\$609.00 ✓
20	1	Rear R/H Trailing Arm <i>Best</i>		\$289.00 ✓
21	1	Rear R/H Stabilizer Bar <i>Not new</i>		\$318.00 +
22	1	Rear R/H Drive Shaft <i>Not new</i>		\$2,585.00 +
23	1	Rear Windscreen Moulding <i>new</i>		\$155.00 ✓
24	1	R/H Rocker Panel Skirt <i>torn</i>		\$889.00 ✓
25	1	R/H Rocker Panel Skirt Chrome Moulding <i>lit</i>		\$255.00 ✓

Subtotal :- \$16,625.00

8711
7839.90

S.N 1050

Labour charges

To remove & refit rear R/H undercarriage	\$380.00 220
To remove & refit reverse sensor	\$100.00 50
To remove & refit petrol tank	\$280.00 80
To remove & refit rear windscreen	\$120.00 100
Gum	nee \$50.00 ✓
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
To reset computer	\$350.00 80
Towing fee	\$150.00 ✗
Tuff kote	\$150.00 50
Panel beating	2440 \$1,400.00 800.
Spray painting	\$1,400.00 900.

Subtotal :- \$4,630.00

Total:- \$21,255.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 11328.80

4/s: 9K
07 days

9K

07 days



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER: CHEW MOTOR DATE: Dec 27, 2018 1:00:00 PM
LICENSE NO: SDG 8283 M
MILEAGE: 34659
REFERENCE: CUSTOM MODEL: MERCEDES BENZ C CLASS

	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	1.00	2.10			4.30				4.30		
PARTIAL TOE	0.00	0.50	1.00		1.50		2.70		0.70		3.60	
SET BACK	---	---	---			0°06"				0°06"		
CAMBER	-1°04"	-0°34"	-0°04"		-0°36"		-1°04" 0°26"		-0°36"		-1°04" 0°26"	
CASTER	7°44"	8°44"	9°44"		8°56"		9°20" 0°24"		8°56"		9°20" 0°24"	
KINGPIN	---	---	---		0°10"		2°04" 1°54"		0°10"		2°04" 1°54"	
INCL ANGLE	---	---	---		-0°26"		1°00"		-0°26"		1°00"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	2.10	4.20			2.50				2.50		
PARTIAL TOE	0.00	1.00	2.10		2.30		0.20		2.30		0.20	
SET BACK	---	---	---			0°20"				0°20"		
CAMBER	0°00"	---	---		-1°42"		-2°54" 1°10"		-1°42"		-2°54" 1°10"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°10"				0°10"		

<< Service Request Details

Claim

S8M01805

Reference

None 

Loss Date

26 December 2018

Action

Request Date

27 December 2018

Due Date

3 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDG8283M

Make

TPVD

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Chew Motor Pte. Ltd. <claims@chewmotor.com>
Sent: Wednesday, 26 December, 2018 5:09 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: SDG8283M CLAIMING AGAINST SHB9769B DOA:26.12.18
Attachments: SDG8283M PRI.pdf

Categories: Santosh

Hi Motor Claims Department,

Please send your surveyor list, thanks.

Please take note this claim under Chew Motor Pte Ltd

Please kindly take note that we have a mutual agreement on the selection of appointed surveyor from your panel surveyor's list. We hope that there will not be any further changes to the finalised repair cost after confirmation with your appointed surveyor or at the stage of LOD.

Regards,

Sukyi Chong



CHEW MOTOR PTE. LTD.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 29/04/2019

Survey Details:

Date of loss	26-Dec-18
Date of appointment	27-Dec-18
Date of survey	27-Dec-18
Location of survey	CHEW MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SDG 8283M
Make and Model	MERCEDES BENZ C180 AVENTGARDE
Date of registration	10/9/2015
Excess	
Market Value	\$110,000
Parf Rebate	\$75,256
Nett Loss	\$34,744

Repair details:

Initial Estimate	\$ 21,255.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 8,889.90
Check items (estimate)	\$ -
Labour	\$ 2,440.00
Total	\$ 11,329.90
Lump Sum(if applicable)	\$ 9,000.00

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 9,000.00	\$ -
Loss of use	-	\$ -
Loss of rental (5DAYS X \$100)	\$ 500.00	\$ -
Loss of income	-	\$ -
LTA search fees	\$ 7.45	\$ -
Others	-	\$ -
Proposed Total	\$ 9,507.49	\$ -



<MANDATE IA> -S8M01805 [ACCIDENT INVOLVING SHB 9769B(OI) & SDG 8283M(TP) ON 26/12/2018

Type

🔗 Question

Message

Liability: 100% OI turning into major road and collided onto Third Party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$9,507.45(claiming LOR). Mandate IA had been uploaded in Smartclaim. Kindly give us your instruction/approval. - Cecilia 29/04/2019

Reply



Pls proceed DS with quantum as proposed

Type

🔗 Question

Message

LOR is subject to rental receipt. TP Excess: \$5000

Reply

Our Reference : CM1902-0027 / SDG8283M
Your Reference : SHB9769B

14th February 2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#B1-01,
Singapore 068811



CHEW MOTOR PTE. LTD

WITHOUT PREJUDICE

Dear Sir/Madam

ACCIDENT INVOLVING SDG8283M & SHB9769B ON 26.12.2018 ALONG HAIG ROAD AT 11:48HRS

We are instructed by **LOW YEE SENG** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SDG8283M** damaged by vehicle **SHB9769B** driven by your insured at the material time.

We are informed that the said accident was caused by your insured's negligence. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows: -

➤ Repair Costs	\$ 9,000.00
➤ Loss of Rental for 05 days	\$ 900.00
➤ LTA Search Fees	\$ 7.45
➤ Total	<u>\$ 9,907.45</u>

A copy of each supporting documents are enclosed for your perusal.

- GIA Report
- Invoice
- LTA Search Receipt

Please let us have your cheque for the sum of **\$9,907.45** made payable to us, **CHEW MOTOR PTE. LTD.** within the next 14 days.

Yours Sincerely,

CHEW MOTOR PTE. LTD.



THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHB 9769B (Insd veh)	Model:	MERCEDES BENZ C180 AVANTGARDE
	SDG 8283M (TP veh)		
Date of Accident:	26/12/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	21,255.00
Final Repair Cost	:	\$	9,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	9,500.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	CHEW MOTOR PTE. LTD.	:	\$ 9,500.00

NUR SHAQILAH BTE ABDOL
WAHAB

13/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18023220/Agb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 13-05-2019		
ATTN: PETER WANG		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 9769B	Veh. Inspected	SDG 8283M	
Policy No.	VPX/P1680520	Coverage (\$)	0.00	
Claim No.	S8M01805	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	27/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180 AVANTGARDE	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD2050402R095626	Colour	GREY	
Odometer	341663	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/50R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/50R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/50R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/12/2018	Inspection Date	27/12/2018	
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDG 8283M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,769.00	1,687.00
1	REAR BUMPER LOWER (CONSISTENT)	NOT NECESSARY	268.00	-
10	REAR BUMPER CLIP @ \$6.50 (CONSISTENT)	NECESSARY	65.00	30.00
1	REAR R/H BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	55.00	55.00
1	REAR R/H BUMPER CHROME MOULDING (CONSISTENT)	CUT	95.00	95.00
1	REAR R/H BUMPER REVERSE SENSOR (CONSISTENT)	NOT NECESSARY	296.00	-
1	REAR R/H TAIL LAMP (CONSISTENT)	CUT	712.00	712.00
1	REAR R/H FENDER (CONSISTENT)	DISTORTED	2,233.00	2,066.00
1	REAR R/H FENDER INNER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,596.00	-
1	REAR R/H FENDER COWLING (CONSISTENT)	NOT NECESSARY	184.00	-
6	REAR R/H FENDER COWLING CLIP @ \$6.50 (CONSISTENT)	NOT NECESSARY	39.00	-
1	REAR R/H PETROL TANK COVER (CONSISTENT)	NOT NECESSARY	81.00	-
1	REAR R/H LOWER ARM (CONSISTENT)	BENT	356.00	356.00
1	REAR R/H UPPER ARM (CONSISTENT)	BENT	239.00	239.00
1	REAR R/H KNUCKLE ARM (CONSISTENT)	BENT	1,706.00	1,035.00
1	REAR R/H KNUCKLE ARM BEARING (CONSISTENT)	DAMAGED	239.00	239.00
1	REAR R/H SHOCK ABSORBER (CONSISTENT)	BENT	609.00	609.00
1	REAR R/H TRAILING ARM (CONSISTENT)	BENT	289.00	289.00
1	REAR R/H STABILIZER BAR (CONSISTENT)	NOT NECESSARY	318.00	-
1	REAR R/H DRIVE SHAFT (CONSISTENT)	NOT NECESSARY	2,585.00	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	155.00	155.00
1	R/H ROCKER PANEL SKIRT (CONSISTENT)	TORN	889.00	889.00
1	R/H ROCKER PANEL SKIRT CHROME MOULDING (CONSISTENT)	CUT	255.00	255.00
	LESS 10% DISCOUNT		-	-871.10
			15,033.00	7,839.90
SPECIAL NETT ITEMS				
1	REAR R/H TYRE (SN) (CONSISTENT)	CUT	450.00	250.00
1	REAR R/H RIM (SN) (CONSISTENT)	CUT	1,142.00	800.00

Report Ref No. CC4/ASM18023220/Agb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GUM (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			1,642.00	1,100.00
	LABOUR			
	TO REMOVE & REFIT REAR R/H UNDERCARRIAGE.		380.00	220.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT PETROL TANK.		280.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	100.00
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TO RESET COMPUTER.		350.00	80.00
	TOWING FEE.	NOT NECESSARY	150.00	-
	TUFF KOTE.		150.00	50.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR R/H FENDER INNER PANEL.		1,400.00	800.00
	SPRAY PAINTING.		1,400.00	900.00
			4,580.00	2,390.00
GRAND TOTAL			21,255.00	11,329.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CC4/ASM18023220/Agb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.