



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

26/12/2018

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPA x A

Xiao Tong

WDD2050402R095626

Accident date: 26/12/2018

Estimated repair cost for vehicle no: SDG8283M MERCEDES C180 1.6 A '15

CHASSIS: WDD2050402R095626

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper Deformed	1687	\$1,769.00 ✓
2	1	Rear Bumper Lower New		\$268.00 X
3	10	Rear Bumper Clip New	\$6.50	\$65.00 30
4	1	Rear R/H Bumper Side Retainer New		\$55.00 ✓
5	1	Rear R/H Bumper Chrome Moulding Lt		\$95.00 ✓
6	1	Rear R/H Bumper Reverse Sensor New		\$296.00 X
7	1	Rear R/H Tail Lamp Lt		\$712.00 ✓
8	1	Rear R/H Fender Distorted	2066	\$2,233.00 ✓
9	1	Rear R/H Fender Inner Panel Repair		\$1,596.00 X
10	1	Rear R/H Fender Cowling New		\$184.00 X
11	6	Rear R/H Fender Cowling Clip New	\$6.50	\$39.00 X
12	1	Rear R/H Petrol Tank Cover New		\$81.00 +
13	1	Rear R/H Tyre Lt		\$450.00 X 250/50
14	1	Rear R/H Rim Lt		\$1,142.00 800/50
15	1	Rear R/H Lower Arm Bent		\$356.00 ✓
16	1	Rear R/H Upper Arm Bent		\$239.00 ✓
17	1	Rear R/H Knuckle Arm Bent	1035	\$1,706.00 ✓
18	1	Rear R/H Knuckle Arm Bearing Damaged		\$239.00 ✓
✓ 19	1	Rear R/H Shock Absorber Bent		\$609.00 ✓
20	1	Rear R/H Trailing Arm Bent		\$289.00 ✓
21	1	Rear R/H Stabilizer Bar New		\$318.00 +
22	1	Rear R/H Drive Shaft New		\$2,585.00 +
23	1	Rear Windscreen Moulding New		\$155.00 ✓
✓ 24	1	R/H Rocker Panel Skirt Torn		\$889.00 ✓
25	1	R/H Rocker Panel Skirt Chrome Moulding Lt		\$255.00 ✓

Subtotal :- \$16,625.00

8711
7839.90

S/N 1050

Labour charges

To remove & refit rear R/H undercarriage	\$380.00 220
To remove & refit reverse sensor	\$100.00 50
To remove & refit petrol tank	\$280.00 80
To remove & refit rear windscreen	\$120.00 100
Gum	\$50.00 /
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
To reset computer	\$350.00 80
Towing fee	\$150.00 X
Tuff kote	\$150.00 50
Panel beating	2440 \$1,400.00 800.
Spray painting	\$1,400.00 900.

Subtotal :- \$4,630.00

Total:- \$21,255.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 11329.50

L/S: 9K

07 days

9K

07 days



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER CHEW MOTOR DATE Dec 27, 2018 1:00:00 PM
LICENSE NO SDG 8283 M
MESSAGE 34659
REFERENCE CUSTOM MODEL MERCEDES BENZ C CLASS

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	1.00	2.10			4.30				4.30		
PARTIAL TOE	0.00	0.50	1.00		1.50		2.70		0.70		3.60	
SETBACK	---	---	---			0°06"				0°06"		
CAMBER	-1°04"	-0°34"	-0°04"		-0°36"		-1°04" 0°26"		-0°36"		-1°04" 0°26"	
CASTER	7°44"	8°44"	9°44"		8°56"		9°20" 0°24"		8°56"		9°20" 0°24"	
KINGPIN	---	---	---		0°10"		2°04" 1°54"		0°10"		2°04" 1°54"	
INCL ANGLE	---	---	---		-0°26"		1°00"		-0°26"		1°00"	
Front-wheel turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	2.10	4.20			2.50				2.50		
PARTIAL TOE	0.00	1.00	2.10		2.30		0.20		2.30		0.20	
SETBACK	---	---	---			0°20"				0°20"		
CAMBER	0°00"	---	---		-1°42"		-2°54" 1°10"		-1°42"		-2°54" 1°10"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°10"				0°10"		