

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6471 Z

S/NETT

1 pc	Rear o/s fender sticker	\$	60.00
	Sundry	\$	50.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear bumper, rear o/s fender etc	\$	550.00 200
	To putty and spray painting on rear bumper, rear o/s fender	\$	400.00 360
	To apply rustproofing on the repaired and replaced panels.	\$	80.00 X
		\$	<u>1,140.00</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Ka / in / U / K / y

M 26/12/18 1610h

2 Rep.

U / s
After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation/claimants is allowed
- Supplier/repairer must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: