

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7482

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0760/18
DATE : 24-DEC-2018

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : WONG KOK GHAY
ADDRESS : BLK 225C COMPASSVALE WALK
#07-351
S(543225)
TELEPHONE NO : 90401613

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100494646-02
VEHICLE NO : SLJ6811S
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2303143A
CHASSIS NO : SJNFEAJ11U1711379
MILEAGE : 40500 KM
DATE IN : 24/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 23/12/2018

-9645 0084 elmer@tanchoy.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ6811S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR BOTH RR FENDER & HATCHBACK DOOR, RENEW RR END PANEL & RR BUMPER	3120.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	1250.00	
3	ZZ/003	APPLY SEALANT TO RR END PANEL	100.00	
4	ZZ/004	RENEW REVERSE SENSOR 4 POINT	110.00	
5	ZZ/005	SUPPLY RR LICENSE PLATE		
6	ZZ/006	REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE RR BUMPER REPLACEMENT	48.00	
TOTAL LABOUR CHARGES			4628.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ6811S

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 REAR LICENCE PLATE	RLP			60.00
2 SUNDRIES	NPN			50.00
3 REAR END PANEL	G9110-4EAMA	482.60		
4 LH REFLECTOR RR BUMPER	26565-JJ90A	55.00		
5 RH REFLECTOR RR BUMPER	26560-JJ90A	55.00		
6 LH STAY RR BUMPER	H5211-4EAMA	126.00		
7 RH STAY RR BUMPER	H5210-4EAMA	126.00		
8 REINFORCEMENT RR BUMPER	H5030-4EAMA	619.20		
9 ENERGY ABSORBER RR BUMPER	85090-4EA0B	126.40		
10 SENSOR-REVERSE 4 POINT	SENSOR			250.00
11 LH SIDE BRACKET RR BUMPER	85221-4EA0A	35.90		
12 RH SIDE BRACKET RR BUMPER	85220-4EA0A	35.90		
13 CLIP RR BUMPER @ SGD \$ 1.20 EACH	01553-05933	7.20		
14 TOW HOOK COVER RR BUMPER	85071-4EA0A	16.80		
15 REAR BUMPER	85022-4EA0H	717.00		
SUB TOTAL		2403.00	0.00	360.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		480.60	0.00	0.00
GRAND TOTAL		1922.40	0.00	360.00
OVERALL TOTAL		2282.40		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ6811S

TOTAL LABOUR CHARGES	4628.00
TOTAL SPARE PARTS CHARGES	2282.40

GRAND TOTAL	6910.40 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.