

INSURANCE

INS CASE OWNER:

CC

QBE1802

LKR:

IDAC:

Surveyor:

Kenneth

DOI:

26/12/18

Date / Time:

26/12/18

Registered in Merimen:

Pre-assign / CCU / FTE

YN 1625K

Insured Vehicle No

Name of Insured

Insured Tel No

Excess Sec II : SS

Is driver the owner?

IF NO, Driver Name / Age

Driver Tel No :

HP:

D.O.A :

Nature of Accident :

(YES / NO)

(V/L: YES / NO)

Claim No.

Policy No.

Make / Model :

Place of Accident :

Ol GIA REPORT, YES / NO :

Insured Liability :

VL01N73

8-V015464

MTMHAISHI

UPP LAMT / RO TMS LAMT

TP GIA REPORT, YES / NO

Final ? Yes / No

SHF 724T

Trans

car

INSRS:

WSP:

Tel :

Liability :

RMKS:

INSRS:

WSP:

Tel :

Liability :

RMKS:

INSRS:

WSP:

Tel :

Liability :

RMKS:

INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

26/12/18

11/21/19

12/31/19

26/12/18

11/21/19

12/31/19

26/12/18

11/21/19

12/31/19

26/12/18

11/21/19

12/31/19

STAGE

DATE / PIC

Non-Reporting 1st

Non-Reporting 2nd

Non-Reporting 3rd

Notification 1st (if non-pickup)

Call Ol:

After call 1st to Ol:

Documentation Check List:

Handler

Typist

Notification 1st (if non-pickup)

After call 1st to Ol:

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA :

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form:

Post-Repair Photos

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by: KSL

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS 8,800

(6 days) Reduction:

85 %

Email

Call

FINAL SETTLEMENT

Date/Time: 13.12.19

Confirm with: WBS Yes

Final Liability:

SS 9,416.00

(Agreed / Assessed) BOLA S/N No. :

74

Repair Cost:

SS 9,416.00

LOSS OF RENTAL (LOR):

SS 913.14

(9 days) x SS 101.46

Loss of Use (LOU):

SS -

(5 days) x SS -

Loss of Income (LOI):

SS 450.00

(550 x 9 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

GIA/LTA Search

SS 7.99

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independence)

Legal Cost

SS -

Total:

SS 10,786.63

Global Sum SS:

FINAL PAYMENT

Date/Time: 13.12.19

Confirm with: WBS Yes

Payee 1:

SS 10,786.63

Name 1:

TRANS-ONE AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

27/12 File rectify Certificate

28/12 2/12/2008 Certificate Jasmine (8+3 x 101.46 + 450)

Red = \$48529.83 / 85%

Veh No: SHF 724T Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude cc 1995

Colour: M. White / Red AC: Insured / Std / NI / NA

Sp. Reading: 303163 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: VF1ABL15AUC 281169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A. 24/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass 107

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return 107

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - St

Phone

Others

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC3/QBE18023225/Kpb3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 27-12-2018	
			Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2635K	Veh. Inspected	SHF 724T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/12/2018	Inspection Date	26/12/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/QBE18023225/Kpb3

Date: 27.12.2018

The Motor Claims Department
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHF724T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.11.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	57,329.83
Revised Estimate Amount	: S\$	8,800.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T**AAD1812-200**

Not Notarised
C/Ling & Jooal

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 724T

VF1ABL15AUC281169

RENAULT

LATITUDE

24.12.2018

QBE

31/12/2014

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPR BRACKET SIDE RH REAR
- 5 1 BUMPR RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPR BRACKET SIDE LH REAR
- 8 1 BUMPR RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

\$	<i>B</i>	1,108.46	—
\$	<i>B</i>	768.84	—
\$	<i>S</i>	113.47	X
\$	<i>S</i>	135.97	X
\$	<i>S</i>	44.99	X
\$	<i>S</i>	43.61	X
\$	<i>S</i>	135.97	X
\$	<i>S</i>	44.99	X
\$	<i>S</i>	43.61	X
\$	<i>B</i>	777.52	✓
\$	<i>R</i>	225.95	X
\$	<i>R</i>	225.95	X
\$	<i>B</i>	2,872.68	✓
\$	<i>W</i>	470.06	✓
\$	<i>D.171/R</i>	323.05	50.00
\$	<i>CM</i>	493.35	—
\$	<i>CM</i>	493.35	—
\$	<i>MC</i>	225.36	—
\$	<i>MC</i>	225.36	—
\$	<i>R</i>	276.08	} X
\$	<i>S</i>	276.08	
\$	<i>R</i>	367.84	
\$	<i>R</i>	367.84	
\$	<i>S</i>	586.45	
\$	<i>S</i>	168.13	
\$	<i>R</i>	202.67	
\$	<i>S</i>	74.40	}
\$	<i>S</i>	50.52	
\$	<i>S</i>	221.81	}

161.53

1.45

Trans-cab Auto Services Pte Ltd**AAD1812-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	}	X
31	1 WHEELARCH REAR LH	\$	Sh	543.47		
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Sh	671.45		
33	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09		
34	1 FENDER PANEL REAR RH	\$	R	3,299.13		
35	1 WHEELARCH REAR RH	\$	Sh	543.47		
36	1 FENDER PANEL INNER TRIM REAR RH	\$	Sh	671.45	}	
37	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09		
38	1 TAILLAMP LH	\$	ngjcm	552.55	✓	
39	1 TAILLAMP PANEL LH	\$	R	986.70	X	
40	1 TAILLAMP RH	\$	Sh	552.55	X	
41	1 TAILLAMP PANEL RH	\$	R	986.70	X	
42	1 OUTER PANEL REAR (End Panel)	\$	Bu	1,471.77	✓	
43	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sh	404.56	X	
44	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X	
45	1 SPARE WHEEL PANEL TRIM	\$	Sh	612.21	X	
46	1 EXHAUST REAR	\$	R	7,489.05	X	
47	1 EXHAUST CAP REAR	\$	R	230.49	X	

TOTAL	\$	45,233.12
10%	\$	4,523.31
	\$	40,709.81

Special Nett

1	1SET PARKING AID	\$	Shot	700.00	Goosn
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sh	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	30sn
13	1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	30sn

Trans-cab Auto Services Pte Ltd**AAD1812-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T

16	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
17	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
19	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
20	1 TAILLAMP CLIP RH	\$	na	5.00	X
21	1 TAILLAMP CLIP LH	\$	na	5.00	✓
22	2 REAR WINDSCREEN SELANT	\$	na	80.00	X
23	1 WINDSCREEN MOULDING	\$	na	100.00	X
24	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
25	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sa	385.00	X
26	1 SPARE TYRE	\$	sa	330.00	X

TOTAL	\$	2,280.02
--------------	-----------	-----------------

TOTAL PARTS	\$	42,989.83
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1812-200

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 724T

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
TOTAL	\$	14,340.00	

Over All Total \$ 57,329.83**(LUMP SUM)****Repair Days****20-DAYS***6 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHF724T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Dec 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002400
Chassis No.:	VF1ABL15AUC281169
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Dec 2014
First Registration Date:	31 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	30 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$25,938.00
Total Rebate Amount:	\$35,311.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Dec 2018

OK

Shu Pei (LKKAuto)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Thursday, 3 January 2019 3:12 PM
To: Shu Pei (LKKAuto)
Cc: Admin A; Hsiao Tong (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving YN2635K (OI : QBE - TBA) and SHF724T (TP : LKK REF - CC3/QBE18023225/Kpb3) on 24.12.2018
Attachments: YN2635K.pdf

Hi Shu Pei

Resend attachment.

Thanks & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 3 January 2019 9:31 AM
To: Joyce Foo <joyce.foo@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving YN2635K (OI : QBE - TBA) and SHF724T (TP : LKK REF - CC3/QBE18023225/Kpb3) on 24.12.2018

Dear Joyce,

No attachment found. Kindly re-sent.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Friday, 28 December 2018 1:56 PM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: FW: Direct Settlement - Accident Involving YN2635K (OI : QBE - TBA) and SHF724T (TP : LKK REF - CC3/QBE18023225/Kpb3) on 24.12.2018

Our ref: VC012173

Hi Shu Pei

Attached Insured's report for your retention. Please proceed for direct settlement.

Thanks & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Jenny Toh
Sent: Friday, 28 December 2018 10:33 AM
To: Joyce Foo <joyce.foo@qbe.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Subject: FW: Direct Settlement - Accident Involving YN2635K (OI : QBE - TBA) and SHF724T (TP : LKK REF - CC3/QBE18023225/Kpb3) on 24.12.2018

Our ref: VC012173

Hi Shu Pei

This case is handled by my colleague Joyce Foo.

Aside to Joyce, FYA

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Thursday, 27 December 2018 8:38 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Direct Settlement - Accident Involving YN2635K (OI : QBE - TBA) and SHF724T (TP : LKK REF - CC3/QBE18023225/Kpb3) on 24.12.2018

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

We have inspected TP vehicle SHF 724T at M/s Trans-cab Auto Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/QBE18023225/Keb3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 19-12-2019



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 2635K	Veh. Inspected	SHF 724T
Policy No.	8-V0018464-MVA	Coverage (\$)	0.00
Claim No.	VC012173	Excess (\$)	0.00
Assign From		Assign Date	26/12/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC281169	Colour	METALLIC WHITE /RED
Odometer	303163	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/12/2018	Inspection Date	26/12/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 724T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	BUCKLED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	WARPED	470.06	470.06
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAUT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	SERVICEABLE	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-

Report Ref No. CC3/QBE18023225/Keb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	WHEEL HOUSING PANEL REAR LH	TO REPAIR SEE LABOUR	4,682.09	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	WHEEL HOUSING PNAEL REAR RH	TO REPAIR SEE LABOUR	4,682.09	-
1	TAILLAMP LH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BUCKLED	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-4,491.01	-945.93
			40,419.04	8,513.37
1	BOOT WEATHERSTRIP (50%) (SN)	DISTORTED / DENTED	323.05	161.53
	LESS 10% DISCOUNT		-32.31	-
			290.74	161.53

Report Ref No. CC3/QBE18023225/Keb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	80.00	30.00
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,280.02	830.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00

Report Ref No. CC3/QBE18023225/Keb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,FENDER PANEL REAR LH,WHEEL HOUSING PANEL REAR LH,FENDER PANEL REAR RH,WHEEL HOUSING PANEL REAR RH,TAILLAMP PANEL LH,TAILLAMP PANEL RH,SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR AND EXHAUST CAR REAR.		6,000.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.)		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.)		170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			14,720.00	1,500.00
GRAND TOTAL			57,709.80	11,004.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,800.00

Report Ref No. CC3/QBE18023225/Keb3q2



Report Ref No. CC3/QBE18023225/Keb3q2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.