

26/12-2018



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
**GST Regn. No. : M2-8922054-2**

QBE Insured's Veh No : GBA5307D  
Date of Accident : 24 December 2018

Messrs Aerojet Pte Ltd

Date : 26 December 2018

Estimate To Repair GBF3705A - Toyota Dyna 150 Manual  
Chassis No : JTFAT35Y20K206556

S/No	Quantity	Description	Amount
		<b>LABOUR &amp; MISC. CHARGES</b>	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 250.00
02		Putty and spray painting of the affected portion.	\$ 350.00
			\$ 600.00
		<b>Total</b>	<b>\$ 600.00</b>

200  
200

not Adhered  
26/12  
P/P \$ 400/2  
22/12  
27/12/18  
Theoph. Adhered

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: