



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

QBE Insured's Veh No : GBA5307D
Date of Accident : 24 December 2018

Messrs Aerojet Pte Ltd

Date : 26 December 2018

Estimate To Repair GBF3705A - Toyota Dyna 150 Manual
Chassis No : JTFAT35Y20K206556

S/No	Quantity	Description	Amount
01		<u>LABOUR & MISC. CHARGES</u> Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 250.00
02		Putty and spray painting of the affected portion.	\$ 350.00
			\$ 600.00
		Total	\$ 600.00