



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2003835
INV Date 13/05/2020
Reference CC4/LPC18023228/Kka3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SGS 1976U
Insured Veh. GZ 1136R
Claim No. 18/18/19/VC00/021255
Policy No. Z/18/VC00/102794
Accident Date 23/12/2018
Inspection Date 31/12/2018

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18023228/Kka3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 13-05-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 1136R	Veh. Inspected	SGS 1976U
Policy No.	Z/18/VC00/102794	Coverage (\$)	0.00
Claim No.	18/18/19/VC00/021255	Excess (\$)	0.00
Assign From	GERALD	Assign Date	27/12/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053AK5004009903	Colour	METALLIC BLACK
Odometer	57082	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	8 mm
L/H Front Tyre	215/55 R17	MICHELIN	8 mm
R/H Rear Tyre	215/55 R17	MICHELIN	8 mm
L/H Rear Tyre	215/55 R17	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/12/2018	Inspection Date	31/12/2018
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 1976U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SIDE MIRROR ASSY	SERVICEABLE	1,605.80	-
1	FRONT FENDER -RH	BENT	797.35	797.35
1	FRONT FENDER EMBLEM -RH	NECESSARY	45.17	45.17
1	FRONT FENDER INNER SHIELD RH	DISTORTED	190.70	190.70
1	FRONT BUMPER	CRACKED	543.20	543.20
2	FRONT BUMPER RETAINER @\$79.75	CRACKED	159.50	159.50
1	HEADLAMP	MTG CRACKED	1,300.70	1,300.70
1	HEADLAMP LOWER BRACKET	NOT NECESSARY	46.75	-
10	CLIP @\$3.89	NECESSARY	38.90	38.90
1	FRONT BUMPER LOWER GRILLE CHROME (ADDITIONAL)	NECESSARY	208.40	208.40
1	FRONT GRILLE (ADDITIONAL)	NECESSARY	611.30	611.30
	LESS 25% DISCOUNT		-1,386.94	-973.80
			4,160.83	2,921.42
<u>LABOUR</u>				
	TO CHECK AND RE-WIRING.		45.00	20.00
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.		450.00	400.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		650.00	600.00
			1,145.00	1,020.00
GRAND TOTAL			5,305.83	3,941.42
RECOMMENDED COST OF REPAIRS				3,941.42

Report Ref No. CC4/LPC18023228/Kka3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGS 1976U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



TOYOTA MOTOR CORPORATION
MODEL ASV503-JE1EXT 2494 ml
ENGINE 2AR-FE
FRAME # JH053AK5004009903
COLOR TRN 4MT ONLY
2.8 L800 Z35
INSTR 0760E-04A OCT 15
MFG: TOYOTA MOTOR THAILAND CO., LTD. MAI, THAILAND



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGS 1976U

RE-INSPECTION

