

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1442/2018/PH
Date : 21-Dec-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Xiao Chao International Pte Ltd
Address : Blk 306A Punggol Place
#05-41
Singapore 821306
Telephone : HP +65 82238267
Type of Claim : Own Damage Claim
Policy No. : 1800080666
Vehicle No : **SMC 8598 U**
Model Code : Audi A5 CAB 2.0 TFSI
Model / Year : Jul-18
Engine No : CVK 059721
Chassis No : WAUZZZF5XJN016115
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Dec-18
Place of Accident : Plus 20 Cecil Street (S) 049705

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 8598 U .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs door's multi-lock system and power window devices.	S/N \$ 280.00	X
2	To remove and reinstall rear parking aid.	S/N \$ 280.00	✓
3	To remove and reinstall rear wire harness, relay, fuse boxes, audio equipment, rhs rear window and lifting mechanism, rhs trims, luggage compartment trims.	S/N \$ 1,600.00	✓
4	To remove and reinstall convertible top, complete with frame, hydraulic system assy, storage box, etc.	S/N \$ 1,800.00	✓
5	To dismantle lhs door, lhs side member trim, rear bumper and rear lid. Cut out and weld lhs rear fender and sill panel. Renew lhs door, align to position. Reinstall all parts removed.	\$ 6,300.00	3000
6	To reapeay lhs door, door handle, lhs side member trim, lhs rear fender, lhs sill panel, door entrance, drain panel and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 4,800.00	Handla : 100 4 x 600 = 2400 4 x 100 = 400 2300
SUB TOTAL LABOUR CHARGES		: \$ 15,060.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 8598 U .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
8	To carry out diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 15,724.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 8598 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR - LH <i>Repair</i>	\$ 2,446.00	<i>+</i>
2	FRONT DOOR OUTER DOOR SEAL <i>new</i>	2 \$ 383.00	<i>✓</i>
3	FRONT DOOR TRIM - LH <i>new</i>	\$ 138.00	<i>+</i>
4	FRONT DOOR CATCH <i>new</i>	\$ 92.00	<i>✓</i>
5	BONDING AGENT <i>new</i>	\$ 43.00	<i>+</i>
6	FRONT DOOR ATTACHMENT PARTS <i>new</i>	TBC	<i>+</i>
7	FRONT DOOR HANDLE TRIM PLATE - LH <i>new</i>	\$ 48.00	<i>✓</i>
8	FRONT DOOR HANDLE TRIM CHROME - LH <i>new</i>	\$ 119.00	<i>+</i>
9	FRONT DOOR HANDLE - LH <i>new</i>	\$ 33.00	<i>✓</i>
10	FRONT DOOR HANDLE MOUNTING BAR - LH <i>new</i>	\$ 143.00	<i>+</i>
11	SECTIONAL PART - SIDE PANEL - REAR LH <i>Painted</i>	\$ 4,049.00	<i>✓</i>
12	SILL TRIM STRIP SATIN BLACK - LH <i>?</i>	\$ 164.00	<i>?</i>
13	SIDE MEMBER TRIM - LH <i>Repair</i>	\$ 723.00	<i>+</i>
14	ATTACHMENT PARTS FOR SIDE MEMBER TRIM <i>new</i>	\$ 111.00	<i>✓</i>
15	SIDE MEMBER TRIM ADHESIVE TAPE <i>new</i>	\$ 182.00	<i>✓</i>
16	SOUND ABSORBER (SELF ADHESIVE) <i>?</i>	2 \$ 216.00	<i>?</i>
17	REAR ALUMINIUM RIM - LH <i>new</i>	\$ 934.00	<i>✓</i>
18	RUBBER VALVE <i>new</i>	4 \$ 20.00	<i>+</i>
19	STICKER WITH PICTOGRAM FOR AIRBAG/CHILD SEAT <i>new</i>	\$ 21.00	<i>✓</i>
20	ARCYLIC SEALER <i>new</i>	S/N \$ 180.00	<i>✓</i>
SUB - TOTAL SPARE PARTS		\$ 10,045.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 8598 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	CAVITY WAX	S/N \$ 140.00	✓
22	STONE CHIP TREATMENT	S/N \$ 180.00	✓
23	METAL FILLER POWDER	S/N \$ 280.00	✓
24	SUNDRIES	\$ 800.00	✓
TOTAL SPARE PARTS		: \$ 11,445.00	
TOTAL LABOUR CHARGES		: \$ 15,724.00	
GRAND TOTAL		: \$ 27,169.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 27/12/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 16 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant