

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5021R**AAD1812-198**

Not Authorised
Resurvey B4 paint
\$895.00

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5021R

VF1ABL15AUC283441

RENAULT

LATITUDE

24.12.2018

AIG

29/12/2017

PART**LIST**

1	DOOR PANEL FRT LH
1	DOOR HINGE UPPER LH
1	DOOR HINGE LOWER LH
1	DOOR CHECK FRT LH
1	DOOR LOCK FRT LH
1	DOOR CATCH FRT LH
1	DOOR HANDLE OUTER FRT LH
1	DOOR HANDLE COVER FRT LH
1	DOOR HANDLE MODULE FRT LH
1	DOOR REGULATOR FRT LH
1	DOOR REGULATOR MOTOR FRT LH
1	DOOR REGULATOR GUIDE FRT LH
1	DOOR PANEL REAR LH

\$	<i>N</i> 2,844.66
\$	<i>N</i> 261.28
\$	<i>N</i> 300.55
\$	<i>S</i> 194.77
\$	<i>N</i> 908.75
\$	<i>S</i> 131.23
\$	<i>S</i> 477.76
\$	<i>S</i> 13.22
\$	<i>S</i> 133.60
\$	<i>S</i> 505.19
\$	<i>S</i> 796.46
\$	<i>S</i> 120.97
\$	<i>N</i> 2,844.66

X

\$	9,533.10
10% \$	953.31
\$	8,579.79

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'
1	FRONT DOOR STICKER 'Chassis'
1	REAR DOOR STICKER '6555 3333'
1	DOOR CHECK BOLT
1	DOOR GUIDE SCREW
1	DOOR HINGE BOLT
1	DOOR HINGE NUT RH
1	DOOR CHECK BOLT
1	DOOR CHECK NUT

\$	<i>N</i> 80.00 <i>60sn</i>
\$	<i>N</i> 50.00 <i>15sn</i>
\$	<i>N</i> 80.00 <i>60sn</i>
\$	<i>S</i> 22.69
\$	<i>S</i> 10.85
\$	<i>S</i> 10.85
\$	<i>S</i> 14.60
\$	<i>S</i> 22.69
\$	<i>S</i> 3.75

X

Trans-cab Auto Services Pte Ltd**AAD1812-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5021R

1	DOOR LOCK SCREW L70Y	\$	nn 6.12 X
1	DOOR CATCH SCREW L70Y	\$	nn 10.06 X

TOTAL \$ 311.63**TOTAL PARTS \$ 8,891.42****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 3001
Putty and spray painting of the affected portion.	\$	3,000.00 44d
To rust-proofing of the affected areas.	\$	nn 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To transfer of front door fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 380.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL \$ 7,870.00**Over All Total \$ 16,761.42**Acknowledged by Rep: **PART-BY-PART (REPAIR DAY)**

Signature:

Date:

10 DAYS

2 days