



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

(SUPPLEMENTARY)

INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD SOMPO
Policy No:	D18MTPV01004983	Date of Loss:	26/12/2018
Vehicle Reg. No.:	SLX1349U	Driveable?	
Driver Age/Info:	33 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PHUA SOCK CHING (PAN SHUZHEN)	Contact No:	+6592340422
Driver:	PHUA SOCK CHING (PAN SHUZHEN)		

Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	19/03/2018
Vehicle Colour:	RED		
Engine No:	G4FGJU135150	Chassis No:	KMHD841CMJU628909
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 0

Description of Accident/Loss: TRAFFIC LIGHT TURN GREEN & I PROCEED TO MOVE. HOWEVER PA7268D WAS STILL STATIONARY THUS COLLIDED ONTO THE REAR OF PA7268D. NO ONE INJURED.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

	Amount
Parts	566.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	566.50
+ GST 7.00% (\$\$)	39.66
Nett Amount (\$\$)	606.16
+ Previous Estimates (\$\$)	3,337.65
Claim Total (\$\$)	3,943.81

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 02 Jan 2019)**Parts:** 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SLX1349U/02/01/2019 13:44**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc frt number plate garnish	0.00	0.00	<i>Not</i> *15.00 F ✓
2	1		*1 pc frt support panel	0.00	0.00	<i>Bul</i> *290.00 F ✓
3	1		*1 pc air-con condenser	0.00	0.00	*210.00 F ?
Sub Total (S\$)						515.00
+ Margin on L,N Items 10.00% (S\$)						51.50
Total Parts (S\$)						566.50

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SLX1349U/02/01/2019 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SLX1349U/02/01/2019 13:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Item No	Vehicle No	Estimate No	Item Description	Quantity	Price
			Total Bld		1314.84
			Labour charges to remove rear boot upholstery to rear panel and left boot access		200.00
			Labour charges to cut out damaged body panels sign and straighten damaged parts and weld replacement body panel. To replace damaged parts and transfer necessary fittings		1000.00
			To paint replacement parts and repair sections in and outside		100.00
			To install replaced and repaired sections		200.00
			Labour charges to check affected electrical wiring circuit replace and test reverse sensor		20.00
			Total		1314.84