

22/02/2003

ASS. REC. BY:

REF

es/MSG18023247/Kvd3er

Special Instruction:

Surveyor
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Pauline them

of

MSG

Date/Time:

28/12/10 11:37pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

GBC 4158M

Insured:

yp5566x

at Workshop m/s

Tong Luek

Tel:

6250 0088

of

160 Sin Ming Drive #07-01/06

Policy No:

B28905427MKC

Claim No:

580201

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/12/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

11:43pm 28/12/18

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 4158M - NA/MSG18022955/h4
	YP5566x - NA/MSG18022955/h4
31/12/18	Send preli revised via merimen
24/1	1/1 Lng 8550d email & confirm (Recd 31/12/20, 37/1)

ASS. REC. BY:

REF:

44/16561

ASSIGNMENT

GBCK158

JTP 288M

Yr Regn: 04, 12

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 L.B. %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. Vito

c.c.

2.143

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

201423

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDF 83960323 709 262

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

7040 225/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

4

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

22/12/18

D.O.I.

28/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/12 File path to Catherine

RECEIVED 2.4

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 24/1 - typist

Report Format:

Lump Sum / I.B.I: (\$

merimen

5500/-

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

: Photos

: Others

TOTAL

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Dec 2018		28 Dec 2018 11:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NTPM (SINGAPORE) PTE LTD, Co. Reg. No.: 198600763K		
Main Claimant:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z		
Vehicle Reg. No.:	GBC4158M	Date of Loss:	22/12/2018 11:00 - :59 [79 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 580201	Policy/Cover Note No.:	B28905427MKC (Comprehensive) Coverage: 27/02/2018 - 26/02/2019
Vehicle Reg. No. (Insured):	YP5566X	Policy No. (Claimant):	
		Excess:	
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01/06 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/12/2018]		
Driver/Custodian (Insured):	NG HON SEN (), NRIC: S1252078F, Tel: +6582229709		
Adj Asg. Remarks:	ON WP, Candy (Workshop) requested Kenneth from LKK to survey this car. GRAB CASE. LIABILITY 100%. TP AGREE WITH SJE - ASSIGN MSIG IN HOUSE SURVEYORS. CONTACT: 6250 0088		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 31 Dec 2018

Preliminary Advice

Insured Vehicle No	: YP5566X		
TP Vehicle No	: GBC4158M	Accident Date	: 22/12/2018
Make	: MERCEDES-BENZ VITO 113	Assignment Date	: 28/12/2018
Date of Inspection	: 28/12/2018	Est. Duration of Repair	: 6.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,016.70
Revised Amount	:S\$	6,573.00
Check Items (Estimated)	:S\$	353.70
Total	:S\$	6,926.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/12/2018 18:45
Date Of Accident	22/12/2018 11:15
Exact Location Of Accident	BKE TOWARDS PIE (CHANGI)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBC4158M
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	OSMAN.AFFAN@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-88762075
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	VITO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	
Driver	
Name of Driver	ABDUL LATIFF BIN MUHAMMAD FIRDAUS
NRIC No	S8733178D
Date Of Birth	15/10/1987
Occupation	OUTDOOR
Date Of Driving Pass	14/06/2016
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91569572
Fax Number	
Contact Number	
EMail Address	DSMANAGEMENT@ASIA.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : SULAIMAN GENDER: : MALE
Passenger 2	NAME: : SYISY GENDER: : MALE
Passenger 3	NAME: : SHIKIN GENDER: : FEMALE
Passenger 4	NAME: : ANISAH GENDER: : FEMALE
Passenger 5	NAME: : ELIAS GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG THE EXPRESSWAY WHILE SLOWING DOWN SUDDENLY THIRD PARTY COLLIDED ONTO THE REAR OF MY VEHICLE. MY FAMILY MEMBERS AND ME WILL BE CONSULTING A DOCTOR LATER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP5566X
-----------------------------	---------

Vehicle Make/Model/Colour	MITSUBISHI / CANTER / SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NG HON SEN
NRIC/Passport Number	S1252078F
Contact Number	82229709
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	4
Passenger 1	NAME: : P1 GENDER: : MALE
Passenger 2	NAME: : P2 GENDER: : MALE
Passenger 3	NAME: : P3 GENDER: : MALE

DETAILS OF INJURED PERSON 1

Name	SULAIMAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBC4158M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	SYISY
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBC4158M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 3

Name	SHIKIN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBC4158M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 4

Name ANISAH
Approximate Age
Injuries Sustain
Injured person in which vehicle? GBC4158M
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 5

Name ELIAS
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
VICTOR ANG


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

BKE - PIE (charging)



veh A: GBC4158M
veh B: YP5566X

ACCIDENT STATEMENT (2000 characters)

I WAS TRAVELLING ALONG THE EXPRESSWAY WHILE SLOWING DOWN
SUDDENLY THIRD PARTY COLLIDED ONTO THE REAR OF MY VEHICLE. MY
FAMILY MEMBERS AND ME WILL BE CONSULTING A DOCTOR LATER.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
ANG QI HAO, VICTOR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

22 December 2018 at 5:38 PM

Date/Time:

22 December 2018 at 5:38 PM



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

ATTN :

TEL : 6849 8118

FAX : 6849 8715

YOUR REF NO : NG HON SEN

CLAIM TYPE : OWN DAMAGE

TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD

ACCIDENT DATE : 22/12/2018

ESTIMATE

NO : QUOT201812-000080(00)

DATE : 26/12/2018

POLICY NO : 999995580

VEH REG NO : GBC4158M

MAKE/MODEL : MERCEDES BENZ VITO 113
LONG

CHASSIS NO : WDF63960323709262

ENGINE NO : 65194030859511

REG. DATE : 2011

Estimate Repair Cost to Vehicle No : GBC4158M

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear wiper arm	1	120.00	120.00
2 Rear wiper blade	1	63.00	63.00
3 Tailgate	1	2,485.00	2,485.00
4 Tailgate centre logo	1	35.00	35.00
5 Tailgate "VITO" emblem	1	58.00	58.00
6 Tailgate 'C&C' emblem	1	38.00	38.00
7 Tailgate centre garnish	1	100.00	100.00
8 Tailgate outer handle	1	182.00	182.00
9 Tailgate lock	1	211.00	211.00
10 Tailgate centre trim rivets	5	9.00	45.00
11 Tailgate trimboard	1	152.00	152.00
12 Tailgate trimboard clips	15	10.00	150.00
13 Rear end panel (outer)	1	262.00	262.00
14 Rear bumper (centre)	1	732.00	732.00
15 Rear bumper side - LH	1	0.00	0.00
16 Rear bumper reflector - LH	1	27.00	27.00
17 Rear bumper clips	15	9.00	135.00
18 Taillamp assy - LH	1	280.00	280.00
19 Taillamp lower garnish - LH	1	40.00	40.00
			5,115.00
			Less 10%
			4,603.50
SPECIAL NET			
20 Rear windscreen sealant	1	60.00	60.00
21 Rear bumper reverse sensor (set)	1	380.00	380.00
22 Tailgate "70km/h" sticker	1	25.00	25.00
23 Rear number plate	1	40.00	40.00
			505.00
LABOUR			
24 To remove and refit rear bumper sensor	1	100.00	100.00
25 To remove and refit rear windscreen glass	1	150.00	150.00
26 To transfer damaged tailgate interior mechanism to new tailgate	1	150.00	150.00
27 To check and rectify wiring system and focus of lightings	1	80.00	80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

ATTN :

TEL : 6849 8118

FAX : 6849 8715

YOUR REF NO : NG HON SEN

CLAIM TYPE : OWN DAMAGE

TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD

ACCIDENT DATE : 22/12/2018

ESTIMATE

NO : QUOT201812-000080(00)

DATE : 26/12/2018

POLICY NO : 999995580

VEH REG NO : GBC4158M

MAKE/MODEL : MERCEDES BENZ VITO 113
LONG

CHASSIS NO : WDF63960323709262

ENGINE NO : 65194030859511

REG. DATE : 2011

Estimate Repair Cost to Vehicle No : GBC4158M

Description	Quantity	Unit Price	Amount
		S\$	S\$
28 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
29 To putty and spray paint on affected areas	1	1,000.00	1,000.00
30 To apply rust-proofing on replaced and repaired panels	1	160.00	160.00
			2,640.00
	8016.70	TOTAL	S\$ 7,748.50
		ADD GST @ 7%	542.40
		GRAND TOTAL	S\$ 8,290.90

SINGAPORE DOLLAR EIGHT THOUSAND TWO HUNDRED NINETY AND CENTS NINETY ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

Not Authorised

ATTN :

TEL : 6849 8118

FAX : 6849 8715

Resurvey B&Pain

YOUR REF NO : NG HON SEN

CLAIM TYPE : OWN DAMAGE

TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD

ACCIDENT DATE : 22/12/2018

6 days

ESTIMATE

NO : QUOT201812-000080(00)

DATE : 26/12/2018

POLICY NO : 999995580

VEH REG NO : GBC4158M

MAKE/MODEL : MERCEDES BENZ VITO 113
LONG

CHASSIS NO : WDF63960323709262

ENGINE NO : 65194030859511

REG. DATE : 2011

Estimate Repair Cost to Vehicle No : GBC4158M

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear wiper arm	1	120.00	120.00 ✓
2 Rear wiper blade	1	63.00	63.00 ✓
3 Tailgate <i>2138.93</i>	1	2,485.00	2,485.00 ✓
4 Tailgate centre logo	1	35.00	35.00 ✓
5 Tailgate "VITO" emblem	1	58.00	58.00 ✓
6 Tailgate 'C&C' emblem	1	38.00	38.00 ✓
7 Tailgate centre garnish	1	100.00	100.00 ✓
8 Tailgate outer handle	1	182.00	182.00 ✓
9 Tailgate lock	1	211.00	211.00 ✓
10 Tailgate centre trim rivets	5	9.00	45.00 ✓
11 Tailgate trimboard	1	152.00	152.00 ✓
12 Tailgate trimboard clips	15	10.00	150.00 ✓
13 Rear end panel (outer)	1	262.00	262.00 ✓
14 Rear bumper (centre)	1	732.00	732.00 ✓
15 Rear bumper side - LH	1	0.00	0.00 ✓
16 Rear bumper reflector - LH	1	27.00	27.00 ✓
17 Rear bumper clips	15	9.00	135.00 ✓
18 Taillamp assy - LH	1	280.00	280.00 ✓
19 Taillamp lower garnish - LH	1	40.00	40.00 ✓
<i>Rear w/screen glass. \$735.00 shortland ✓</i>			5,115.00
		Less 10%	511.50
			4,603.50
SPECIAL NET			
20 Rear windscreen sealant	1	60.00	60.00 ✓
21 Rear bumper reverse sensor (set)	1	380.00	380.00 ✓
22 Tailgate "70km/h" sticker	1	25.00	25.00 ✓
23 Rear number plate	1	40.00	40.00 ✓
			505.00
LABOUR			
24 To remove and refit rear bumper sensor	1	100.00	100.00 ✓
25 To remove and refit rear windscreen glass	1	150.00	150.00 ✓
26 To transfer damaged tailgate interior mechanism to new tailgate	1	150.00	150.00 ✓
27 To check and rectify wiring system and focus of lightings	1	80.00	80.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

ATTN :

TEL : 6849 8118

FAX : 6849 8715

YOUR REF NO : NG HON SEN

CLAIM TYPE : OWN DAMAGE

TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD

ACCIDENT DATE : 22/12/2018

ESTIMATE

NO : QUOT201812-000080(00)

DATE : 26/12/2018

POLICY NO : 999995580

VEH REG NO : GBC4158M

MAKE/MODEL : MERCEDES BENZ VITO 113
LONG

CHASSIS NO : WDF63960323709262

ENGINE NO : 65194030859511

REG. DATE : 2011

Estimate Repair Cost to Vehicle No : GBC4158M

Description	Quantity	Unit Price	Amount
		S\$	S\$
28 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
29 To putty and spray paint on affected areas	1	1,000.00	1,000.00
30 To apply rust-proofing on replaced and repaired panels	1	160.00	160.00
			2,640.00
	8678.20	TOTAL	S\$ 7,748.50
		ADD GST @ 7%	542.40
		GRAND TOTAL	S\$ 8,290.90

SINGAPORE DOLLAR EIGHT THOUSAND TWO HUNDRED NINETY AND CENTS NINETY ONLY

\$ 7,234.50
20% 1,446.90
\$ 5,787.60

5500h
Jump Sum \$ 5,750.00
7% 402.50
\$ 6,152.50

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Dec 2018		28 Dec 2018 11:37 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	NTPM (SINGAPORE) PTE LTD, Co. Reg. No.: 198600763K	
Main Claimant:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z	
Vehicle Reg. No.:	GBC4158M	Date of Loss: 22/12/2018 11:00 - :59 [79 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 580201	Policy/Cover Note No.: B28905427MKC (Comprehensive) Coverage: 27/02/2018 - 26/02/2019
Vehicle Reg. No. (Insured):	YP5566X	Policy No. (Claimant):
		Excess:
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01/06 Sin Ming Autocity, 575722 Sin Ming - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 27/01/2019]	
Driver/Custodian (Insured):	NG HON SEN (), NRIC: S1252078F, Tel: +6582229709	
Adj Asg. Remarks:	ON WP. Candy (Workshop) requested Kenneth from LKK to survey this car. GRAB CASE. LIABILITY 100%. TP AGREE WITH SJE - ASSIGN MSIG IN HOUSE SURVEYORS. CONTACT: 6250 0088	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*GBC4158M (580201)

[YP5566X]

TP

DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Dec 22 2018 11:00AM

[NTPM (SINGAPORE) PTE LTD]




Tong Luck Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print	
1	27/12/18 14:49	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: YP5566X, Claimant: NTPM (SINGAPORE) PTE LTD</small>	 Load HTM		
No	Finalized On		Thumbnail	Print	
1	31/12/18 11:16	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	 Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print	
LKK Auto Consultants Pte Ltd (HQ)					
1	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	31/12/18 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	24/01/19 11:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
30	24/01/19 11:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
31	24/01/19 11:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/12/18 14:49	GBC4158M E-FILE REPORT From: SC - Reg. No: YP5566X, Claimant: NTPM (SINGAPORE) PTE LTD	 Load PDF	
2	27/12/18 14:50	TP estimate and GIA Report	 Load PDF	
3	27/12/18 14:51	tp agree with sje -assign IHS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18023247/KVD3E2

Date: 24/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28905427MKC
Claimant Vehicle No : GBC4158M **Insured Vehicle No :** YP5566X
 Date of Loss: 22/12/2018 Nature of Claim: TP Claim No: 580201

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC4158M**
 Make & Model: MERCEDES-BENZ VITO 113, 2.1 D Long (M) Engine No: 65194030859511
 Reg. Date: 23/04/2012 (Man. Year: 2011) Chassis No: WDF63960323709262
 Colour: Red Odometer: 201423 km
 Engine Capacity: 2143 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/60 R16 Rear Tyre Size: 225/60 R16
 Front Left Side: Toyo 9 mm Rear Left Side: Roadstone 4 mm
 Front Right Side: Toyo 9 mm Rear Right Side: Roadstone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,038.20	5,163.04	875.16	14.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,760.00	880.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,678.20	6,923.04	1,755.16	20.22
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	8,678.20	5,500.00	3,178.20	36.62
+ GST 7.00/7.00% (S\$)	607.47	385.00	222.47	36.62
Nett Amount (S\$)	9,285.67	5,885.00	3,400.67	36.62

INSPECTION

Date of Assignment: 28/12/2018
 Date Inspected: 28/12/2018 Inspected At: Tong Luck Auto Pte Ltd (HQ)
 160 Sin Ming Drive, #07-01/06 Sin Ming
 Autocity
 Singapore 575722
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Jan 2019)	
Parts:	N/A	MERCEDES-BENZ VITO 113 2.1 D Long (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4158M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WIPER ARM	Dented	120.00 FL	*120.00 FL
2	1		*REAR WIPER BLADE	Cut	63.00 FL	*63.00 FL
3	1		*TAILGATE	Bent	2,485.00 FL	*2,138.93 FL
4	1		*TAILGATE CENTRE LOGO	Necessary	35.00 FL	*35.00 FL
5	1		*TAILGATE VITO EMBLEM	Necessary	58.00 FL	*58.00 FL
6	1		*TAILGATE C&C EMBLEM	Necessary	38.00 FL	*38.00 FL
7	1		*TAILGATE CENTRE GARNISH	Dented / Warped	100.00 FL	*100.00 FL
8	1		*TAILGATE OUTER HANDLE	Serviceable	182.00 FL	*- FL
9	1		*TAILGATE LOCK	Repair	211.00 FL	*- FL
10	5		*TAILGATE CENTRE TRIM RIVETS	Necessary	45.00 FL	*45.00 FL
11	1		*TAILGATE TRIMBOARD	Buckled	152.00 FL	*152.00 FL
12	15		*TAILGATE TRIMBOARD CLIPS	Necessary	150.00 FL	*150.00 FL
13	1		*REAR END PANEL (OUTER)	Bent	262.00 FL	*262.00 FL
14	1		*REAR BUMPER (CENTRE)	Cracked	732.00 FL	*732.00 FL
15	1		*REAR BUMPER SIDE - LH	Cracked	298.00 FL	*298.00 FL
16	1		*REAR BUMPER REFLECTOR - LH	Cracked	27.00 FL	*27.00 FL
17	15		*REAR BUMPER CLIPS	Necessary	135.00 FL	*135.00 FL
18	1		*TAILLAMP ASSY - LH	Cracked	280.00 FL	*280.00 FL
19	1		*TAILLAMP LOWER GARNISH - LH	Cracked	40.00 FL	*40.00 FL
20	1		*REAR W/SCREEN GLASS	Shattered	735.00 FL	*735.00 FL
21	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
22	1		*SET REAR BUMPER REVERSE SENSOR	Scratched	380.00 FS	*200.00 FS
23	1		*TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
24	1		*REAR NUMBER PLATE	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,653.00	5,703.93
- List Item Discount on L Items 10.00/10.00% (S\$)	614.80	540.89
Total Parts (S\$)	6,038.20	5,163.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	50.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
3	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE	New	150.00	60.00
4	TO CHECK AND RECTIFY WIRING SYSTEM AND FOCUS OF HEADLIGHTS	New	80.00	20.00
5	TO PANEL BEAT AND STRAIGHTEN REAR CHASSIS FRAME, REAR FLOORBOARD PANEL, TO CUT AND WELD REAR END PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	800.00
6	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	650.00
7	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	160.00	60.00
Gross Labour Cost (\$\$)			2,640.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >