

AIG Aisa Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

3RD PARTY CLAIM ESTIMATION

Vehicle number	SLV8532X
Make / Model	AUDI / A3
Chassis number	WAUZZZ8V7J1028453
Accident date	24 December 2018
Reference	1812-38

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BONNET <i>ist</i>	2659.85 ✓ <i>2501.00</i>
2	FRONT BONNET ABSORBER <i>new</i>	187.35 X
1	BONNET LOCK <i>Down</i>	187.20 ✓
1	BONNET INSULATOR <i>new</i>	184.00 X
2	BONNET HINGE <i>new</i>	90.40 X
1	BONNET SAFETY LOCK <i>new</i>	56.66 X
1	BONNET RUBBER <i>new</i>	38.95 X
2	FRONT HEADLAMP ASSY <i>SVC</i>	5667.85 X
2	FRONT HEADLAMP BRACKET <i>new</i>	493.05 X
1	FRONT BUMPER <i>Replaced / distorted</i>	1814.50 ✓ <i>1667.00</i>
1	FRONT BUMPER INNER PAD <i>deformation</i>	239.90 ✓
1	FRONT BUMPER SIDE RETAINER <i>SVC</i>	54.00 X
1	FRONT BUMPER REINFORCEMENT BRACKET <i>Distorted</i>	622.65 ✓
2	FRONT BUMPER SIDE COVER <i>new</i>	327.90 X
1	FRONT GRILLE <i>broken</i>	1277.99 ✓ <i>1040.80</i>
1	FRONT GRILLE EMBLEM <i>crack</i>	103.94 ✓
1	AIR CON CONDENSER <i>ist / punctured</i>	691.74 ✓ <i>7829.98</i>
1	AIRCON FAN ASSY <i>new</i>	1571.94 X <i>7046.98</i>
1	RADIATOR <i>ist / punctured</i>	775.75 ✓
		17045.62
Less 10 %		1704.56
Subtotal		15342.06
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
Balance B/F		15341.06
1	FRONT NUMBER PLATE WITH CASING <i>ist</i>	80.00 <i>45/-</i>
1 SET	FRONT BUMPER CLIP <i>new</i>	50.00 <i>20/-</i>
1 SET	FRONT GRILLE CLIP <i>new</i>	40.00 <i>20/-</i>
1 BOT	COOLANT <i>SVC</i>	50.00 X
Subtotal		220.00
Balance C/F		15561.06
LABOUR AND MISCELLANEOUS CHARGES		
Balance B/F		15561.06
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 <i>30/-</i>
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	200.00 <i>80/-</i>
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	200.00 <i>50/-</i>
4	DIAGNOIS CHECK AND CLEAR FAULT CODE	500.00 <i>new</i>
5	PANEL BEATING ON AFFECTED AREAS	1200.00 <i>800/-</i>
6	SPRAY PAINTING ON AFFECTED AREAS	1000.00 <i>600/-</i>
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>40/-</i>
Subtotal		3310.00
Grand total		18871.06

28/12/2018 @ 12:00pm
Not Antimal 8 days
L/Sum LKK Auto
Tyan



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC: 201015366H

AIG Aisa Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way #07-16
 Singapore 079120

Vehicle number	SLV8532X
Make / Model	AUDI / A3
Chassis number	WAUZZZ8V7J1028453
Accident date	24 December 2018
Reference	1812-38

3RD PARTY SUPPLEMENTARY

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	HOSE JOINT <i>torn</i>	30.66 ✓
1	RADIATOR SIDE BRACKET <i>crack</i>	54.12 ✓
1	RADIATOR GRILLE <i>replaced</i>	1293.54 X
1	SUPPORT PANEL <i>broken</i>	690.12 ✓
1	FRONT BUMPER LOWER GRILLE <i>broken</i>	140.94 ✓
1	FRONT BUMPER SPONGE <i>1st / damaged</i>	107.04 ✓
1	FRONT BUMPER UNDERCOVER <i>torn</i>	471.66 ✓
1	ENGINE LOWER COVER <i>torn</i>	236.58 ✓
1	AIRCON PIPE <i>broken</i>	652.86 ✓
1	AIRCON PIPE HOSE <i>1st</i>	849.66 ✓
		4527.18
		Less 10 %
		452.72
		Subtotal
		4074.46

3233.64
 2910.27

28/12/2018
ryan

LKK Auto

8731.98

SUP 2910.27
 11642.25

[Handwritten signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4/89300/-