

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD4992U

DATE: 27. Dec. 2018

MAKE : HYUNDAI

MODEL : i40

DOA: 26. Dec. 2018

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover <i>X rep</i>			\$544.50
1	Front Bumper Side Bracket – LH ✓			\$24.60
1	Front Bumper Top Bracket – LH ?			\$22.40
10	Front Bumper Clips <i>X</i>		\$2.20	\$22.00
1	Headlamp Panel <i>X</i>			\$907.40
1	Headlamp – LH <i>X</i>			\$1,388.00
1	Front Fender – LH <i>X rep</i>			\$566.30
1	Front Fender Shield – LH <i>X</i>			\$174.90
SUB TOTAL				\$3,650.10
LESS 20%				\$730.02
DISCOUNTED TOTAL				\$2,920.08
				\$-
Labour Charge				
1	Panel Beating			<i>200</i> \$500.00
1	Spray Painting Charge			\$500.00 <i>400</i>
1	Tuff Kote			\$50.00 <i>X</i>
1	Wiring Charge			\$50.00 <i>X</i>
TOTAL LABOUR				\$1,100.00
ESTIMATE TOTAL				\$4,020.08
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

Kohli 1/11/18
28/12/18 10:20h
2 days
4/5
After Repair photo

Larry Ng