

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMF9836K (AXA)

Accident Date : 20-12-2018

Our Ref : SGP299M / CHAN

CHONG FOO YUAN

C/O ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND. EST .SECTOR C

01-76

SINGAPORE 575642

Date : 26-12-2018

*Not with car
11/12/18
Repair after 2 days*

ESTIMATE COST OF REPAIR FOR TOYOTA HARRIER 2.4A SGP299M

1 PC FRONT N/S BUMPER SIDE RETAINER

Nil \$74.90 ✓

1 PC FRONT N/S BUMPER FOGLAMP

\$346.50 7

1 PC N/S HEADLAMP

2 \$1,921.80 X
\$2,343.20

LESS 25% \$585.80
\$1,757.40

\$1,757.40

1 PC FRONT BUMPER FASCIA (ACCESSORIES)

1 \$900.00 SN X

1 PC FRONT N/S BUMPER PARKING SENSOR

Nil \$250.00 SN ✓

TO PUTTY AND SPRAY REPLACED PARTS

\$300.00 *2801*

TO REMOVE & RENEW FRONT BUMPER, PARKING SENSOR, HEADLAMP AND PANEL
BEATING FRONT N/S FENDER, ALIGN AND READJUST REPLACED PART

\$400.00 *2501*
\$3,607.40

Singapore Dollars Three Thousand Six Hundred Seven And Cents Forty Only