

INS. CASE OWNER: CC 4/LPC1802 3207, UH 2022 LKK IDAC

Surveyor: cks ASSIGNMENT DOI: 28/12/18 Date / Time: 28/12/18

Pre-assign / CCU / FTE
Insured Vehicle No. ABB 57906 Claim No. 18/01/19/01258
Name of Insured ADVERTISE DESIGN VN Policy No. 215V/05001244
Insured Tel No. HP: 90/12/18 Make / Model: PINT
Excess Sec II :SS D.O.A. 28/12/18 Place of Accident: BET HIEPACH RD & NINH NHI
Is driver the owner? (YES / NO) Nature of Accident: DRIVER BEAT
If NO, Driver Name / Age: DRIVER BEAT OI GIA REPORT: YES / NO, TP GIA REPORT: YES / NO
Driver Tel No.: (V/L: FB / NO) Insured Liability: % Final ? Yes / No

SKX 8217P
INSRS: WSP: PRECISE INSRS: WSP: INSRS: WSP: INSRS: WSP:
Tel: Tel: Tel: Tel: Tel: Tel:
Liability: Liability: Liability: Liability: Liability: Liability:
RMKS: RMKS: RMKS: RMKS: RMKS: RMKS:

Date / Time		STAGE	DATE / PIC
10/1/19	SKX 8217P - 4	Non-Reporting hr (1st):	
20/1/19	ABB 57906 - 7	Non-Reporting hr (2nd):	
		Non-Reporting hr (Final):	
		Notification hr (if non-pickup):	
		Call OI:	
		After call hr to OE:	
01/02/19		Documentation Check List: Handler	Typist
03/02/19		Notification hr (if non-pickup)	
02/02/19		After call hr to OE:	
		Authorisation To Act:	
30/02/19		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
3-6-19		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time: 01/02/19	Sent By: JOY
FINALIZATION	Date/Time: 30/08/19	Confirm with: YAN HONG
Repair Cost: <u>46</u>	\$S 4,600.00	5 days Reduction: 39 %
FINAL SETTLEMENT	Date/Time: 30/08/19	Confirm with: YAN HONG
Final Liability: 0%	100 (Assessed / Assessed)	BOLA S/N No: 27
Repair Cost: (w/loss)	\$S 4,922.00	
Loss of Rental (LOR):	\$S -	days
Loss of Use (LOU):	\$S 480.00	5 x 8 days
Loss of Income (LOI):	\$S -	days
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LO ☐	[Tick only one]
GIA/LTA Search	\$S 37.00	
Medical:	\$S -	
Disbursement:	\$S -	(e.g. Tow/ Independent)
Legal Cost:	\$S -	
Total:	\$S 5,439.00	Global Sum \$S:
FINAL PAYMENT	Date/Time: 30/08/19	Confirm with: YAN HONG
Payee 1:	\$S 5,439.00	Name 1: PRECISE AUTO SERVICE
Payee 2: (Strike if N.A.)	\$S -	Name 2: -
Payee 3: (Strike if N.A.)	\$S -	Name 3: -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18023267/Ujb3

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 28-12-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 5390G	Veh. Inspected	SKX 8292P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/12/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/12/2018	Inspection Date	28/12/2018
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 0800A

Vehicle Details

Vehicle No.: SKX8292P

Vehicle to be Exported: No

Intended Deregistration Date: 28 Dec 2018

Vehicle Make: HONDA

Vehicle Model: FREED 1.5G A

Primary Colour: White

Manufacturing Year: 2008

Engine No.: L15A2304953

Chassis No.: GB31004915

Maximum Power Output: 87.0 kW (116 bhp)

Open Market Value: \$17,582.00

Original Registration Date: 18 Dec 2009

First Registration Date: 18 Dec 2009

Transfer Count: 4

Actual ARF Paid: \$17,582.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Dec 2019

PARF Rebate Amount: \$8,791.00

Intended COE Rebate Details

COE Expiry Date: 17 Dec 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$17,189.00

COE Rebate Amount: \$1,663.00

Total Rebate Amount: \$10,454.00

The information contained herein is correct as at 28 Dec 2018

OK

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

14-04-19

Accident Date : 24-12-18

OUR REF : SKX 8292P/T/18

Wayaaauto Trading

Blk 3 Queen's Road

#08-149

Singapore 260003

LPC J Marcus

Date in/out : 26/12/18 to 31/12/18

not Addressed
Noble
2/5 = 4600/
527.

ESTIMATE BILL ON VEH. NO. : SKX 8292P

VEH. MODEL : HONDA FREED

CHASSIS NO. : GB31004915

LIST ITEM

Tail Gate		Body/100	1,460.20
Tail Gate Weather Stripe		tail	120.80
Tail Gate Stopper	2pcs @ 12.40	11	24.80 X
Tail Gate Badge		11	37.20
Tail Gate Emblem 'Freed'		11	42.10
Tail Gate Inner Trim Board		11	381.80 X
Tail Gate Inner Lock		10/30	198.50
Tail Gate Inner Lock Striker		11	26.70 X
Rear Windscreen Glass Moulding (Side)	2pcs @ 31.30	11	62.60
Rear Windscreen Glass Inner Seal		11	48.00
Rear Windscreen Glass Clips	14pcs @ 5.50	11	77.00 X
Rear Bumper Fascia		10/10	895.20
Rear Bumper Side Retainer	2pcs @ 28.40	11	56.80 X
Rear Bumper Bracket	2pcs @ 26.10	11	52.20 X
Rear Bnumper Centre Beam		11	68.50
Rear Bumper Tow Cover		11	32.40 X
Rear Bumper Clips	10pcs @ 5.50	11	55.00

Rear End Panel (Outer)		20/ser	590.00
Rear End Panel (Inner)		1	381.40 X
Rear End Panel Top Trim		1/1	241.60
Rear End Panel Top Trim Clips	4pcs @ 5.50	17	22.00 X
Rear Fender Inner Trim Board	2pcs @ 400.80	2/one	801.60
Rear Fender Inner Trim Board Clips	16pcs @ 5.50 60	1/1	88.00
	4681.30		5,764.40
	3745.04	Less Discount 20%:	1,152.88
			4,611.52

SPECIAL NETT ITEM


Reverse Sensor with Control Unit	1/ser	5/1	380.00
Rear Windscreen Glass Sealant		1/1	60.00

LABOUR CHARGE

To Check Wiring System.	30	80.00
To Tuff Coat Affected Areas.	60	150.00
To Remove & Refix Interior Upholstery.	10	180.00
To Remove & Refix Rear Windscreen Glass.	120	180.00
To Respray Affected Areas.	880	900.00
To Renew Damaged Parts, Straighten & Repair & Aligned All Parts.	600	1,000.00

7,541.52
GST 7%: 527.91
AMOUNT DUE : 8,069.43

5755.04



Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 28 December 2018 11:43 AM
To: assignments@lkkauto.com; Precise Auto Service; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: Our Ref: 18/18/19/021258 RE: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.
Attachments: 27122018113805.pdf; 27122018105545.pdf

11.49am @ 28/12/18
Arine
vehicle in

Dear Catherine/Nivitha

Please refer to the attached and follow up with TP workshop for pre-repair inspection.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: GERALD POH WEE BIN
Sent: Thursday, 27 December, 2018 11:40 AM
To: Precise Auto Service
Cc: MT_Claim_SG
Subject: RE: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.


WITHOUT PREJUDICE

Our Ref : 18/18/19/VC05/021258

Dear Arine,

Please see attached and revert.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Precise Auto Service [mailto:Support@preciseauto.sg]
Sent: Thursday, 27 December, 2018 11:01 AM
To: MT_Claim_SG
Subject: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.

Dear Sir,

We refer to the above mentioned matter, herewith enclosed a 2 days notice for your attention.

Please arrange to do pre-repair inspection for **SKX 8292P** in our workshop ASAP.

Thank You!

Best Regards
Arine

--

T : 6745 7367 | **F** : 6841 3390

E : support@preciseauto.sg

W : www.preciseauto.sg

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



PRECISE AUTO SERVICE

準 確 汽 車 服 務

Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>


Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 9 January 2019 1:32 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Our Ref: 18/18/19/021258 RE: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.
Attachments: GBB5390G 241218.PDF

Dear Shu Pei

Attached is our Insured's GIA report for your handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706




From: ONG LI LI
Sent: Thursday, 3 January, 2019 5:44 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Our Ref: 18/18/19/021258 RE: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.

Dear Shu Pei

Our Insured has still not reported the accident. We are following up.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 2 January, 2019 7:48 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Our Ref: 18/18/19/021258 RE: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SKX 8292P at M/s Precise Auto Service on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Friday, 28 December 2018 11:52 AM

To: 'ONG LI LI' <long@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <int_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 18/18/19/021258 RE: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: ONG LI LI (<mailto:llong@lonpac.com>)

Sent: Friday, 28 December 2018 11:43 AM

To: assignments@lkkauto.com; Precise Auto Service <Support@preciseauto.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: Our Ref: 18/18/19/021258 RE: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.

Dear Catherine/Nivitha

Please refer to the attached and follow up with TP workshop for pre-repair inspection.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: GERALD POH WEE BIN

Sent: Thursday, 27 December, 2018 11:40 AM

To: Precise Auto Service

Cc: MT_Claim_SG

Subject: RE: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.

WITHOUT PREJUDICE

Our Ref : 18/18/19/VC05/021258

Dear Arine,

Please see attached and revert.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Precise Auto Service (<mailto:Support@preciseauto.sg>)

Sent: Thursday, 27 December, 2018 11:01 AM

To: MT_Claim_SG

Subject: Pre-repair Inspection for SKX 8292P. Your Insured Vehicle no : GBB 5390G.

Dear Sir,

We refer to the above mentioned matter, herewith enclosed a 2 days notice for your attention.

Please arrange to do pre-repair inspection for **SKX 8292P** in our workshop ASAP.

Thank You!

Best Regards
Arine

--

T : 6745 7367 | **F** : 6841 3390

E : support@preciseauto.sg

W : www.preciseauto.sg

A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



Follow us on social media:



<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>



This email has been checked for viruses by AVG antivirus software.
www.avg.com

4

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 # 02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

28-08-19

Your Ref. : GBB 5390G

Vehicle No. : SKX 8292P/T/18(SJE)

M/s LONPAC Insurance BHD

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

ATTN : MS. Joy (LKK Motor Claim Department)

Dear Sir

RE : ACCIDENT INVOLVING VEHICLE NO. SKX 8292P AND GBB 5390G ON 24 DEC 2018
@ 16 : 25 HRS ALONG TRAFFIC JUNCTION BETWEEN AIRPORT RD & EUNOS LINK

We enclose herewith the discharge voucher duly executed as requested for your attention.

Kindly forward us payment of **\$5,439.00** within the next fourteen (14) days to be issued in favour of "PRECISE AUTO SERVICE".

Your prompt reply of the above claims will be much appreciated.

Yours faithfully



Yan Hong



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18023267/Uhb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 04-09-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 5390G	Veh. Inspected	SKX 8292P	
Policy No.	Z18VC05001294	Coverage (\$)	0.00	
Claim No.	18/18/19/VC05/021258	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	28/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GB31004915	Colour	WHITE	
Odometer	252848	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	ROADWEAR	6 mm	
L/H Front Tyre	185/70 R14	ROADWEAR	6 mm	
R/H Rear Tyre	185/70 R14	ROADWEAR	6 mm	
L/H Rear Tyre	185/70 R14	ROADWEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/12/2018	Inspection Date	28/12/2018	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 8292P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE	BADLY DENTED	1,460.20	1,460.20
1	TAIL GATE WEATHER STRIPE	TWISTED	120.80	120.80
2	TAIL GATE STOPPER @\$12.40	NOT NECESSARY	24.80	-
1	TAIL GATE BADGE	NECESSARY	37.20	37.20
1	TAIL GATE EMBLEM 'FREED'	NECESSARY	42.10	42.10
1	TAIL GATE INNER TRM BOARD	NOT NECESSARY	381.80	-
1	TAIL GATE INNER LOCK	DENTED / JAMMED	198.50	198.50
1	TAIL GATE INNER LOCK STRIKER	NOT NECESSARY	26.70	-
2	REAR WINDSCREEN GLASS MOULDING (SIDE) @\$31.30	NECESSARY	62.60	62.60
1	REAR WINDSCREEN GLASS INNER SEAL	NECESSARY	48.00	48.00
14	REAR WINDSCREEN GLASS GLASS CLIPS @\$5.50	NOT NECESSARY	77.00	-
1	REAR BUMPER FASCIA	DENTED / DEFORMED	895.20	895.20
2	REAR BUMPER SIDE RETAINER @\$28.40	NOT NECESSARY	56.80	-
2	REAR BUMPER BRACKET @\$26.10	NOT NECESSARY	52.20	-
1	REAR BUMPER CENTRE BEAM	BENT	68.50	68.50
1	REAR BUMPER TOW COVER	NOT NECESSARY	32.40	-
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	REAR END PANEL (OUTER)	DENTED / BENT	590.00	590.00
1	REAR END PANEL (INNER)	TO REPAIR SEE LABOUR	381.40	-
1	REAR END PANEL TOP TRIM	TWISTED	241.60	241.60
4	REAR END PANEL TOP TRIM CLIPS @\$5.50	NOT NECESSARY	22.00	-
2	REAR FENDER INNER TRIM BOARD @\$400.80	DEFORMED / CRACKED	801.60	801.60
16	REAR FENDER INNER TRIM BOARD CLIPS @\$5.50	NECESSARY	88.00	60.00
	LESS 20% DISCOUNT		-1,152.88	-936.26
			4,611.52	3,745.04
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR WITH CONTROL UNIT (SN)	SHORTED	380.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	60.00	40.00
			440.00	240.00
	LABOUR			
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO TUFF COAT AFFECTED AREAS.		150.00	60.00
	TO REMOVE & REFIX INTERIOR UPHOLSTERY .		180.00	80.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS.		180.00	120.00
	TO RESPRAY AFFECTED AREAS.		900.00	880.00
	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR & ALIGNED ALL PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL (INNER).		1,000.00	600.00
			2,490.00	1,770.00
GRAND TOTAL			7,541.52	5,755.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,600.00

Report Ref No. CC4/LPC18023267/Uhb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.