

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

14-04-19

Accident Date : 24-12-18

OUR REF : SKX 8292P/T/18

Wayaaauto Trading

Blk 3 Queen's Road

#08-149

Singapore 260003

LPC J Marcus

Date in/out : 26/12/18 to 31/12/18

not allowed
note
46800
527.

ESTIMATE BILL ON VEH. NO. : SKX 8292P

VEH. MODEL : HONDA FREED

CHASSIS NO. : GB31004915

LIST ITEM

Tail Gate		Body/SD 1,460.20
Tail Gate Weather Stripe		tu 120.80
Tail Gate Stopper	2pcs @ 12.40	11 24.80 X
Tail Gate Badge		tu 37.20
Tail Gate Emblem 'Freed'		tu 42.10
Tail Gate Inner Trim Board		11 381.80 X
Tail Gate Inner Lock		SD/SD 198.50
Tail Gate Inner Lock Striker		11 26.70 X
Rear Windscreen Glass Moulding (Side)	2pcs @ 31.30	tu 62.60
Rear Windscreen Glass Inner Seal		tu 48.00
Rear Windscreen Glass Clips	14pcs @ 5.50	11 77.00 X
Rear Bumper Fascia		SD/SD 895.20
Rear Bumper Side Retainer	2pcs @ 28.40	11 56.80 X
Rear Bumper Bracket	2pcs @ 26.10	11 52.20 X
Rear Bnumper Centre Beam		SD 68.50
Rear Bumper Tow Cover		11 32.40 X
Rear Bumper Clips	10pcs @ 5.50	tu 55.00

Rear End Panel (Outer)

20/set 590.00 ✓

Rear End Panel (Inner)

2 381.40 X

Rear End Panel Top Trim

1 set 241.60 ✓

Rear End Panel Top Trim Clips

4pcs @ 5.50 17 22.00 X

Rear Fender Inner Trim Board

2pcs @ 400.80 before 801.60 ✓

Rear Fender Inner Trim Board Clips

16pcs @ 5.50 60 88.00 ✓

4681.30

3745.04

Less Discount 20%:

5,764.40

1,152.88

4,611.52

SPECIAL NETT ITEM

Reverse Sensor with Control Unit

1 set

sketch 200 380.00

Rear Windscreen Glass Sealant

ner 40 60.00

LABOUR CHARGE

To Check Wiring System.

30 80.00

To Tuff Coat Affected Areas.

60 150.00

To Remove & Refix Interior Upholstery.

20 180.00

To Remove & Refix Rear Windscreen Glass.

120 180.00

To Respray Affected Areas.

880 900.00

To Renew Damaged Parts, Straighten & Repair & Aligned All Parts.

600 1,000.00

7,541.52

GST 7%:

527.91

AMOUNT DUE :

8,069.43

5755.04

Like Auto Glass, hence notify the following:
• To view and monitor spray painting
• To check damaged parts during resurvey
• Parts prices are subject to confirmation
• To inspect, survey on a "Without Prejudice" basis
• No cash payment is allowed
• Supply of parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: