

10/2010

INS. CASE OWNER:

CC 4/LPC1802

LKK:

IDAC:

Surveyor:

Adrian

DOE:

ASSIGNMENT

14/1/19

Date / Time:

27/1/19

Registered in Merit:

Pre-assign / CCU / FTE

XD 26944



Insured Vehicle No.

Name of Insured

ROTARY ENGINEERING VN

Insured Tel No.

HP:

27/1/19

Excess See II :SS

D.O.A:

Claim No.

18/1/19/UC00/07260

Policy No.

21/1/19/11054

Make / Model

ISUZU

Place of Accident

LTE AFTER SQUADRON KU

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHARANAM VN

Driver Tel No.:

(VA / YES / NO)

OI GIA REPORT (YES / NO)

YES

TP GIA REPORT (YES / NO)

YES

Insured Liability:

Final ? Yes / No

SDB 2012



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium CARZ



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

16/1/19
27/1/19

SDB 2012 - X

XD 26944 - X

50/5 X

TP VIDEO ; OI DOWN. B15

3-6-19

LOD IN FOR MANDATE

STAGE	DATE / PIC
Non-Reporting Itr (1st):	
Non-Reporting Itr (2nd):	
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	
After call Itr to OI:	
Documentation Check List: Handler Typist	
Notification Itr (if non-pickup)	☒
After call Itr to OI:	☒
Authorisation To Act:	☒
Release Voucher:	☒
Final Repair Bill:	☒
Car Rental Invoice:	☒
Towing Invoice:	☒
LTA / GIA:	☒
Medical Bill:	☒
PIR:	☒
Mandate/Reject Instruction:	☒
LOD:	☒
Payment Breakdown Form:	☐
Post-Repair Photos:	☐
Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	SS	days Reduction:	Email ☐ Call ☐
--------------	----	-----------------	--

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
------------------	------------	---------------	--

Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	If NO or B-28, Ass. Lia:
------------------	---	-----------------------------------	--------------------------

Repair Cost:	SS	4,900	
--------------	----	-------	--

Loss of Rental (LOR):	SS	500	(S 100.5 days)
-----------------------	----	-----	----------------

Loss of Use (LOU):	SS	500	(S 100.5 days)
--------------------	----	-----	----------------

Loss of Income (LOI):	SS		(S x days)
-----------------------	----	--	------------

LOR only	☐	LOU only	☐	LOR + LOU	☐	LOR + LO	☐	[Tick only one]
----------	--------------------------	----------	--------------------------	-----------	--------------------------	----------	--------------------------	-----------------

GIA/LTA Search	SS	7.45	
----------------	----	------	--

Medical:	SS		
----------	----	--	--

Disbursement:	SS		(e.g. Tow/ Independent)
---------------	----	--	-------------------------

Legal Cost	SS		
------------	----	--	--

Total:	SS	5,407.45	Global Sum SS:
--------	----	----------	----------------

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
---------------	------------	---------------	--

Payee 1:	SS	5,407.45	Name 1: PREMIUM CARZ SERVICES PTE LTD
Payee 2: (Strike if N.A.)	SS	X	Name 2: X
Payee 3: (Strike if N.A.)	SS		Name 3: X

COPY SENT 27/1/19 TP VIDEO.

OI COT LANE.

4144006

Date: 14/01/2019

L/\$ 4,900 x x (R \$14,220.60/74%)

MV: 52 $\approx 8 \times 6.5$
PV: 46k
Netfi: 6k.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18023268/Ajb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 28-12-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 3694Y	Veh. Inspected	SDB 301Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/12/2018	Inspection Date	14/01/2019	
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	0188F
Vehicle Details	
Vehicle No.:	SDB301Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E350
Primary Colour:	Grey
Manufacturing Year:	2005
Engine No.:	27296430044467
Chassis No.:	WDB2110562A761782
Maximum Power Output:	200.0 kW (268 bhp)
Open Market Value:	\$67,813.00
Original Registration Date:	14 Jul 2005
First Registration Date:	14 Jul 2005
Transfer Count:	1
Actual ARF Paid:	\$74,595.00
Importation and Exportation Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Importation and COE Details	
COE Expiry Date:	31 May 2025
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$72,136.00
COE Rebate Amount:	\$46,015.00
Total Rebate Amount:	\$46,015.00

The information contained herein is correct as at 14 Jan 2019

OK

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

CERTIFICATE OF INSURANCE

ORIGINAL

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

RECEIVED
01 JAN 2010
BY: _____

Type of Policy: : PRIVATE MOTOR CAR INSURANCE
Type of Cover: : Third Party Fire and Theft
Certificate No.: : D-18089525MVPC
Vehicle No / Chassis No : : SDB301Z / WDB2110562A761782
Name of Insured : : ONG TECK SONG
Period Of Insurance : : 14.01.2018 To 13.01.2019
Insured Estimated Value : : Market Value At Time Of Loss

Excess:

SGD3,500.00 SECTION I & II SEPARATELY IS IMPOSED ON THOSE DRIVERS WHO ARE
BELOW 22 YEARS OLD AND/OR WHO HAVE LESS THAN 2 YEARS OF DRIVING EXPERIENCE

Authorised Driver*
ONG TECK SONG

Persons or classes of persons entitled to drive*

- 1) The Insured.
The Insured may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him or his employer or his partner.
- 2) Any other person who is driving on the Insured's order or with his permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitations as to use*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or reward, racing, pacemaking, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

First Capital Insurance Limited
(Approved Insurers)

ITHMINAH/B0188/MX1F 

Issued at Singapore on 08.01.2018


Authorised Signatory

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8376496A



Name
KHIN THIDA WIN
@MA KHIN THIDA WIN

Race
CHINESE

Date of birth
12-12-1983

Sex
F

Country of birth
MYANMAR




REPUBLIC OF SINGAPORE DRIVING LICENCE



12 Dec 2004
12 Dec 2004

001833961K

4828737



NRIC No S8376496A



Date of issue
14-01-2013

22 LOHONG MELAYU
SINGAPORE 418875

NRIC No: S8376496A Date: 24/08/2018

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 17 Nov 2004

NP 428A

Licence No: S8376496A



Date : 26/12/2018

TO: **Lonpac Insurance Bhd**
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

Our Customer : Ong Teck Song
Vehicle No : SDB301Z
Model : Mercedes Benz E350
Manufacture Year : 2005
Date of Accident : 24/12/2018

Total Estimate Repair Days : 8
Total Pages : 2

Attn : Motor Claims Department
Tel: 6296 3767

Joy

Re: Repair Estimate For Third Party Claim against XD3694Y

No.	Item Descriptions	Qty	Unit Price	Amount	
A.	Spare Parts				
1	Rear bumper <i>change</i>	1	\$1,390.00	\$1,390.00	✓
2	Rear bumper protector w/chrome RH <i>new</i>	1	\$168.00	\$168.00	+
3	Rear bumper side retainer RH <i>new</i>	1	\$39.00	\$39.00	✓
4	Tail lamp RH <i>new</i>	1	\$567.00	\$567.00	+
5	Tail lamp rubber RH <i>new</i>	1	\$25.00	\$25.00	+
6	Rear door RH <i>repair</i>	1	\$2,450.00	\$2,450.00	x
7	Rear door rivet RH <i>new</i>	10	\$10.00	\$100.00	x
8	Rear door weatherstrip RH <i>new</i>	1	\$295.00	\$295.00	+
9	Rear door lower rubber RH <i>new</i>	1	\$158.00	\$158.00	x
10	Rear door black sash pillar sticker RH <i>new</i>	1	\$182.00	\$182.00	x
11	Rear door hinge RH <i>new</i>	2	\$125.00	\$250.00	x
12	Rear door checker RH <i>new</i>	1	\$175.00	\$175.00	x
13	Rear door chanel RH <i>new</i>	1	\$185.00	\$185.00	+
14	Rear door regulator RH <i>new</i>	1	\$600.00	\$600.00	x
15	Rear door regulator motor RH <i>new</i>	1	\$580.00	\$580.00	x
16	Rear door protector w/chrome RH <i>new</i>	1	\$298.00	\$298.00	✓
17	Rear door outer moulding RH (chrome) <i>new</i>	1	\$150.00	\$150.00	x
18	Rear door trimboard RH <i>new</i>	1	\$475.00	\$475.00	+
19	Rear fender RH <i>repair</i>	1	repair	repair	+
20	Side skirt RH <i>repair</i>	1	repair	repair	x
21	Rear knuckle arm RH <i>new</i>	1	\$1,038.00	\$1,038.00	+
22	Rear wheel hub bearing RH <i>new</i>	1	\$398.00	\$398.00	+
23	Side mirror RH <i>new</i>	1	\$1,694.00	\$1,694.00	+
24	Signal lamp, side mirror RH <i>new</i>	1	\$198.00	\$198.00	✓
25	Front door RH <i>dented</i>	1	\$2,009.00	\$2,009.00	✓
26	Front door rivet RH <i>new</i>	10	\$10.00	\$100.00	+
27	Front door lower rubber RH <i>new</i>	1	\$158.00	\$158.00	✓
28	Front door outer handle RH <i>new</i>	1	\$499.00	\$499.00	x
29	Front door regulator RH <i>new</i>	1	\$600.00	\$600.00	+
30	Front door regulator motor RH <i>new</i>	1	\$580.00	\$580.00	+
31	Front door trimboard RH <i>new</i>	1	\$475.00	\$475.00	+
32	Front door protector w/chrome RH <i>new</i>	1	\$298.00	\$298.00	✓
	Sub-Total			\$16,134.00	
	Less 10%			\$1,613.40	

4390
3951

No.	Item Descriptions	Qty	Unit Price	Amount	
Sub-Total 1				\$14,520.60	
B.	Special Nett				
1	Rear tyre RH <i>new</i>	1	\$450.00	\$450.00	+
2	Rear rim RH <i>4</i>	1	\$550.00	\$550.00	✓
3	Rear bumper clip <i>new</i>	10	\$9.00	\$90.00	30
4	Rear door trimboard clip RH <i>3M</i>	10	\$9.00	\$90.00	+
5	Front door trimboard clip RH <i>3M</i>	10	\$9.00	\$90.00	+
Sub-Total 2				\$1,270.00	
Total for Parts				\$15,790.60	
C.	Labour				
1	To check wiring.			\$120.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00	600
3	Spray painting all affected parts & areas.			\$1,400.00	900
4	To remove and refit front door glass RH.			\$100.00	80
5	To remove and refit rear door glass RH.			\$100.00	+
6	To remove and replace rear undercarriage RH.			\$200.00	+
7	To spray anti-rust undercoat.			\$90.00	+
Total Labour				\$3,210.00	
Total Repair Cost				\$17,730.60	

19,120.60

Adrian Lij
4/5 14/01/19.
0.5 days.

total: 6141
4/5: 4.8K. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Yours faithfully,

Acknowledged by Repairer
Signature:
Date:

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 27 December 2018 1:39 PM
To: Admin-D (LKKAuto)
Cc: MT_Claim_SG; Aunteng
Subject: FW: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

Our Ref : 18/18/19/VC00/021260

Dear Catherine/Nivitha,

Kindly proceed as proposed.

For your information, our insured has yet to lodge the report.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Aunteng [mailto:aunteng@premiumcarz.com.sg]
Sent: Thursday, 27 December, 2018 1:19 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

Dear Gerald

We would like to appoint Adrian Ling/Marcus Chua to conduct the pre-repair survey on our client's vehicle.

Regards

Aun Teng

Premium Carz Services Pte Ltd

Tel: 6636 9100 Fax: 6636 9113

1 Kaki Bukit Avenue 6

#01-90 Autobay@Kaki Bukit

Singapore 417883

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: 27 December 2018 12:37:13
To: Aunteng
Cc: MT_Claim_SG
Subject: RE: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

WITHOUT PREJUDICE

Our Ref : 18/18/19/VP05/021260

Dear Aun Teng,

Please see attached and revert.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Aunteng [mailto:aunteng@premiumcarz.com.sg]

Sent: Thursday, 27 December, 2018 12:19 PM

To: MT_Claim_SG

Cc: GERALD POH WEE BIN

Subject: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

Dear Officer-in-charge

We refer to the above matter.

Attached our client's accident report for your perusal.

Your client's vehicle is XD3694Y.

A copy of estimate will be ready and made available to surveyor upon site inspection at our workshop.
Please indicate whether you are sending your surveyor to our workshop.

In the meantime, please provide us a list of surveyor of your choice for our selection.

Regards

Aun Teng

Premium Carz Services Pte Ltd

Tel: 6636 9100 Fax: 6636 9113

1 Kaki Bukit Avenue 6

#01-90 Autobay@Kaki Bukit

Singapore 417883


Shu Pei (LKKAUTO)

From: ONG LI LI <lilong@lonpac.com>
Sent: Tuesday, 15 January 2019 8:52 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: Our Ref: 18/18/19/VC00/021260 RE: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018
Attachments: XD3694Y 241218.PDF

Dear Shu Pei

Please see our Insured's GIA report attached.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 14 January, 2019 6:17 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: RE: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SDB 301Z at M/s Premium Carz Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 27 December 2018 2:08 PM

To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Thursday, 27 December 2018 1:39 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Aunteng <aunteng@premiumcarz.com.sg>

Subject: FW: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018


Our Ref : 18/18/19/VC00/021260

Dear Catherine/Nivitha,

Kindly proceed as proposed.

For your information, our insured has yet to lodge the report.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Aunteng [<mailto:aunteng@premiumcarz.com.sg>]
Sent: Thursday, 27 December, 2018 1:19 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

Dear Gerald

We would like to appoint Adrian Ling/Marcus Chua to conduct the pre-repair survey on our client's vehicle.

Regards

Aun Teng

Premium Carz Services Pte Ltd

Tel: 6636 9100 Fax: 6636 9113

1 Kaki Bukit Avenue 6

#01-90 Autobay@Kaki Bukit

Singapore 417883

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: 27 December 2018 12:37:13
To: Aunteng
Cc: MT_Claim_SG
Subject: RE: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

WITHOUT PREJUDICE

Our Ref : 18/18/19/VP05/021260

Dear Aun Teng,

Please see attached and revert.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Aunteng [<mailto:aunteng@premiumcarz.com.sg>]

Sent: Thursday, 27 December, 2018 12:19 PM

To: MT_Claim_SG

Cc: GERALD POH WEE BIN

Subject: Pre-repair inspection! Accident involving SDB301Z & XD3694Y on 24/12/2018

Dear Officer-in-charge

We refer to the above matter.

Attached our client's accident report for your perusal.

Your client's vehicle is XD3694Y.

A copy of estimate will be ready and made available to surveyor upon site inspection at our workshop. Please indicate whether you are sending your surveyor to our workshop.

In the meantime, please provide us a list of surveyor of your choice for our selection.

Regards

Aun Teng

Premium Carz Services Pte Ltd

Tel: 6636 9100 Fax: 6636 9113

1 Kaki Bukit Avenue 6

#01-90 Autobay@Kaki Bukit

Singapore 417883



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

SATISFACTION VOUCHER

Our ref.: 0357/SOB301Z/TP/PC/1218

To : Longac Insurance BHD

ACCIDENT INVOLVING SOB301Z AND X03694Y ON 24/12/2018
ALONG P1E (CHANGI) TOWARDS CTE

I/We hereby acknowledge having received from Premium Carz Services Pte Ltd, 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883, my/our vehicle number SOB301Z which has been repaired to my/our satisfaction and acceptance. I/We admit that the payment of *SGD _____ account for such repairs is in full discharge of my/our claim.

Dated : 18 day of January 2019

Signature : 

Owners' name: Ong Teck Song

NRIC/Co. Reg.: S1200188F

Address : 72 Long Melagar
Singapore 416975

Date : 14/06/2019

Your Ref.: 18/18/19/VP05/021260

Our Ref.: 0357/SDB301Z/TP/PC/1218

Bill To :

Longpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Our Customer : Ong Teck Song
IC No : S1200188F
Address : 72 Lorong Melayu
Singapore 416975

Vehicle No : SDB301Z
Date of Accident : 24/12/2018
Model : Mercedes Benz E350

Re: Third Party Claim Against XD3694Y

No.	Item Descriptions	Amount
1	FINALIZED SETTLEMENT SUM	
	COR	\$ 4,900.00
	Loss of Use (5 days @ \$100/day)	\$ 500.00
	LTA Search Fee	\$ 7.45
TOTAL AMOUNT DUE		\$ 5,407.45

(Singapore Dollars Five Thousand Four Hundred Seven and Cents Forty Five only)

Yours faithfully



Premium Carz Services Pte Ltd

* All cheque should be crossed and make payable to "Premium Carz Services Pte Ltd"



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18023268/Ajb3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 25-06-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 3694Y	Veh. Inspected	SDB 301Z	
Policy No.	Z/18/VC00/102054	Coverage (\$)	0.00	
Claim No.	18/18/19/VC00/021260	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	27/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E350	c.c	3498	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	WDB2110562A761782	Colour	RED	
Odometer	253617	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	MICHELIN	6 mm	
L/H Front Tyre	225/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	225/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	225/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/12/2018	Inspection Date	14/01/2019	
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDB 301Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,390.00	1,390.00
1	REAR BUMPER PROTECTOR W/CHROME RH	NOT NECESSARY	168.00	-
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	39.00	39.00
1	TAIL LAMP RH	NOT NECESSARY	567.00	-
1	TAIL LAMP RUBBER RH	NOT NECESSARY	25.00	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	2,450.00	-
10	REAR DOOR RIVET RH @\$10.00	NOT NECESSARY	100.00	-
1	REAR DOOR WEATHERSTRIP RH	NOT NECESSARY	295.00	-
1	REAR DOOR LOWER RUBBER RH	NOT NECESSARY	158.00	-
1	REAR DOOR BLACK SASH PILLAR STICKER RH	NOT NECESSARY	182.00	-
2	REAR DOOR HINGE RH @\$125.00	NOT NECESSARY	250.00	-
1	REAR DOOR CHECKER RH	NOT NECESSARY	175.00	-
1	REAR DOOR CHANEL RH	NOT NECESSARY	185.00	-
1	REAR DOOR REGULATOR RH	NOT NECESSARY	600.00	-
1	REAR DOOR REGULATOR MOTOR RH	NOT NECESSARY	580.00	-
1	REAR DOOR PROTECTOR W/CHROME RH	CUT	298.00	298.00
1	REAR DOOR OUTER MOULDING RH (CHROME)	NOT NECESSARY	150.00	-
1	REAR DOOR TRIMBOARD RH	NOT NECESSARY	475.00	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	SIDE SKIRT RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR KNUCKLE ARM RH	NOT NECESSARY	1,038.00	-
1	REAR WHEEL HUB BEARING RH	NOT NECESSARY	398.00	-
1	SIDE MIRROR RH	TO REPAIR SEE LABOUR	1,694.00	-
1	SIGNAL LAMP ,SIDE MIRROR RH	CUT	198.00	198.00
1	FRONT DOOR RH	DENTED	2,009.00	2,009.00
10	FRONT DOOR RIVET RH @\$10.00	NOT NECESSARY	100.00	-
1	FRONT DOOR LOWER RUBBER RH	NECESSARY	158.00	158.00
1	FRONT DOOR OUTER HANDLE RH	NOT NECESSARY	499.00	-

Report Ref No. CC4/LPC18023268/Ajb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR REGULATOR RH	NOT NECESSARY	600.00	-
1	FRONT DOOR REGULATOR MOTOR RH	NOT NECESSARY	580.00	-
1	FRONT DOOR TRIMBOARD RH	NOT NECESSARY	475.00	-
1	FRONT DOOR PROTECTOR W/CHROME RH	CUT	298.00	298.00
	LESS 10% DISCOUNT		-1,613.40	-439.00
			14,520.60	3,951.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TYRE RH (SN)	NOT NECESSARY	450.00	-
1	REAR RIM RH (SN)	CUT	550.00	550.00
10	REAR BUMPER CLIP @\$9.00(SN)	NECESSARY	90.00	30.00
10	REAR DOOR TRIMBOARD CLIP RH @\$9.00 (SN)	NOT NECESSARY	90.00	-
10	FRONT DOOR TRIMBOARD CLIP RH @\$9.00 (SN)	NOT NECESSARY	90.00	-
			1,270.00	580.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		120.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.INCLUSIVE OF THE REPAIR OF REAR DOOR RH,REAR FENDER RH, SIDE SKIRT RH AND SIDE MIRROR RH.		1,200.00	600.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		1,400.00	900.00
	TO REMOVE AND REFIT FRONT DOOR GLASS RH ,		100.00	80.00
	TO REMOVE AND REFIT REAR DOOR GLASS RH.	NOT NECESSARY	100.00	-
	TO REMOVE AND REPLACE REAR UNDERCARRIAGE RH.	NOT NECESSARY	200.00	-
	TO SPRAY ANTI-RUST UNDERCOAT.	NOT NECESSARY	90.00	-
	TO CHECK WHEELS W/COMPUTERISED WHEEL ALIGNMENT.		120.00	80.00
	-		-	-
	-		-	-
	-		-	-
			3,330.00	1,690.00
	GRAND TOTAL		19,120.60	6,221.00

Report Ref No. CC4/LPC18023268/Ajb3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00
---	--	--	--	----------

Report Ref No. CC4/LPC18023268/Ajb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.