

Date : 26/12/2018

TO: Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

Our Customer : Ong Teck Song
Vehicle No : SDB301Z
Model : Mercedes Benz E350
Manufacture Year : 2005
Date of Accident : 24/12/2018
Total Estimate Repair Days : 8
Total Pages : 2

Attn : Motor Claims Department
Tel: 6296 3767

Joy

Re: Repair Estimate For Third Party Claim against XD3694Y

No.	Item Descriptions	Qty	Unit Price	Amount	
A.	Spare Parts				
1	Rear bumper <i>Reborn</i>	1	\$1,390.00	\$1,390.00	✓
2	Rear bumper protector w/chrome RH <i>new</i>	1	\$168.00	\$168.00	+
3	Rear bumper side retainer RH <i>new</i>	1	\$39.00	\$39.00	+
4	Tail lamp RH <i>new</i>	1	\$567.00	\$567.00	+
5	Tail lamp rubber RH <i>new</i>	1	\$25.00	\$25.00	+
6	Rear door RH <i>Reps</i>	1	\$2,450.00	\$2,450.00	x.
7	Rear door rivet RH <i>new</i>	10	\$10.00	\$100.00	x
8	Rear door weatherstrip RH <i>3 new</i>	1	\$295.00	\$295.00	+
9	Rear door lower rubber RH <i>3 new</i>	1	\$158.00	\$158.00	x
10	Rear door black sash pillar sticker RH <i>new</i>	1	\$182.00	\$182.00	+
11	Rear door hinge RH <i>2</i>	2	\$125.00	\$250.00	x
12	Rear door checker RH <i>1 new</i>	1	\$175.00	\$175.00	+
13	Rear door chanel RH <i>1 new</i>	1	\$185.00	\$185.00	+
14	Rear door regulator RH <i>1 new</i>	1	\$600.00	\$600.00	+
15	Rear door regulator motor RH <i>1 new</i>	1	\$580.00	\$580.00	+
16	Rear door protector w/chrome RH <i>new</i>	1	\$298.00	\$298.00	✓
17	Rear door outer moulding RH (chrome) <i>new</i>	1	\$150.00	\$150.00	x.
18	Rear door trimboard RH <i>new</i>	1	\$475.00	\$475.00	+
19	Rear fender RH <i>3 Reps</i>	1	repair	repair	+
20	Side skirt RH <i>3 Reps</i>	1	repair	repair	x
21	Rear knuckle arm RH <i>3 new</i>	1	\$1,038.00	\$1,038.00	+
22	Rear wheel hub bearing RH <i>3 new</i>	1	\$398.00	\$398.00	+
23	Side mirror RH <i>new Reps</i>	1	\$1,694.00	\$1,694.00	+
24	Signal lamp, side mirror RH <i>new</i>	1	\$198.00	\$198.00	✓
25	Front door RH <i>Dented</i>	1	\$2,009.00	\$2,009.00	✓
26	Front door rivet RH <i>new</i>	10	\$10.00	\$100.00	+
27	Front door lower rubber RH <i>new</i>	1	\$158.00	\$158.00	✓
28	Front door outer handle RH <i>new</i>	1	\$499.00	\$499.00	x
29	Front door regulator RH <i>3 new</i>	1	\$600.00	\$600.00	+
30	Front door regulator motor RH <i>3 new</i>	1	\$580.00	\$580.00	+
31	Front door trimboard RH <i>new</i>	1	\$475.00	\$475.00	+
32	Front door protector w/chrome RH <i>new</i>	1	\$298.00	\$298.00	✓
	Sub-Total			\$16,134.00	
	Less 10%			\$1,613.40	

4390
3951

No.	Item Descriptions	Qty	Unit Price	Amount	
Sub-Total 1				\$14,520.60	
B.	Special Nett				
1	Rear tyre RH <i>new</i>	1	\$450.00	\$450.00	+
2	Rear rim RH <i>lt</i>	1	\$550.00	\$550.00	✓
3	Rear bumper clip <i>new</i>	10	\$9.00	\$90.00 <i>580</i>	<i>30</i>
4	Rear door trimboard clip RH <i>3M</i>	10	\$9.00	\$90.00	+
5	Front door trimboard clip RH <i>3M</i>	10	\$9.00	\$90.00	+
Sub-Total 2				\$1,270.00	
Total for Parts				\$15,790.60	
C.	Labour				
1	To check wiring.			\$120.00 <i>30</i>	
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00 <i>600</i>	
3	Spray painting all affected parts & areas.			\$1,400.00 <i>900</i>	
4	To remove and refit front door glass RH.			\$100.00 <i>80</i>	
5	To remove and refit rear door glass RH.			\$100.00	+
6	To remove and replace rear undercarriage RH.			\$200.00	+
7	To spray anti-rust undercoat.			\$90.00	+
<i>To check wheels w/ computerized wheel alignment. \$120</i>				Total Labour	
				\$3,210.00	
Total Repair Cost				\$17,730.60	

flg.

Adrian Lij
4/s 14/01/19.
05 days.

total: 6141
4/s: 4-9K. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Yours faithfully,

Acknowledged by Repairer
Signature:
Date:

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No