

ASS. REC. BY:

REF:

CS/GA18023279/Kad3et

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Kelyna Ngün

of

GAI

Date/Time

28/12/18

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.

SHC5902D

Insured:

PC761G

at Workshop m/s

Transcab

Tel:

6287 6666

of

No. 2 Amk st. 63

Policy No:

Claim No:

MOMVCO0000627301

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/12/18

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

11:30am 28/12/18

Person Contacted:

Amenda

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC5902D-CC3/AIG/14003899/Kv/b3q.2
	PC761G-NBA/LIP140127574
31/12/18 Call	was revised to Kelyna by email.

JWA: 28/12/18

JWA: 5/07/14

ASS. REC. BY:

REF:

GAZ/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

11 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

31/12

File path to Carhome

61 Reg 813, 750L (Red 637169.41, 73%)

Date/Time, File Pass to?

11/11/11

Date/Time, File Return to?

21

Report Format :

Lump Sum / I.B.I. (\$) TP

13750

Days Of Repair: 11

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech Invs (\$)  
☐ : Weekend (\$)  
☐ :

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

450

450

Veh No:

SHC5902D

Yr Regn:

12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c.

1985

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

680334

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC - 280977

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

26/12/18

D.O.I.

28/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

**Nivitha (LKK Auto)**

---

**From:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Sent:** Friday, 28 December 2018 11:31 AM  
**To:** SUR; Admin-D (LKKAuto); 'Admin A'  
**Subject:** GA: PC761G ARRANGE FOR SURVEY SHC5902D  
**Attachments:** SHC5902D.pdf

Hi team

TP survey please

Thanks  
Kelvyna

-----Original Message-----

From: Amanda Tay <amanda.tay@transcab.com.sg>  
Sent: Friday, December 28, 2018 11:01 AM  
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>  
Cc: zhewei.kek@transcab.com.sg; Motor Claims <MotorClaims@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
Subject: [External] ARRANGE FOR SURVEY SHC5902D

Dear all ,

Please arrange for survey as below :

PC761G - 26.12.2018 at 1440Hrs - SHC5902D

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs  
Amanda Tay  
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

This email has been checked for viruses by AVG.

[https://urldefense.proofpoint.com/v2/url?u=https-3A\\_\\_www.avg.com&d=DwlCAg&c=tbYyL\\_Dr1tbrHXGUavt\\_ityX6BKXh9yO5QMbpNi15jsc&r=fe\\_EbyO8s3DH2MABscLP7xEnM93QFaf4qlkP1QK4PII&m=pyJLgjJKRlxvGVVw0iHyhrBNmTaHNsYr2qeDtKved44&s=olPLe6xEfGJ5D\\_CbMVO7OSZQ5FDAXnLEwJgrJjlw4P8&e=](https://urldefense.proofpoint.com/v2/url?u=https-3A__www.avg.com&d=DwlCAg&c=tbYyL_Dr1tbrHXGUavt_ityX6BKXh9yO5QMbpNi15jsc&r=fe_EbyO8s3DH2MABscLP7xEnM93QFaf4qlkP1QK4PII&m=pyJLgjJKRlxvGVVw0iHyhrBNmTaHNsYr2qeDtKved44&s=olPLe6xEfGJ5D_CbMVO7OSZQ5FDAXnLEwJgrJjlw4P8&e=)

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

## Shiau Chan (LKKAUTO)

---

**From:** Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Sent:** Friday, 4 January 2019 4:37 PM  
**To:** Shiau Chan (LKKAUTO); assignments  
**Cc:** SUR  
**Subject:** MOMVC00000622301 : PC761G ARRANGE FOR SURVEY SHC5902D

-----Original Message-----

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>  
Sent: Friday, January 04, 2019 11:26 AM  
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: [External] RE: PC761G ARRANGE FOR SURVEY SHC5902D

Dear Kelvyna,

Kindly provide us the claims number of above mentioned.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shiau Chan (LKKAUTO)  
Sent: Monday, 31 December 2018 11:15 AM  
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: RE: PC761G ARRANGE FOR SURVEY SHC5902D

Dear Kelvyna,

Enclosed herewith preliminary advice of SHC 5902D.

Kindly provide us the claim number of above mentioned.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)  
Sent: Friday, 28 December 2018 11:36 AM  
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; assignments <assignments@lkkauto.com>  
Cc: SUR <sur@lkkauto.com>  
Subject: RE: PC761G ARRANGE FOR SURVEY SHC5902D

Dear Sir/Mdm,

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 31 December 2018 11:15 AM  
**To:** 'Ngian, Kelvyna'; assignments  
**Cc:** SUR  
**Subject:** RE: PC761G ARRANGE FOR SURVEY SHC5902D  
**Attachments:** CSGAI18023279Kqd3.pdf

Dear Kelvyna,

Enclosed herewith preliminary advice of SHC 5902D.

Kindly provide us the claim number of above mentioned.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)  
Sent: Friday, 28 December 2018 11:36 AM  
To: 'Ngian, Kelvyna' <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
Cc: SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
Subject: RE: PC761G ARRANGE FOR SURVEY SHC5902D

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,  
G.Nivitha | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]  
Sent: Friday, 28 December 2018 11:31 AM  
To: SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
Subject: GA: PC761G ARRANGE FOR SURVEY SHC5902D

Hi team

TP survey please



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: PC761G

Date: 31<sup>st</sup> December 2018

Our Ref: CS/GAI18023279/Kqd3

The Motor Claims Department  
Great American Insurance Company

Attn: Kelvyna

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SHC 5902D**


We thank you for the instruction on 28/12/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/12/2018 at the premises of M/s TRANSCAB and have the following to report:-

Workshop Estimate Amount	: S\$ <u>50,919.41</u>
Revised Estimate Amount	: S\$ <u>17,184.82</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages consistent.

Recommend repair days: 11 days

We have NOT authorise repair.

Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5902D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Dec 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002289
Chassis No.:	VF1ABL15AUC280977
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$25,644.00
Total Rebate Amount:	\$35,017.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/12/2018 10:59
Date Of Accident	26/12/2018 14:40
Exact Location Of Accident	BUKIT TIMAH ROAD TOWARDS UPPER BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5902D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	SOO MOON KHAN
NRIC No	S0773074H
Date Of Birth	22/02/1951
Occupation	OUTDOOR
Date Of Driving Pass	17/04/1979
Driving Experience	39 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96490097
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 850 YISHUN STREET 81 #10-104
Postcode	760850
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please see the attach Police Report T/20181227/2020.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC761G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	VISHNU S/O AMURTHALINGAM

NRIC/Passport Number	S8309350A
Contact Number	87160557
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1	
-----------------------------	--

Name	SOO MOON KHAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHC5902D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN

A: SHC 5902D  
B: PC 761G

Bukit Timah Road  
towards Upper Bukit  
Timah Road

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Amanda  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Police Report Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20181227/2020

1 of 3

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

Report No. T/20181227/2020

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/12/2018 10:45	Vide Report No.:	Station Diary No.: 19
--	------------------	--------------------------

Informant's Particulars				
Name of Informant: SOO MOON KHAN			Address: APT BLK 850 YISHUN STREET 81 #10-104 SINGAPORE 760850	
ID Type / ID No.: NRIC NO / S0773074H			Contact No.: Home/Office: Mobile: 96490097	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 67	Date of Birth: 22/02/1951	Type of Informant: Driver	
Race: Chinese			Language: Chinese	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/12/2018 14:40	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 BUKIT TIMAH ROAD UPPER BUKIT TIMAH ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: MOVING VEHICLE AGAINST STATIONARY VEHICLE				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC761G	Van					4
SHC5902D	Car				Slightly Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20181227/2020

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

2 of 3

Report No. T/20181227/2020

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	VISHNU S/O AMURTHALINGAM		ID No. S8309350A
Related Vehicle	PC761G (Van)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	SOO MOON KHAN		ID No. S0773074H
Related Vehicle	SHC5902D (Car)		Contact No. 96490097
Hospital/Clinic	SIN MING CLINIC		Class of Driving Licence & Expiry Date Class: 2,3 Date of Expiry: NIL
Date Treatment	27/12/2018	Date Discharge	27/12/2018
No. of Days granted Medical Leave	07	Degree of Injury	Slight

**Brief Details.**

On 26/12/2018 at about 1440hrs, I was driving my taxi SHC5902D along Bukit Timah Rd towards Upper Bukit Timah Rd with 2 passengers inside the taxi along the center lane. As I was approaching a traffic light, it was red and there were several vehicles in front of me. Therefore, I put my gear in neutral and pulled my handbrake. While waiting for the traffic light to turn green, I was hit suddenly by a vehicle from behind. I checked my mirror and saw that I was hit on the rear on the left side by a van. I made a check with my passengers if they were injured and they were not injured.

When I alighted the taxi, I spoke to the van driver and agreed to settle the matter through insurance. We exchanged particulars and took photos of the accident and left. Traffic Police officers came to scene and told us to shift to the road shoulder since there was no injuries. Subsequently I left the scene.

On 27/12/2018, I woke up and felt pain at the back of my neck and back so I went to a clinic and was given 7 days of medical leave by the doctor.

I am lodging this report for insurance claims.



**SINGAPORE  
POLICE FORCE**



T/20181227/2020

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

3 of 3



Report No. T/20181227/2020

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sr Staff Sgt NEO ZE HWEE, EDMUND	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 27/12/2018 10:45
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE-SYED MOHD SAID Contact No. 65476172 Authentication Stamp NP168  Singapore Police Force	Classification Of Case:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5902D****AAD1812-217***Not Notarized*  
*1/1 Smp @ 13,750/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHC 5902D**

VF1ABL15AUC280977

RENAULT

LATITUDE

26.12.2018

**GREAT AMERICAN**

18/12/2014

**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Tn</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Dis/Re</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>SL Br</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>CM</i> 135.97 ✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>CM</i> 44.99 ✓
9	1 BUMPER REFLECTOR LH	\$	<i>Br</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$	<i>Bz</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 BOOT REAR	\$	<i>Bz</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>Dis</i> 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35 ✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Re</i> 225.36 ✓
19	1 BOOT BADGE	\$	<i>Re</i> 225.36 ✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81

**Trans-cab Auto Services Pte Ltd**

AAD1812-217

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5902D**

30	1 FENDER PANEL REAR LH	\$	B <sub>1</sub> 3,299.13 ✓
31	1 WHEELARCH REAR LH	\$	S <sub>2</sub> 543.47 X
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Return 671.45 ✓
33	1 WHEEL HOUSING PANEL REAR LH	\$	R 4,682.09 X
34	1 FUEL FLAP	\$	S <sub>2</sub> 343.57 X
35	1 TAILLAMP LH	\$	B <sub>2</sub> 552.55 ✓
36	1 TAILLAMP PANEL LH	\$	B <sub>1</sub> 986.70 ✓
37	1 TAILLAMP RH	\$	S <sub>2</sub> 552.55 X
38	1 TAILLAMP PANEL RH	\$	R 986.70 X
39	1 OUTER PANEL REAR (End Panel)	\$	B <sub>1</sub> 1,471.77 ✓
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	Am CM 404.56 ✓
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88 X
42	1 SPARE WHEEL PANEL TRIM	\$	S <sub>2</sub> 612.21 X
43	1 KUCKLE ARM REAR LH L70Y	\$	S <sub>2</sub> 736.67 X
44	1 BRAKE DISC REAR L70Y	\$	S <sub>2</sub> 525.91 X
45	1 WHEEL HUB NUT L70Y	\$	S <sub>2</sub> 51.11 X
46	1 WHEEL HUB CAP L70Y	\$	S <sub>2</sub> 57.82 X
47	1 ABS SENSOR REAR LH L70Y	\$	S <sub>2</sub> 375.93 X
48	1 REAR AXLE L70Y	\$	S <sub>2</sub> 4,167.03 X
49	1 LOWER ARM REAR LH L70Y	\$	S <sub>2</sub> 905.99 X
50	2 LOWER ARM BALANCER REAR LH L70Y	\$	S <sub>2</sub> 34.14 X
51	1 LOWER ARM REAR RH L70Y	\$	S <sub>2</sub> 905.99 X
52	2 ABSORBER REAR	\$	S <sub>2</sub> 389.75 X
53	1 STABILIZER BAR REAR L70Y	\$	S <sub>2</sub> 604.65 X

<b>TOTAL</b>	<b>\$</b>	<b>37,415.99</b>
<b>10%</b>	<b>\$</b>	<b>3,741.60</b>
	<b>\$</b>	<b>33,674.39</b>

**Specical Nett**

1	1SET PARKING AID	\$	T <sub>2</sub> 700.00 600.00
2	1SET REAR BUMPER CLIP	\$	R <sub>2</sub> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	R <sub>2</sub> 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	R <sub>2</sub> 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	R <sub>2</sub> 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	R <sub>2</sub> 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	R <sub>2</sub> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	R <sub>2</sub> 22.00 X

**Trans-cab Auto Services Pte Ltd****AAD1812-217**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5902D**

9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
11 1SET BOOT FINISHER CLIP	\$	nn	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	nn	30.00	✓
13 1 BOOT STICKER "6555-3333"	\$	nn	30.00	✓
14 1 BOOT INNER TRIM CLIP	\$	nn	45.00	X
15 1 LEFT REAR TYRE	\$	nn	300.00	24052
16 1 LEFT REAR TYRE RIM	\$	nn	380.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19 1 TAILLAMP CLIP RH	\$	nn	5.00	X
20 1 TAILLAMP CLIP LH	\$	nn	5.00	✓
21 2 REAR WINDSCREEN SELANT	\$	nn	80.00	4052
22 1 WINDSCREEN MOULDING	\$	nn	100.00	✓
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	3052
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	X
25 1 SPARE TYRE	\$	nn	330.00	X

**TOTAL \$ 2,905.02****TOTAL PARTS \$ 36,579.41****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	1100/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	1200/
To Rust-Proofing Of The Affected Areas.	\$	170.00	90/
To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60/

**Trans-cab Auto Services Pte Ltd****AAD1812-217**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5902D**

To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1000
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1200
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	~ 380.00	X
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	~ 380.00	X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 2500

**TOTAL \$ 14,340.00** 15860

**Over All Total \$ 50,919.41**

**(LUMP SUM) Repair Days 20 DAYS**

Acknowledged by Repairer  
Signature:  
Date:

11 days 52439.41

- Under the following conditions:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18023279/Kqd3e2

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Date : 15-01-2019



Code : GAI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 761G	Veh. Inspected	SHC 5902D
Policy No.		Coverage (\$)	0.00
Claim No.	MOMVC00000622301	Excess (\$)	0.00
Assign From	KELVYNA NGIAN	Assign Date	28/12/2018

## 2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC280977	Colour	METALLIC WHITE / RED
Odometer	680334	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	26/12/2018	Inspection Date	28/12/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5902D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER REAR	TORN	1,108.46	1,108.46
1	BUMPER LOWER REAR	DISTORTED / DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	CRACKED	135.97	135.97
1	BUMPER RETAINER LH REAR	CRACKED	44.99	44.99
1	BUMPER REFLECTOR LH	BROKEN	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	DISTORTED	323.05	323.05
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CS/GAI18023279/Kqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR LH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR LH	DEFORMED	671.45	671.45
1	WHEEL HOUSING PANEL REAR LH	TO REPAIR SEE LABOUR	4,682.09	-
1	FUEL FLAP	SERVICEABLE	343.57	-
1	TAILLAMP LH	BROKEN	552.55	552.55
1	TAILLAMP PANEL LH	BENT	986.70	986.70
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	KUCKLE ARM REAR LH L70Y	SERVICEABLE	736.67	-
1	BRAKE DISC REAR L70Y	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y	SERVICEABLE	51.11	-
1	WHEEL HUB CAP L70Y	SERVICEABLE	57.82	-
1	ABS SENSOR REAR LH L70Y	SERVICEABLE	375.93	-
1	REAR AXLE L70Y	SERVICEABLE	4,167.03	-
1	LOWER ARM REAR LH L70Y	SERVICEABLE	905.99	-
2	LOWER ARM BALANCER REAR LH L70Y	SERVICEABLE	34.14	-
1	LOWER ARM REAR RH L70Y	SERVICEABLE	905.99	-
2	ABSORBER REAR	SERVICEABLE	389.75	-
1	STABILIZER BAR REAR L70Y	SERVICEABLE	604.65	-
	LESS 10% DISCOUNT		-3,741.60	-1,440.54
			33,674.38	12,964.81

Report Ref No. CS/GAI18023279/Kqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	TORN	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	LEFT REAR TYRE (SN) (80%)	CUT	300.00	240.00
1	LEFT REAR TYRE RIM (SN)	SERVICEABLE	380.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SELANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,905.02	1,240.00
	<b><u>LABOUR</u></b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,100.00

Report Ref No. CS/GAI18023279/Kqd3e2

Report Ref No. CS/GAI18023279/Kqd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,750.00
---	--	--	-----------

Report Ref No. CS/GAI18023279/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.