

23/03/2011

ASS. REC. BY:

REP

03/AIG/18023281 / Ng03⁵⁴

Special Instruction:

Surveyor of
Mainman

Nq2

From (Person):

Chinlee Ying

ASSIGNMENT (Office)

of

AIG

Date/Time:

28/12/18 @ 11:53am

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBJ 9706L

Insured:

at Workshop m/s:

Bike Production
610 Serangoon Road

Tel:

6299 5177

of

Policy No: 21044 6860-61000

Claim No:

131507635556

Excess:

TBA

D.O.A. 23/12/2018

Sum Insured:

Make of Veh:

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

Date/Time: 1pm @ 28/12/18

Person Contacted:

wendy

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBJ 9706L - X
31/12/18 @ 12.17pm	Informed wendy c/A 8 EX: TBA by email.
04/1/19 @ 2.41pm	Informed w/sgp EX: \$300 by email.
15/1/19 @ 8.42am	Tong Shing informed excess should be \$1300. thru email.
15/1/19 @ 8.52am	Informed mr Ewan excess should be \$1300 instead of \$300 by email.
30/4/19	WKSHIP withdraw OD claim, claiming from TP.

PRO-1

NAZ

REF:

AIG

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 28K

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: FBT 9706L Yt Regn: 20 JAN 2015

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW R 1200 GS c.c. 1,170

Colour: BLUE A/C: Insured / Std / NI / ☒ NA

Sp. Reading: 31,184 T/Radio: Insured / Std / NI / ☒ NA

Eng/No:

C/No: WBI0A020XF254342

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 120/70 R19

R: 170/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or METZELER

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. - mm L/Bal. - mm

D.O.A. 23/12/18 D.O.I. 28/12/18

Survey held at BIKE PRODUCTION

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 28K
COR Rebate \$2,664.00 (Margin for repair \$20K)

RECEIVED 30 APR 2017

Date/Time, File Pass to?

☒ Preli. Report

1) 30/4/18

☐ Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

- OWN DAMAGE CLAIM FBJ9706L

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 28/12/2018 11:53:35 AM
Attachments:  FBJ9706L 231218 AIG OD OWS.PDF  20181228_114114.jpg

Hi LKK,

Kindly assist to survey, bike in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

-----Original Message-----

From: Sbk E [mailto:sbk5643e@yahoo.com]
Sent: Friday, December 28, 2018 11:47 AM
To: AIG SGP, Claims-Survey
Subject: Fw: RE: OWN DAMAGE CLAIM FBJ9706L

Resent with correct vehicle number: FBJ9706L

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

--- On Fri, 12/28/18, Sbk E <sbk5643e@yahoo.com> wrote:

> From: Sbk E <sbk5643e@yahoo.com>
> Subject: RE: OWN DAMAGE CLAIM FS787S
> To: AIGSGP_ClaimsSurvey@aig.com
> Date: Friday, December 28, 2018, 11:46 AM Dear Sir,
>
> Good Day. Please refer to the attached file. Please contact us at
> 62995177 for pre-repair inspection appointment. Thank you very much
> for your attention.
>
> Regards,
>
> Kwan S. H.
> Director
> Bike Production Pte Ltd

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no respon

sibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

WITHDRAWAL OF OD CLAIM, RE: RE: OWN DAMAGE CLAIM FBJ9706L

Sbk E <sbk5643e@yahoo.com>

Sat 27/4/2019 9:33 AM

To: Claims-SurveyAIG SGP <AIGSGP_ClaimsSurvey@aig.com>;

Cc: Naz (LKKAuto) <Naz@lkkauto.com>;

Dear Sir,

We will withdraw this OD claim as we has successfully claimed from TP Insurer. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Fri, 12/28/18, AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com> wrote:

Subject: RE: RE: OWN DAMAGE CLAIM FBJ9706L
To: "Sbk E" <sbk5643e@yahoo.com>
Date: Friday, December 28, 2018, 11:52 AM

Hi Mr. Kwan,

We'll appoint LKK to survey this case.

Thanks.

AIG
Claims Survey

-----Original Message-----

From: Sbk E [<mailto:sbk5643e@yahoo.com>]

Sent: Friday, December 28, 2018 11:47 AM
To: AIG SGP, Claims-Survey
Subject: Fw: RE: OWN DAMAGE CLAIM FBJ9706L

Resent with correct vehicle
number: FBJ9706L

Regards,

Kwan
S. H.
Director
Bike
Production Pte Ltd

--- On Fri, 12/28/18, Sbk E <sbk5643e@yahoo.com>
wrote:

> From: Sbk E
> <sbk5643e@yahoo.com>
> Subject: RE: OWN DAMAGE CLAIM FS787S
> To: AIGSGP_ClaimsSurvey@aig.com
> Date: Friday, December 28, 2018, 11:46 AM

Dear Sir,

>

> Good

Day. Please refer to the attached file. Please contact us at

> 62995177 for pre-repair inspection
appointment. Thank you very much

> for

your attention.

>

>

Regards,

>

> Kwan S.

H.

> Director

> Bike

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 15 January 2019 8:57 AM
To: Sbk E
Cc: SUR
Subject: RE: MOTORBIKE FBJ 9706L (DOA: 23/12/2018)

Dear Mr Kwan,

Please be informed that the excess of FBJ 9706L should be \$1,300.00 instead of \$300.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sbk E <sbk5643e@yahoo.com>

Sent: Wednesday, 9 January 2019 12:31 AM

To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: MOTORBIKE FBJ 9706L (DOA: 23/12/2018)

Dear Shiau Chan,

Please kindly confirm excess is \$300?

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Fri, 1/4/19, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Subject: RE: MOTORBIKE FBJ 9706L (DOA: 23/12/2018)

To: "sbk5643e@yahoo.com" <sbk5643e@yahoo.com>

Cc: "SUR" <sur@lkkauto.com>

Date: Friday, January 4, 2019, 2:41 PM

#yiv2358378649

#yiv2358378649 --

_filtered #yiv2358378649 {panose-1:2 4 5 3 5 4 6 3 2 4;}

_filtered #yiv2358378649 {font-family:DengXian;panose-1:2 1 6 0 3 1 1 1 1 1;}

_filtered #yiv2358378649 {font-family:Calibri;panose-1:2 15 5 2 2 4 3 2 4;}

_filtered #yiv2358378649 {font-family:Verdana;panose-1:2 11 6 4 3 5 4 4 2 4;}

_filtered #yiv2358378649 {panose-1:2 1 6 0 3 1 1 1 1 1;}

Shiau Chan (LKKAUTO)

From: Loo, Tong Shing <TongShing.Loo@aig.com>
Sent: Tuesday, 15 January 2019 8:42 AM
To: Shiau Chan (LKKAUTO)
Cc: SUR
Subject: RE: FBJ9706L / OD / 23/12/2018 / Coverage & Excess update

Hi,

Apologies for that.

Correct excess should be \$1300.00.

Appreciate if you could inform repairer about it.

Thank you.

Loo Tong Shing
AIG

Express Claims Adjuster
Claims Operations | AIG Shared Services

TongShing.Loo@aig.com | www.aig.com

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, January 14, 2019 5:53 PM
To: Loo, Tong Shing
Cc: SUR
Subject: RE: FBJ9706L / OD / 23/12/2018 / Coverage & Excess update

Dear Tong Shing,

Kindly confirm the excess is \$300.00?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 9 January 2019 9:00 AM
To: TongShing.Loo@aig.com
Cc: SUR <sur@lkkauto.com>
Subject: Re: FBJ9706L / OD / 23/12/2018 / Coverage & Excess update

This mail is associated with :

***FBJ9706L (1315076355SG)**

OD

Dec 23 2018 2:30PM

[TEO CHOON MING]

Bike Production Pte Ltd

Dear Tong Shing,

Kindly confirm the excess is \$300.00?

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 02/01/2019 11:13 AM

Subject: FBJ9706L / OD / 23/12/2018 / Coverage & Excess update


Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$300.00

Thank you
Loo, Tong Shing

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 4 January 2019 2:41 PM
To: sbk5643e@yahoo.com
Cc: SUR
Subject: RE: MOTORBIKE FBJ 9706L (DOA: 23/12/2018)

Dear Sir/Madam,

Please be informed that the excess of FBJ 9706L is \$300.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Monday, 31 December 2018 12:19 PM
To: sbk5643e@yahoo.com
Cc: SUR <sur@lkkauto.com>
Subject: MOTORBIKE FBJ 9706L (DOA: 23/12/2018)

Dear Sir/Madam,

As spoken with Wendy.

Please proceed to repair the insured motorbike **FBJ 9706L (Excess TBA)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 31 December 2018 12:19 PM
To: sbk5643e@yahoo.com
Cc: SUR
Subject: MOTORBIKE FBJ 9706L (DOA: 23/12/2018)

Dear Sir/Madam,

As spoken with Wendy.

Please proceed to repair the insured motorbike **FBJ 9706L (Excess TBA)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2018 12:39
Date Of Accident	23/12/2018 14:30
Exact Location Of Accident	CAUSEWAY AFTER MALAYSIA TOWARDS TO SINGAPORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ9706L
Insured/Policyholder	
Name Of Registered Owner	TEO CHOON MING
NRIC No	S7618470D
Email Address	THOMASTEOCM@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97777731
Alternative Phone No	OFFICE-97777731

Vehicle Particulars

Manufacturer	BMW
Model	R1200 GSA-1.2

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100446860-01000
Cover Note Number	

Driver

Name of Driver	TEO CHOON MING
NRIC No	S7618470D
Date Of Birth	22/06/1976
Occupation	INDOOR
Date Of Driving Pass	03/05/2013
Driving Experience	5 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97777731
Fax Number	
Contact Number	OFFICE-97777731
Email Address	THOMASTEOCM@YAHOO.COM

Address

BLK 413 HOUGANG AVENUE 10 #02-1216

Postcode

530413

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBL6455U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver LEE POOI LING

NRIC/Passport Number S7960367H

Contact Number 96308957

Address

Postcode

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number FR826T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2018 12:39
Date Of Accident	23/12/2018 14:30
Exact Location Of Accident	CAUSEWAY AFTER MALAYSIA TOWARDS TO SINGAPORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ9706L
Insured/Policyholder	
Name Of Registered Owner	TEO CHOON MING
NRIC No	S7618470D
Email Address	THOMASTEOCM@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97777731
Alternative Phone No	OFFICE-97777731

Vehicle Particulars

Manufacturer	BMW
Model	R1200 GSA-1.2

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

YES / OD

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100446860-01000
Cover Note Number	

Driver


Name of Driver	TEO CHOON MING
NRIC No	S7618470D
Date Of Birth	22/06/1976
Occupation	INDOOR
Date Of Driving Pass	03/05/2013
Driving Experience	5 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97777731
Fax Number	
Contact Number	OFFICE-97777731
Email Address	THOMASTEOCM@YAHOO.COM



Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

MOTORCYCLE

SKETCH PLAN SINGAPORE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was riding back from Malaysia. After passing Malaysia custom, and heading back via the Causeway to Singapore, the accident happened on the Causeway ~~that~~ towards Singapore.

The motor bike in front of me, FR826T, stopped suddenly in front of me, when he noted that he dropped something on the road.

I have stopped in time to prevent collision to him, but the bike behind me did not stop in time.

The bike behind, FB6455U rode by Ms Lee Poo Ling NRIC number 37960367H, collided with me from behind and cause me to fall on the right side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

24/12/18 11:30.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	8470D

Vehicle No.:	FBJ9706L
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	R1200GS
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	122EN38140268
Chassis No.:	WB10A010XFZ154342
Maximum Power Output:	-
Open Market Value:	\$19,645.00
Original Registration Date:	20 Jan 2015
First Registration Date:	20 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$2,947.00

Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,403.00
COE Rebate Amount:	\$2,664.00
Total Rebate Amount:	\$2,664.00

The information contained herein is correct as at 31 Dec 2018

OK

Enquire Transfer Fee

Vehicle No.: FBJ9706L
 Vehicle Type: P00 - Passenger Motorcycle/Autocycle/Moped
 Vehicle Attachment 1: No Attachment
 Vehicle Scheme: Normal
 Vehicle Make: B.M.W.
 Vehicle Model: R1200GS
 Chassis No.: WB10A010XFZ154342
 Propellant: Petrol
 Engine No.: 122EN38140268
 Engine Capacity: 1170 cc
 Maximum Power Output: -
 Maximum Laden Weight: 450 kg
 Unladen Weight: 238 kg
 Year Of Manufacture: 2014
 Original Registration Date: 20 Jan 2015
 Lifespan Expiry Date: -
 COE Category: D - Motorcycle
 Quota Premium: \$4,403.00
 COE Expiry Date: 19 Jan 2025
 Road Tax Expiry Date: 19 Jan 2019
 Inspection Due Date: 19 Jan 2020
 Intended Transfer Date: 31 Dec 2018
 CO2 Emission: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -

The current road tax expiry is 19 Jan 2019. You may renew the road tax from 20 Oct 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 19 Jan 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.
 Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:		-	166.00
Nett Road Tax Amount (After Offsetting Over Payment):	166.00		191.00
Total Amount Payable:			

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:		-	332.00
Nett Road Tax Amount (After Offsetting Over Payment):	332.00		357.00
Total Amount Payable:			

You may print this page for reference.

OK

Print

Bike model
BMW R1200GS

Type
Any

Price From
Any

Price To
Any

Class
2

MORE SEARCH OPTIONS

SEARCH

VIEW ALL

SEARCH

BMW R1200GS Adventure



Posted on : 31/12/2018

SGD **\$39800**

Reg : 15/07/2015

Type: **Sport Tourers**

1170cc

23000km

Well taken care by previous owner. Please visit the bike at I Motoring showroom location at Block 1008 Bukit Merah Lane 3 #01-14 Singapore 159722.

PAID AD

DEALER AD

COMPARE

DETAILS

BMW R1200GS Adventure



Downpayment \$500 or Zero Down.
Posted on : 30/12/2018

SGD **\$43500**

Reg : 08/07/2015

Type: **Sport Tourers**

1170cc

Downpayment \$500 or \$0 Without insurance (Terms and conditions apply). Please call 67468582 De Xing Motor Pte Ltd Block 3006 Ubi Road 1 #01-356 S 408700.

[PAID AD](#)[DEALER AD](#)[COMPARE](#)[DETAILS](#)

BMW R1200GS Adventure



SGD **\$34000**

Reg : 29/09/2015

Type: **Sport Tourers**

1170cc

42000km

Pristine conditions with no accidents. Keyless activation. If interested do text me.

Posted on : 12/12/2018

[PAID AD](#)[DIRECT SELLER](#)[COMPARE](#)[DETAILS](#)

BMW R1200GS



SGD **\$31800**

Reg : 17/04/2015

Type: **Sport Tourers**

1170cc

15000km

Underutilized BMW R1200GS Glossy black storm metallic color with genuine low mileages of 15,000km only. Excellent condition and accident free. Dynamic ESA,

ASC, ABS, 4 Riding Modes, LED Headlight &...
Loan And Trade In Available With Attractive Rate.
Posted on : 19/12/2018

[PAID AD](#)[DEALER AD](#)[COMPARE](#)[DETAILS](#)

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 24 Dec 2018

ASSESSMENT FOR REPAIR: B.M.W. R1200GS - FBJ9706L

Chassis No.: WB10A010XFZ154342

Engine No.: 122EN38140268

Qty

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

1 pc

Description*FRONT FENDER*

Front left signal

Front right signal

Front socket plug

Right hand guard

Handle bar

Right view mirror

Right side cover

Right side cover emblem BMW

Right crash bar

Right engine cover

Right engine cover gasket

Rear fender

Rear splash guard

Rear box rack

Subframe assy

Exhaust assy

Less discount 10%

Special nett items

1 pc

Rear number plate

1 pc

Rear rim

1)

Towing charges

2)

Replace, realign and adjust above damaged parts, check wiring and lighting system

3)

To replace and balance front and rear wheel rim

4)

To knock, straighten chassis & body balancing

5)

To remove/refit, replace (if damage) check and straighten front fork tubes.

6)

Spray painting

Total Estimate**Estimate**

\$600

\$195.00

\$195.00

\$214.00

\$305.00

\$355.00

\$214.00

\$580.00

\$105.00

\$550.00

\$550.00

\$145.00

\$495.00

\$480.00

\$780.00

\$1,350.00

\$1,880.00

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

\$839.30

\$7,553.70

Note: The above estimate is subjected to the prevailing GST of 7%

02

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 7 Jan 2019

ASSESSMENT FOR REPAIR: B.M.W. R1200GS - FBJ9706L

Chassis No.: WB10A010XFZ154342

Engine No.: 122EN38140268

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front brake pump assy	\$785.00
		<hr/>
		\$785.00
	Less discount 10%	\$78.50
		<hr/>
		\$706.50
	<u>Special nett items</u>	
4 pcs	Engine oil @ \$30.00	\$120.00
1)	Additional Labour for above work	X \$300.00
	Total Estimate	<hr/> <hr/>
		\$1,126.50

LEVER SCR.
 Need to make change
 p change whole
 pump

/NEC.

USD. 100

Note: The above estimate is subjected to the prevailing GST of 7%

PARTS \$6,429
 LESS 10% \$5,786.10

S/NETT \$ 230

LABOUR \$ 500

TOTAL \$ 6516.10

LESS LIS 20% \$ 1522.88

LIS TOTAL \$ \$5200.00 / 3 DAYS



[Signature]

For Bike Production Pte Ltd

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

31 Dec 2018

DISMANTLE MARKING
ASSESSMENT FOR REPAIR: B.M.W. R1200GS - FBJ9706L

Chassis No.: WB10A010XFZ154342

Engine No.: 122EN38140268

07

NA2 46K

28/12/18 1730

L15

3 Days

check item photos
After repair photos

QTY
1 PC

Description

FRONT FENDER

Front left signal

Front right signal

• Front socket plug

Right hand guard

• Handle bar

Right view mirror

Right side cover

Right side cover emblem BMW

Right crash bar

• Right engine cover

• Right engine cover gasket

• Rear fender

Rear splash guard

Rear box rack

Subframe assy

• Exhaust assy

Less discount 10%

Special nett items

Rear number plate

Rear rim

• Towing charges

• Replace, realign and adjust above damaged parts, check wiring and lighting system

To replace and balance front and rear wheel rim

To knock, straighten chassis & body balancing

To remove/refit, replace (if damage) check and straighten front fork tubes.

Spray painting

Total Estimate

Estimate

7.50 / SCR

\$195.00 XNL

\$195.00 / SCR

\$214.00 XNL - Mis

\$305.00 / SCR

\$355.00 XNL ? / BT

\$214.00 / SCR

\$580.00 / SCR

\$105.00 / NEC

\$550.00 / SCR

\$550.00 XSVL / SCR

\$145.00 XNN / NEC

\$495.00 XSVL ? / SCR

\$480.00 / DEF

\$780.00 / SCR

\$1,350.00 XNN

\$1,880.00 ? only exhaust
muffler cover
damaged - BT.

\$8,393.00

\$839.30

\$7,553.70

\$30 \$45.00 / DD

\$1,450.00 XR

? \$60

\$200.00 ? provide receipt

\$1,200.00 \$200 ?

\$200.00 XNN

\$480.00 XNN

\$400.00 XNN

\$400.00 \$150

\$11,628.70

Note: The above estimate is subjected to the prevailing GST of 7%

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Dec 2018		28 Dec 2018 16:52 Edit Adj Rpt	S\$5,200.00 Edit Estimates	S\$5,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	TEO CHOON MING , ID: S7618470D, Tel: +6597777731, Email: thomasteocm@yahoo.com								
Vehicle Reg. No.:	FBJ9706L	Date of Loss:	23/12/2018 14:00 - :59 [47 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 1315076355SG	Policy/Cover Note No.:	2100446860-01000 (Comprehensive)						
		Excess:	S\$1,300.00						
Repairer:	Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 09/01/2019]								
Driver/Custodian:	TEO CHOON MING (42 / Male) , NRIC: S7618470D, Tel: +6597777731 Email: thomasteocm@yahoo.com								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (15/01/2019): FBJ9706L / OD / 23/12/2018 / Coverage & Excess update AIG_SG (02/01/2019): FBJ9706L / OD / 23/12/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS			View All	Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ9706L (1315076355SG)





















OD

Dec 23 2018 2:30PM

[TEO CHOON MING]

Bike Production Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
2	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
3	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
4	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
5	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
6	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
7	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
8	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
9	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
10	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
11	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
12	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
13	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
14	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
15	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
16	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
17	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
18	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
19	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
20	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
21	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
22	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
23	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
24	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
25	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
26	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
27	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
28	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
29	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
30	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
31	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
32	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
33	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
34	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
35	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	
36	31/12/18 10:05	General View										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	08/01/19 15:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/12/18 12:24	ESTIMATE	 Load PDF	

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/12/18 13:20	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	24/12/18 13:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	24/12/18 13:13	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG18023281/NQD3S2

Date: 02/05/2019

REFERENCE

Insured/Claimant: TEO CHOON MING Policy No: 2100446860-01000
Date of Loss: 23/12/2018 Nature of Claim: OD Claim No: 1315076355SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ9706L**
Make & Model: BMW R1200 GSA, 1.2 Engine No: 122EN38140268
Reg. Date: 20/01/2015 (Man. Year: 2014) Chassis No: WB10A010XFZ154342
Colour: Blue Odometer: 31184 km
Engine Capacity: 1170 cc
Market Value/New Car Price: S\$28,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70R19 Rear Tyre Size: 170/60R17
Front Left Side: Metzeler 6 mm Rear Left Side: Metzeler 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,550.20	5,936.10	4,614.10	43.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	580.00	2,300.00	79.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,430.20	6,516.10	6,914.10	51.48
Approved Total (Overridden) (S\$)		5,200.00		
- Excess (S\$)	1,300.00	1,300.00	0.00	0.00
(S\$)	12,130.20	3,900.00	8,230.20	67.85
+ GST 7.00/7.00% (S\$)	849.11	273.00	576.11	67.85
Nett Amount (S\$)	12,979.31	4,173.00	8,806.31	67.85

INSPECTION

Date of Assignment: 28/12/2018

Date Inspected: 28/12/2018

Inspected At:

Bike Production Pte Ltd (HQ)
610 SERANGOON ROAD
Singapore 218216

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Scratched	750.00 FL	*600.00 FL
2	1		*FRONT LEFT SIGNAL	Not Necessary	195.00 FL	*- FL
3	1		*FRONT RIGHT SIGNAL	Scratched	195.00 FL	*195.00 FL
4	1		*FRONT SOCKET PLUG	Serviceable	214.00 FL	*- FL
5	1		*RIGHT HAND GUARD	Scratched	305.00 FL	*200.00 FL
6	1		*HANDLE BAR	Bent	355.00 FL	*355.00 FL
7	1		*RIGHT VIEW MIRROR	Scratched	214.00 FL	*214.00 FL
8	1		*RIGHT SIDE COVER	Scratched	580.00 FL	*450.00 FL
9	1		*RIGHT SIDE COVER EMBLEM BMW	Necessary	105.00 FL	*105.00 FL
10	1		*RIGHT CRASH BAR	Scratched	550.00 FL	*400.00 FL
11	1		*RIGHT ENGINE COVER	Serviceable	550.00 FL	*- FL
12	1		*RIGHT ENGINE COVER GASKET	Not Necessary	145.00 FL	*- FL
13	1		*REAR FENDER	Scratched	495.00 FL	*495.00 FL
14	1		*REAR SPLASH GUARD	Deformed	480.00 FL	*350.00 FL
15	1		*REAR BOX RACK	Scratched	780.00 FL	*780.00 FL
16	1		*SUBFRAME ASSY	Not Necessary	1,350.00 FL	*- FL
17	1		*EXHAUST ASSY	Bent	1,880.00 FL	*1,500.00 FL
18	1		*REAR NUMBER PLATE	Dented	45.00 FS	*30.00 FS
19	1		*REAR RIM	Repair	1,450.00 FS	*- FS
20	1		*FRONT BRAKE PUMP ASSY	Lever Scratched	785.00 FL	*785.00 FL
21	4		*ENGINE OIL	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,543.00	6,579.00
- List Item Discount on L Items 10.00/10.00% (S\$)	992.80	642.90
Total Parts (S\$)	10,550.20	5,936.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES.	New	200.00	80.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM.	New	1,200.00	350.00
3	TO REPLACE AND BALANCE FRONT AND REAR WHEEL RIM.	New	200.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.	New	480.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.	New	100.00	0.00
6	SPRAY PAINTING.	New	400.00	150.00
7	ADDITIONAL LABOUR FOR ABOVE WORK.	New	300.00	0.00
Gross Labour Cost (\$\$)			2,880.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >