

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1463/2018/GW
Date : 28-Dec-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chai Chee Meng
Address : 83 Anchorvale Crescent
Singapore 544626
Telephone : HP +65 98157571
Type of Claim : Own Damage Claims
Policy No. : 1800044000
Vehicle No : **SJA 4008 D**
Model Code : Audi A6 1.8 TFSI S-Tronic
Model / Year : Apr-18
Engine No : CYG 025662
Chassis No : WAUZZZ4GXJN074418
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Dec-18
Place of Accident : Along Buangkok East Drive

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJA 4008 D

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper, rhs front fender, rhs headlight and rhs wing mirror assy. To repair rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 3,150.00 1250.
3	To respray front bumper, rhs front fender, rhs front door and rhs wing mirror cover.	\$ 3,000.00 1800 550 x 3 = 1650 Mirror Cover = 150. 1800
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓
5	To reinstall front right door glass solar film	S/N \$ 400.00 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>7,502.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SJA 4008 D**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repairs</i>	\$ 2,650.00	X
2	FRONT BUMPER FIXING PARTS	\$ 464.00	X
3	FRONT BUMPER ADAPTER-RH	\$ 32.00	X
4	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 496.00	X
5	FRONT BUMPER WHEEL SPOILER-RH	\$ 232.00	X
6	FRONT BUMPER COVER CAP-LH/RH	2 \$ 98.00	X
7	FRONT BUMPER GUIDE PIECE-RH	\$ 32.00	X
8	FRONT BUMPER COVER -RH	\$ 44.00	X
9	FRONT FENDER-RH <i>Distorted.</i>	\$ 1,220.00	✓
10	FRONT FENDER ATTACHMENT PARTS-RH	\$ 88.00	?
11	FRONT FENDER STONE CHIP GUARD-RH	\$ 105.00	✓
12	FRONT FENDER BRACE-RH	\$ 72.00	✓
13	FRONT WHEEL HOUSING LINER-RH	\$ 246.00	X
14	FRONT WHEEL HOUSING LINER ATTACHMEN PARTS-RH	\$ 62.00	X
15	FRONT WHEEL HOUSING LINER STONE CHIP GUARD-RH	\$ 63.00	X
16	FRONT WHEEL HOUSING LINER BRACKET TRIM-RH	\$ 14.00	X
17	HEADLIGHT MOUNTING-RH	\$ 103.00	X
18	LED HEADLIGHT	\$ 8,386.00	X
19	FRONT SIDE MIRROR MOUNTING-RH	\$ 1,237.00	✓
20	FRONT SIDE MIRROR HOUSING-RH	\$ 185.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 15,829.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJA 4008 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT SIDE MIRROR TURN SIGNAL INDICATOR-RH <i>2nd</i>	\$ 111.00	✓
22	FRONT SIDE MIRROR GLASS-RH <i>2nd.</i>	\$ 1,506.00	✓
23	FRONT COVER TRIM-RH <i>?</i>	\$ 311.00	?
24	MOLDING ROOF-RH <i>new</i>	\$ 440.00	x
25	WINDOW SLOT SEAL WITH TRIM STRIP-RH <i>new</i>	\$ 294.00	x
26	FRONT DOOR WINDOW-RH <i>let</i>	\$ 1,018.00	✓
27	FRONT ALUMINIUM-RH <i>let</i>	\$ 726.00	✓
28	RUBBER VALVE <i>new</i>	4 \$ 12.00	x
29	SUNDRIES <i>?</i>	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		\$ 20,747.00	
TOTAL LABOUR CHARGES		\$ 7,502.00	
GRAND TOTAL		\$ 28,249.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *28/12/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 06 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant