

Finalization

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR EY1028Z

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623 64616555

Vehicle & Document Information

WIP No 29722

Reg No/Reg Date EY1028Z / 03/08/2015

Date In/Mileage 34/12/2018/ 51582 WDD1760422J389991 Chassis No

Engine No 27091030718497

Make/Model MB/A 180 (W176) "URBAN"

Colour/Trim 021 191 Cosmos Blac/ 043 361 ARTICO Laro

Account No Terms Date/Time Printed CSE Operator WT009122 Credit 21/01/2019/ 19:17 ΥK 395 / Yik Chan Hoe

| Description of Goods / Services Qty | Unit Price Disc% Amount |
|---|-------------------------|
| Z REQUEST Customer Request | RASIMVOICE |
| DRIVE IN/EXCESS : 28/12/2018 // TP VEH NO XE2448T SOMPO DATE IN/DATE SURVEY: 31/12/2018 // RASUL LKK BY/AUTHRIZED ON : DIRECT SETTLEMENT // SHAWN SOMPO | Working Days |
| S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD | 60.00 |
| A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH. | 4800.00 |
| A BPIRES RESPRAY REAR BUMPER, RIGHT REAR FENDER, RIGHT REAR DOOR | 2400.00 |
| AND REAR END PANEL A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO | 0.10 380.00 |
| STANDARD SETTINGS. A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT | 120.00 |
| A BPILAB REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS | 960.00 |
| AND SEATS FOR NEC. REPAIRS. A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT | 480.00 |
| A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT | 540.00 |
| X REAR BUMPER 1.00 | 1300.73 00.00 1300.73 |

Confirmed & accepted by

RIGHT REAR FENDER

RIGHT REAR ALLOY WHEEL

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

696.89 00.00

2184.03 00.00

1.00

1.00

696.89

2184.03



Finalization

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

WIP No

ESTIMATE FOR EY1028Z

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

29722

EY1028Z / 03/08/2015

34/12/2018/ 51582

WDD1760422J389991

27091030718497

1.00

1.00

1 00

MB/A 180 (W176) "URBAN"

021 191 Cosmos Blac/ 043 361 ARTICO Laro

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623

64616555

| Account No | Terms | Date/Time Printed | ı cs | E Operator | | |
|------------|-------------------------------------|-------------------|-----------------|--------------------|--|---|
| WT009122 | Credit | 21/01/2019/ 19 | 9:17 YK | 395 / Yik Chan Hoe | <u>angula a sa </u> | Strategy of the second |
| | | Description o | of Goods / Serv | ices | Qty Unit Price | Disc% Amount |
| X RIGHT RE | EAR FENDER AR DOOR AR DOOR WE | ATHERSTRIP | AN | OFFICIAL | 1.00 128.68 1.00 1643.66 | 3 00.00 00.00 1643. 290. |

RIGHT REAR DOOR HANDLE Χ TS TWO-COMPONENT ADHESIVE TWO-COMPONENT ADHESIVE

RIGHT REAR DOOR INSULATION

SEAM SEAL χ BLIND RIVET WITH PAN HEAD Χ RIVET

MOLDING CLIP Χ

RIVET

| 1.00 | /OT - / O | 00.00 |
|----------|-----------|-------|
| 1.00 | 102.64 | 00.00 |
| 1.00 | 101.12 | 00.00 |
| \10.00\\ | 2.35 | 00.00 |
| 5.00 | 2.35 | 00.00 |
| L.00 | 6.07 | 00.00 |
| 5.00 | 5.21 | 00.00 |
| | | |

63.93 00.00

137.42 00.00

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett

17.238.77

7% GST on 17238.77 1206.71

128.68 1643.66 290-54

63.93

137.42

781.76

102.64

101.12

23.50

11.75

6.07

26.05

Total Payable

18,445.48

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR EY1028Z

SUPPLEMENTARY

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623 64616555

Vehicle & Document Information WIP No

29722

EY1028Z

/ 03/08/2015

31/12/2018/ 51582

WDD1760422J389991

27091030718497

MB/A 180 (W176) "URBAN"

021 191 Cosmos Blac/ 043 361 ARTICO Laro

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|---------------------|--------------|-----------------------------|
| WT009122 | Credit | 21/01/2019/ 19:18 | YK | 395 / Yik Chan Hoe |
| | | Description of Good | s / Services | Oty Unit Price Disc% Amount |

| to a first the state of the sta | | III FIICE DISC/0 AIROURI |
|--|--------------------------|--|
| X TWO-COMPONENT ADHESIVE X SEAM SEAL X BLIND RIVET WITH PAN HEAD | AN OFFICAL 1.00 (1.00 A) | 102.64 00.00 102.64 101.12 00.00 101.12 2.35 00.00 23.50 |
| X RIVET | 5.00 | 2.35 00.00 11.75 |
| X MOLDING CLIP | 1.00 | 6.07 00.00 6.07 |
| X RIVET | 5.00 | 5.21 00.00 26.05 |

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett

271.13

7% GST on

18.98

Total Payable

271.13

290.11

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

