

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Tan Yu Zhong BLK 202A PUNGGOL FIELD #06-226 SINGAPORE 821202 Contact No Mobile: 98761104	Cust No/Name	/Tan Yu Zhong
	Reg No/Reg Date	SLD3666X / 15/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MG5602802
	Engine No	G4FGGH613136
	Make/Model	KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	28/12/2018/ 10:30	BLC	442 / CocoLu	41858			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1650 1800.00
RENEW FRT BUMPER, FRT FENDER LH, FRT SUPPORT PANEL								
REPAIR BONNET,X								
E PNT98000								840 1080.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER LH								
E PNT88000								? 100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								? 80.00
M SUNDRY								
TOP UP AIRCON GAS								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
A 90000001								20.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 90000001								120.00
CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM								
M SUNDRY								20.00
Sundry								? 300.00
A 90000001								
RENEW FRT UNDER CARRIAGE								
M COVER-FR BUMPER Torn					1.00	728.00	00.00	728.00
M GRILLE ASSY-RADIATOR					1.00	322.00	00.00	322.00
M MOULDING-FRONT BUMPER A/INTAKE at					1.00	80.00	00.00	80.00
M ABSORBER-FRONT BUMPER ENERGY CRA					1.00	97.00	00.00	97.00
M STIFFNER-FR BPR LWR					1.00	131.00	00.00	131.00
M RAIL ASSY-FR BUMPER 7H					1.00	410.00	00.00	410.00
M BRACKET-FR BUMPER SIDE MTG,LH CRA					1.00	12.00	00.00	12.00
M BRACKET-FR BUMPER UPR SIDE MTG CRA					1.00	26.00	00.00	26.00
M GRILLE-FRONT BUMPER SIDE,LH MIS					1.00	17.00	00.00	17.00
M LAMP ASSY-FRONT FOG,LH MIS					1.00	241.00	00.00	241.00
M CARRIER ASSY-FRONT END MODULE ?					1.00	776.00	00.00	776.00
M PANEL-FENDER,LH 7H					1.00	396.00	00.00	396.00
M BRACKET ASSY-FENDER & BPR MTG,Rec					1.00	14.00	00.00	14.00
M GUARD ASSY-FRONT WHEEL,LH MIS					1.00	109.00	00.00	109.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Tan Yu Zhong BLK 202A PUNGGOL FIELD #06-226 SINGAPORE 821202 Contact No Mobile: 98761104	Cust No/Name	/Tan Yu Zhong
	Reg No/Reg Date	SLD3666X / 15/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MG5602802
	Engine No	G4FGGH613136
	Make/Model	KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	28/12/2018/ 10:30	BLC	442 / CocoLu	41858

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY-HEAD, LH <i>5/10</i>	1.00	1870.00	00.00	1870.00
M HUB ASSY-FR WHEEL <i>?</i>	1.00	150.00	00.00	150.00
M DUCT ASSY-EXTENSION <i>?</i>	1.00	144.00	00.00	144.00
M DUCT-AIR "B" <i>?</i>	1.00	77.00	00.00	77.00



6 days
28/12/18 @ 1720
Rey 50 part

Confirm & accepted by

	Nett	9,210.00
7% GST on	9210.00	644.70
Total Payable		9,854.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.