

## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

Co Reg No : 199405410K

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info			
Tan Yu Zhong	Cust No/Name	/Tan Yu Zhong			
ταπ το Σπολία	Reg No/Reg Date	SLD3666X / 15/06/201			
BLK 202A PUNGGOL FIELD	Date In/Mileage	/ 0.			
#06-226 SINGAPORE 821202	Chassis No KNAFX411MG5602802				
	Engine No G4FGGH613136				
Contact No Mobile: 98761104	Make/Model KIA/FORTE K3 1.6 A EX BF4				
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK			

Account No Terms Date/Time Printed CSE Operate	or WIP No
CSM00081 Cash 28/12/2018/ 10:30 BLC 442 / 6	CocoLu 41858
Description of Goods / Services	Qty Unit Price Disc% Amount
E PNT88000	1800.00
RENEW FRT BUMPER, FRT FENDER LH, FRT SUPPORT PANEL	
REPAIR BONNET,	1050.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER LH	1050.00
E PNT88000	100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	
M SUNDRY	80.00
TOP UP AIRCON GAS	
B WHEELALIGNMENT	120.00
To Conduct Computerize Full Wheel Alignment	00.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM	
CHECK WIRING & ELECTRICAL SYSTEM	120.00
A 90000001  CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM	
M SUNDRY	20.00
Sundry	
A 90000001	300.00
RENEW FRT UNDER CARRIAGE	770 0
M COVER-FR BUMPER	1.00 728.00 00.00 728.00
M GRILLE ASSY-RADIATOR	1.00 322.00 00.00 322.00 1.00 80.00 00.00 80.00
M MOULDING-FRONT BUMPER A/INTAKE	1.00 97.00 00.00 97.00
M ABSORBER-FRONT BUMPER ENERGY M STIFFNER-FR BPR LWR	1.00 131.00 00.00 131.00
M RAIL ASSY-FR BUMPER	1.00 410.00 00.00 410.00
M BRACKET-ER BUMPER SIDE MTG, LH	1.00 12.00 00.00 12.00
M BRACKET-FR BUMPER UPR SIDE MTG	1.00 26.00 00.00 26.00
M GRILLE-FRONT BUMPER SIDE, LH	1.00 17.00 00.00 17.00
M LAMP ASSY-FRONT FOG.LH	1.00 241.00 00.00 241.0
M CARRIER ASSY-FRONT END MODULE	1.00 776.00 00.00 776.0
M PANEL-FENDER, LH	1.00 396.00 00.00 396.0 1.00 14.00 00.00 14.0
M BRACKET ASSY-FENDER & BPR MTG,	# 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
M GUARD ASSY-FRONT WHEEL, LH	1.00 109.00 00.00 109.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

Co Reg No : 199405410K

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info			
Tan Yu Zhong	Cust No/Name	/Tan Yu Zhong			
	Reg No/Reg Date	SLD3666X / 15/06/201			
BLK 202A PUNGGOL FIELD	Date In/Mileage	/ 0			
#06-226	Chassis No KNAFX411MG5602802				
SINGAPORE 821202	Engine No	G4FGGH613136			
Contact No Mobile: 98761104	Make/Mode1	KIA/FORTE K3 1.6 A EX BF4			
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK			

CSM00081 Cash		28/12/2018/ 10:30	BLC 442 /	/ CocoLu		41858				
		Description	of Goods	/ Services			Qty	Unit Price	Disc%	Amount
M LAMP AS	SY-HEAD,1	Н					1.00	1870.00	00.00	1870.00
	Y-FR WHE						1.00	150.00	00.00	150.00
	SY-EXTENS						1.00	144.00	00.00	144.00
M DUCT-AI	•	,					1.00	77.00	00.00	77.00



Confirm & accepted by

Nett 7% GST on 9210.00

9,210.00

644.70

Total Payable

9,854.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.