



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 28.12.2018

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

RE: ESTIMATE COST OF REPAIR TO SHD2483K TOYOTA PRIUS 1.8L

To Supply

1) 1pc	rear bumper	\$ <i>de</i> 1,324.50
2) 1set	rear bumper clip	\$ <i>ue</i> 30.00
3) 1pc	rear bumper right side retainer	\$ <i>ue</i> 112.70
4) 1pc	right rear bumper extension filler	\$ <i>Rx</i> 112.81

Sub total parts	\$ 1,580.01
Less: 25% discount	\$ (395.01)
	\$ 1,185.00

L/charges

1) To remove rear bumper, right bumper extension filler, replace the above part \$ *200* 200.00
align rear bumper

2) To putty & respray painting rear bumper & bumper extension filler \$ *250* 250.00

Sub L/charges	\$ 450.00
Estimated total	\$ 1,635.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jia 9749547
wp
Resurvey after repair
02 days
sure (LKK auto-wm)