

WATPAH

Marcus

REF:

III

ASSIGNMENT

From

Date 02/01/2019

Estimated Cost

OD / TP / VS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No.

GBE 3543E

at Workshop n/s

Yew Tee Automobile

of

Blk 6 Woodlands Rd 399F

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

3 days Res. Yes or No

Lump Sum

% 3 Val. Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle IN / OUT

Date

Person Contacted

Veh No

GBE3543E

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make

Nissan NV200 c.c. 1597

Colour

B/gc Insured / Std / NI / NA

Sp. Reading

158627 T/Ratio: Insured / Std / NI / NA

Eng/No

C/No

VM 20082765

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6 mm

R/Bal

6 mm

L/Bal

6 mm

L/Bal

6 mm

D.O.A

24/1/18

D.O.A

24/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 13303

No Amok

P/P \$ 1326.32 (incl) \$ 300.78 / 737.1

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ + RS. \$

1) Photos

1) Others

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|------|----------------------------|---|
| INDIA INTERNATIONAL INSURANCE PL | | | Ref : CC4/III18023331/Upp3 | |
| 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 | | | Date : 31-12-2018 |  |
| | | | Code : III2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHD 7121Y | | Veh. Inspected | GBE 3543E |
| Policy No. | | | Coverage (\$) | 0.00 |
| Claim No. | | | Excess (\$) | 0.00 |
| Assign From | | | Assign Date | 31/12/2018 |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | | c.c | 0 |
| Engine No. | HIDDEN | | Year of Reg. | |
| Chassis No. | | | Colour | |
| Odometer | - | | Steering | |
| Brakes | | | Modification | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 24/12/2018 | | Inspection Date | 02/01/2019 |
| Survey held at | YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD

| PARTICULARS OF CLAIM | | | |
|------------------------------|---|------------------------------|------------------------------|
| Claim Type: | TP | Ref. No: | YTKB/TP/1812/011 |
| Policy No: | 5094821249-01 | Date of Loss: | 24/12/2018 |
| Vehicle Reg. No.: | GBE3543E | Driveable? | no |
| Driver Age: | | Third Party Vehicle No.: | SHD7121Y |
| Any Injuries? | no | Contact No: | |
| Insured/Claimant: | HOPE TECHNIK PTE LTD | Driver: | MUHAMMAD NURAZLI BIN JUMA EN |
| <hr/> | | | |
| Make/Model: | Nissan, NV200 - VSKYBAM20U | Vehicle Reg. Date: | 02 Nov 2015 |
| Vehicle Colour: | BLACK | Engine Number: | HR16039239D |
| Chassis No: | VM20082765 | Odometer: | |
| Total Loss? | NO | Est. Duration of Repair(Day) | |
| <hr/> | | | |
| Description of Accident/loss | COLLISION - HEAD TO REAR | | |
| Remarks: | | | |
| Present Location: | Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ | | |

| COST OF CLAIMS | | Amount |
|--------------------------|--|-----------------|
| Parts | | 3,677.15 |
| Miscellaneous Items | | 60.00 |
| Labour | | 610.00 |
| Paintwork Labour | | 840.00 |
| Towing | | 0.00 |
| Gross Total(S\$): | | 5,187.15 |
| GST 7.00%(S\$): | | 363.10 |
| Nett Amount(S\$): | | 5,550.25 |

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|---------------------------|------|----------|--------|------------|
| 1 | 1 | REAR BUMPER | 0.00 | 650.40 | -30.00 | 455.28 |
| 2 | 1 | REAR TAILLAMP RH | 0.00 | 258.70 | -30.00 | 232.83 |
| 3 | 1 | REAR FENDER RH | 0.00 | 2,997.20 | -30.00 | 2,098.04 |
| 4 | 1 | REAR WHEEL HUB RH | 0.00 | 380.00 | -30.00 | 342.00 |
| 5 | 1 | REAR WHEEL HUB BEARING RH | 0.00 | 240.00 | -30.00 | 216.00 |
| 6 | 1 | REAR SHOCK ABSORBER RH | 0.00 | 370.00 | -30.00 | 333.00 |

Total Parts (\$\$) 3,677.15

Estimates of Miscellaneous Items

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|-------------------------|------|--------|-------|------------|
| 1 | 1 | REAR WHEEL HUB COVER RH | 0.00 | 60.00 | 0.00 | 60.00 |

Sub Total (\$\$) 60.00

Estimates On Labour

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|---|--------|--------|-------|------------|
| 1 | 1 | To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts. | 30.00 | 30.00 | 0.00 | 30.00 |
| 2 | 1 | To Conduct Computer Wheel Alignment. | 80.00 | 80.00 | 0.00 | 80.00 |
| 3 | 1 | To Dismantle and Refit Rear Undercarriage. | 220.00 | 220.00 | 0.00 | 220.00 |
| 4 | 1 | To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools. | 280.00 | 280.00 | 0.00 | 280.00 |

Gross Labour Cost (\$\$) 610.00

Estimates On Paint Work Labour

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|--|--------|--------|-------|------------|
| 1 | 1 | To Carry-Out Body Cavity Preservation. | 40.00 | 40.00 | 0.00 | 40.00 |
| 2 | 1 | To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available. | 800.00 | 800.00 | 0.00 | 800.00 |

Gross Labour Cost (\$\$) 840.00

< END OF ESTIMATES >

Not Approved
 taken part. After repair
 2/12/19 37.

Let's Auto Care Inc. 1015 10th St
 Los Angeles, CA 90015
 Tel: (213) 481-1111
 Fax: (213) 481-1112
 Email: info@letsauto.com
 Website: www.letsauto.com

Approved by: [Signature]

Date: [Signature]

Date:

Print Sent Message

This mail is associated with :

***GBE3543E (MCT18120662)**
[SHD7121Y]

TP
HOPE TECHNIK PTE LTD
Dec 24 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Yew Tee Automobile Tech Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 13/06/2019 10:29 AM.
To aida@iii.com.sg
CC III_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <Submit wp Report> MCT18120662

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that third party claimant did not send in his vehicle for repair at Yew Tee Automobile Tech Pte Ltd. Third party repairer had closed the case.

In view of this, we will proceed to close file and submit wp report to your good office.

Thank you.

Hsiao Tong

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 28 December 2018 1:49 PM
To: 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: YT(HQ); Zuhaidah Samsuri
Subject: RE: Accident involving GBE3543E (NTUC) and SHD7121Y (INDIA) ON 24.12.2018
Attachments: GBE3543E_24122018.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GBE3543E and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

2:09pm @ 28/12/2018
peno@vinnie
VNI

From: YT(HQ) [mailto:info@yewteegroup.com]
Sent: 28 December, 2018 11:31 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: YT(HQ) <info@yewteegroup.com>
Subject: RE: Accident involving GBE3543E (NTUC) and SHD7121Y (INDIA) ON 24.12.2018

Hi Garbriel,

We would like to choose LKK Auto Consultants Pte Ltd to conduct the pre-repair survey.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID: 62562081

Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Friday, 28 December, 2018 11:27 AM

To: YT(HQ)

Subject: RE: Accident involving GBE3543E (NTUC) and SHD7121Y (INDIA) ON 24.12.2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: YT(HQ) [<mailto:info@yewteegroup.com>]
Sent: 28 December, 2018 10:54 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: YT(HQ) <info@yewteegroup.com>
Subject: Accident involving GBE3543E (NTUC) and SHD7121Y (INDIA) ON 24.12.2018

Hi Motor Claim Department,

Attached the report for your kind perusal.

Kindly assist arrange survey before repair at Yew Tee HQ.

Please let us have the surveyor list to choose and the officer-in-charge too.

Thank you

Best Regards

Vinnie Lim




Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,

#01-12 Mega@Woodlands
Singapore 737856
DID:62562081
Email: info@yewteegroup.com



Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 31 Dec 2018 Edit Reg | | 28 Dec 2018 00:00 Edit Adj Rpt | S\$1,376.37 Edit Estimates | S\$1,376.37 View Rpt | | Pending for Survey Report Cancel Case |




| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: - | | | | | | | | |
| Main Claimant: | HOPE TECHNIK PTE LTD, Co. Reg. No.: 200606254N | | | | | | | | |
| Vehicle Reg. No.: | GBE3543E | Date of Loss: | 24/12/2018 08:00 - :59 [37 Months and 22 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / MCT18120662 | Policy/Cover Note No.: | MCOM0015 | | | | | | |
| Vehicle Reg. No. (Insured): | SHD7121Y | Policy No. (Claimant): | 5094821249-01 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F., Yew Tee Ind Estate, 678006 Woodlands - Tel: 67622081 | | | | | | | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070] | | | | | | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/01/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> III_SG (21/01/2019): Alert - Adj Mandate Approved (S\$0.00) - GBE3543E - Claim Handler: Zuhaidah Bte S... III_SG (09/01/2019): Alert - Adj Mandate Maintained - GBE3543E - Claim Handler: Zuhaidah Bte Samsuri | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |































Claim Documents

*GBE3543E (MCT18120662)
[SHD7121Y]
TP
HOPE TECHNIK PTE LTD
Dec 24 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Yew Tee Automobile Tech Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|-------|----------------|--|--|-------------------------------------|
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 09/01/19 12:32 | Video - Accident(OID) |  Load MP4 | <input type="checkbox"/> |
| 2 | 09/01/19 12:32 | Video - Accident(TP-front) |  Load MP4 | <input type="checkbox"/> |
| 3 | 09/01/19 12:32 | Video - Accident(TP-rear) |  Load MP4 | <input type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 08/01/19 11:59 | Chassis Number |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 08/01/19 11:59 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 08/01/19 11:59 | General View |  Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|--|--|------------|-------------------------------------|
| | | | | |

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|-------|-----------------|--|------------|-------------------------------------|
| No | Finalized On | India International Insurance Pte Ltd (HQ) | | Thumbnail Print |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail Print |
| 1 | 31/12/18 11:48 | EMAIL FROM III DD 28122018. | | Load PDF |
| 2 | 31/12/18 11:48 | TP GIA REPORT | | Load PDF |
| 3 | 04/01/19 09:24 | TP ESTIMATE- MARKED | | Load PDF |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | | Thumbnail Print |
| 1 | 02/01/19 08:49 | Singapore Accident Statement | | Load PDF |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18023331/UPB3Q2

Date: 24/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: GBE3543E

Insured Vehicle No: SHD7121Y

Date of Loss: 24/12/2018

Nature of Claim:

TP

Claim No: MCT18120662

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE3543E

Make & Model: NISSAN NV200, 1.5 (A)

Engine No: HR16039239D

Reg. Date: 02/11/2015 (Man. Year: 2015)

Chassis No: VM20082765

Colour: Black

Odometer: 158627 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 3,487.41 | 696.37 | 2,791.04 | 80.03 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,450.00 | 680.00 | 770.00 | 53.10 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 4,937.41 | 1,376.37 | 3,561.04 | 72.12 |
| + GST 7.00/7.00% (S\$) | 345.62 | 96.35 | 249.27 | 72.12 |
| Nett Amount (S\$) | 5,283.03 | 1,472.72 | 3,810.31 | 72.12 |

INSPECTION

Date of Assignment: 28/12/2018

Date Inspected: 02/01/2019 Inspected At:

Yew Tee Automobile Tech Pte Ltd (HQ)
Blk 6 Woodlands Road 399F., Yew Tee
Ind Estate
Singapore 678006

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | (Last Synchronised: 23 Jun 2019) | |
| Parts: | N/A | NISSAN NV200 1.5 (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBE3543E) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|---------------|---|-----------------|
| 1 | 1 | | *REAR BUMPER | Grazed | 650.40 FL | *650.40 FL |
| 2 | 1 | | *REAR FENDER RH | Repair | 2,997.20 FL | *- FL |
| 3 | 1 | | *REAR TAILLAMP RH | Grazed | 258.70 FL | *258.70 FL |
| 4 | 1 | | *REAR WHEEL HUB RH | Not Necessary | 380.00 FL | *- FL |
| 5 | 1 | | *REAR WHEEL HUB BEARING RH | Not Necessary | 240.00 FL | *- FL |
| 6 | 1 | | *REAR SHOCK ABSORBER RH | Not Necessary | 370.00 FL | *- FL |
| 7 | 1 | | *REAR WHEEL HUB COVER RH | Cut | 60.00 FS | *60.00 FS |
| | | | | | Sub Total (S\$) | 4,956.30 |
| | | | | | - List Item Discount on L Items 30.00/30.00% (S\$) | 1,468.89 |
| | | | | | Total Parts (S\$) | 3,487.41 |
| | | | | | | 696.37 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | TO DISCONNECT AND RECONNECT CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS | New | 30.00 | 20.00 |
| 2 | TO CONDUCT COMPUTER WHEEL ALIGNMENT | New | 80.00 | 60.00 |
| 3 | TO DISMANTLE AND REFIT REAR UNDERCARRIAGE | New | 220.00 | 0.00 |
| 4 | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIG AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS | New | 280.00 | 200.00 |
| 5 | TO CARRY OUT BODY CAVITY PRESERVATION | New | 40.00 | 0.00 |
| 6 | TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE | New | 800.00 | 400.00 |
| Gross Labour Cost (\$\$) | | | 1,450.00 | 680.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >